

Susana Martinez

Governor

John H. Bemis Cabinet Secretary-Designate

Brett F. Woods, Ph.D. **Acting Cabinet Secretary**

Jami Bailey Division Director **Oil Conservation Division**



Response Required - Deadline Enclosed

Underground Injection Control Program "Protecting Our Underground Sources of Drinking Water" Mailed: 9/16/2011

September 13, 2011

STEPHENS & JOHNSON OP CO

PO BOX 2249

WICHITA FALLS TX 76307

30-015-02231

LETTER OF VIOLATION and SHUT-IN DIRECTIVE Failed Mechanical Integrity Test

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

EAST MILLMAN POOL UNIT No.004

30-015-02231-00-00 L-13-19S-28E

Active Injection - (All Types)

8/23/2011 Test Date: 5-year Test Test Reason:

Permitted Injection PSI:

Actual PSI:

Std. Annulus Pres. Test Test Type:

Test Result:

Repair Due: 11/26/2011

FAIL TYPE: Other Internal Failure Pressured up and fluid came out of surface valve. Comments on MIT:

EAST MILLMAN UNIT No.145

Active Injection - (All Types)

30-015-02247-00-00

M-14-19S-28E

8/23/2011 Test Date:

Permitted Injection PSI:

Actual PSI:

FAIL CAUSE:

680 11/26/2011

Test Reason: Test Type:

5-year Test

Test Result:

Repair Due:

Std. Annulus Pres. Test

FAIL TYPE: Other Internal Failure

FAIL CAUSE:

Comments on MIT: Well would not pressure-up

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

RICHARD /NGE Artesia OCD District Office