<u>District I</u> 1625 N French Dr , Hobbs, NM 88240 District II
1301 W Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back side of form

Release Notification and Corrective Action

nMLB1125249455						OPER	ATOR		XX I	nitial Report	Final Report	
Name of Company Oxy Permian LTD /6696						Contact Du	isty Wilson					
Address 1017 W. Stanolind Rd						Telephone No. (575) 397-8247						
Facility Nar	ne Federa			Facility Type Production								
Surface Owner BLM Mineral Owner						BLM Lease No 30-015-27266						
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	North/	South Line	Feet from the	East/V	Vest Line	County		
М	29	23s	31e							['] Eddy		
LatitudeLongitude												
NATURE OF RELEASE												
Type of Release							Volume of Release Volume Record 60 bbls 20 bbls					
Oil Source of Release										Date and Hour of Discovery		
Hole in tank				07/30/2011 07/30/2011								
Was Immediate Notice Given? XX Yes ☐ No Not Required							If YES, To Whom? Mike Bratcher(NMOCD) Terry Gregston (BLM) via email					
By Whom? CJ Summers							Date and Hour 07/31/2011					
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse					
70 777				n/a CE 2011								
If a Watercourse was Impacted, Describe Fully.*												
N/A AUD ARTE												
By Whom? CJ Summers Date and Hour 07/31/2011 Was a Watercourse Reached? If YES, Volume Impacting the Watercourse n/a If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken * Hole developed in bottom area of tank due to corrosion and spilled out approximately 60 bbls of oil covering a area approximately 50' x 50' A Vac												
Describe Cause of Problem and Remedial Action Taken *												
Hole developed in bottom area of tank due to corrosion and spilled out approximately 60 bbls of oil covering a area approximately 50' x 50' A Vac Truck was dispatched to the area and recovered 20 bbls of free standing fluids Remediation efforts continue Will remediate to NMOCD guidelines												
Describe Area Affected and Cleanup Action Taken.*												
Remediate to NMOCD Guidelines												
I hereby certif	y that the ir	nformation gi	ven above	is true and comple	ete to th	e best of my	knowledge and ui	nderstan	d that pur	suant to NMOCE	rules and	
regulations all	operators a	are required to	report an	d/or file certain re e of a C-141 repor	lease no	tifications an	d perform correct	tive action	ons for rel	leases which may	endanger	
should their of	perations ha	ive failed to a	dequately	investigate and re	mediate	contamination	on that pose a thre	eport de eat to gre	ound wate	r. surface water.	human health	
or the environ	ment In ad	ldition, NMO	CD accept	tance of a C-141 re	eport do	es not relieve	the operator of r	esponsıl	ollity for c	compliance with a	ny other	
federal, state,	or local law	s and/or regu	lations.	-//			OII CONS	FPV	ATION	DIVISION		
4/1/						OIL CONSERVATION DIVISION						
Signature - M. Auf						Approved by District Supervisor						
Printed Name Dusty L Wilson							District Superviso	1				
Title HES Specialist A							Approval DEP 0 9 2011					
E-mail Addres	s dustv v	vilson@oxv c	om			onditions of	Approval.			_		
			,		Remediation per OCD Rules & Attached							
Date 08/24/2	2011 Additiona	one (575) 397-82		Guidelines, SUBMIT REMEDIATION								
Anach	ASGUIUOIIZ	n Sheets II I	vecessary	,	P	ROPOSAL	NOT LATER TH	IAN:		2RP	884	