Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires July 31, 2010

- 5	Lease Serial No
-	NMI C029435A
	NIVII I .UZ94.35A

SUNDRY N	DIICE2 AND RE	PURIS UN W	/ELLS
Do not use this	form for proposal	s to drill or to r	e-enter an
abandoned well.	Use form 3160-3	(APD) for such	proposals

6 If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on reverse side.					,	7 If Unit or CA/Agreement, Name and/or No		
1. Type of Well						8 Well Name and No.		
Oil Well Gas V	Vell 🛮 Oth	er INJECTION		•		J L KEEL A 6		
2 Name of Operator Contact: TERRY B CALLAHAN LINN OPERATING INCORPORATED E-Mail: tcallahan@linnenergy.com						9 API Well No. 30-015-05094-00-S1		
3a. Address 600 TRAVIS STREET SUITE 5100 HOUSTON, TX 77002 3b. Phone No. (include area code) Ph: 281-840-4272					·)	10 Field and Pool, or Exploratory GRAYBURG		
4. Location of Well (Foo	tage, Sec., T	., R, M, or Survey Description)				11. County or Parish, and State		
Sec 7 T17S R31E SESE 660FSL 660FEL						EDDY COUNTY,	NM	
12. CHE	CK APPF	ROPRIATE BOX(ES) TO I	INDICATE N	ATURE OF	NOTICE, RE	EPORT, OR OTHER	DATA	
TYPE OF SUBMISS	SION			TYPE OF ACTION				
Notice of Intent		□ Acidize	□ Deeper	1 ,		on (Start/Resume)	☐ Water Shut-Off	
	• •	☐ Alter Casing	☐ Fractur	e Treat	□ Reclama	ition	□ Well Integrity	
Subsequent Report	-	Casing Repair	□ New C	onstruction	□ Recomp	lete	□ Other	
Final Abandonment	t Notice	☐ Change Plans	□ Plug ar	nd Abandon	□ Tempora	arily Abandon		
		☐ Convert to Injection	□ Plug B	ack	☐ Water Disposal			
following completion of testing has been completed determined that the site is Work Completed to 7/26/11 - RUWSU, flowing, flowback to that it was 2 7/8 and 7/27/11 - Csg 1200 total of 86 jts tag @ bit sub, 6-2 7/8 Drill down to 2904' circula 7/28/11 - Bleed down	the involved ed. Final Abs ready for fi Return Wo NDWH, N tank. TOC I had ordous, flowba 2822, PBI collars, XO ate clean I n well con	ell to Injection: UBOP & Environmental par OH W/87 jts 2 3/8 IPC last 2 ered 2 3/8. Called TFH to de ock well. Spot in W/S. PU 4 FD @ 3482', 660' of fill. TOC O 80 jts. PU swivel & jt 81 d LD Pull up 30' SWI. tinue cleaning out, cleaned	ts in a multiple conly after all request, RU Floor & jts were plug eliver the right 3/4 bit & bit sOH W/86 jts Lirilled it down.	tongs release ged. Spot in Vit work string. ub start PU 2.D scrapper. F jt 82, jt 83 dri	ompletion in a rading reclamation SEPIEC IO NMOC PARTICIPATION PARTICIPA	new interval, a Form 3160- n, have been completed, ar	4 shall be filed once	
14. Thereby certify that the Name(Printed/Typed)	Com	Electronic Submission #117 For LINN OPERATIN mitted to AFMSS for process	NG INCORPOR sing by KURT	ATED, sent to SIMMONS on	the Carisbac	I IKMS2544SE)		
Name(1 timeur ypeu)	LIMID	VALLAHAN		HEGUL	ATOM SPE	OIALIOT III		
Signature (Electronic S	ubmission)	· D	ate 09/12/2	011			
		THIS SPACE FOR	FEDERAL	OR STATE	OFFICE US	SE		
Approved By ACC		ED	+-		WHITLOCK FROLEUM E	NGINEERING TECH	Date 09/19/2011	
	legal or equ	 Approval of this notice does no utable title to those rights in the su ect operations thereon 	ubject lease	Office Carlsba	d			

Additional data for EC transaction #117349 that would not fit on the form

32. Additional remarks, continued

Circulate hole clean getting back scale in returns. LD Swivel TOOH LD 100 jts 2 3/8 W/S, 6-2 7/8 drill collars & 3 7/8 bit. SWI ordered injection packer & tbg tester for the AM.

7/29/11 - Bleed down well, RU Tbg tester. PU 4 1/2 Arrow set 1 W/1.50 profile nipple, T2 on/off tool. TIH W/87 jts testing tbg to 5000 psi, had to change out 2 jts that had scale. RD floor & tongs, NDBOP, Land tbg. Circulate 55 Bbls packer fluid set packer @ 2756 land tbg NUWH. MOCK MIT 510 psi lost 40 in 30 min, good test. RDWSU move off line up acid for Monday morning.

8/1/11 - RU Crane Pump 4000 gal 15% HCl flush 60 Bbls H2O @ 2bpm @ 2100 psi. SWI

8/2/11 - RTI with passed MIT witnessed by Richard Inge.