		•	OCD Artes	-1-	
	UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT			FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007	
SUNDRY NOTICES AND REPORTS ON WELLS				5. Lease Serial No.	919
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.					ttee or Tribe Name
SUBMIT IN TRIPLICATE- Other instructions on reverse side.					Agreement, Name and/or No.
. Type of Well Oil Well Gas Well Other				8. Well Name and	
. Name of Operator OXY USA W	TP LP		192463	RoaringSprig 9. API Well No	ings 14 Federal #5
a Address P.O. Box 50250 Midland, TX 79710		3b. Phone No. (include area code) 432-685-5717		30-015-29362 10. Field and Pool, or Exploratory Area	
3 - 2275 FNL 245	OFEL SENE(H) 51 FWL SENW(F)) " "	u	11. County or Par Eddy	NU
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, R TYPE OF SUBMISSION TYPE OF ACTION					HER DATA
Notice of Intent Subsequent Report Final Abandonment Notice	Acidize Alter Casing Casing Repair Change Plans Convert to Injection	Deepen Fracture Treat New Construction	Production (Star Reclamation Recomplete Temporarily Aba Water Disposal		Water Shut-Off Well Integrity Other
Attach the Bond under which the following completion of the inv	ectionally or recomplete horizontally the work will be performed or proviously olved operations. If the operation and Abandonment Notices shall be by for final inspection.)	y, give subsurface locations a de the Bond No. on file with results in a multiple completi	and measured and true BLM/BIA. Require on or recompletion in	e vertical depths of a d subsequent reports a a new interval, a Fo	Il pertinent markers and zones. shall be filed within 30 days rm 3160-4 shall be filed once

Roaring Springs 14 Federal #5 - 30-015-28302

TD-10135'M 7635'V OH-7769-10135'

Accepted for record

DEC 06 2011

NMOCD ARTESIA

OXY USA WTP LP respectfully requests to temporarily abandon this well. It is currently being evaluated for possible future recompletion with the coil tubing-acid simulation. The pilot project is to begin in 12/11 and depending on the success of this project, this well would be a future candidate.

1. POOH w/ prod equipment, RIH & set CIBP @ +/-7719'


SEE ATTACHED FOR CONDITIONS OF APPROVAL

- 2. Notify BLM/NMOCD of casing integrity test 24hrs in advance.
- 3. RU pump truck, circulate well with treated water, pressure test casing to 500# for 30 min.

14. I hereby certify that the foregoing is true and correct Name (Printed/Typed)]				
David Stewart	Title Regulatory Advisor	e Regulatory Advisor			
Signature V. Signature	Date 11/22/1!				
THIS SPACE FOR FEDERAL	L OR STATE OFFICE USE				
/s/ JD Whitlock Jr	Title CPF7 Date 13	5/11			
Conditions of approval, if any, are attached. Approval of this notice does not warra certify that the applicant holds legal or equitable title to those rights in the subject lewhich would entitle the applicant to conduct operations thereon.	l l				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

OXY USA WTP LP
Roaring Spring 14 Federal #5
API No. 30-015-28302



CIBP @ +/-7719'

Whipstock @ 7778-7769' Perfs @ 7788-7944' - sqz w/ cmt

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Roaring Springs 14 Federal #5

- 1. Well may be approved to be TA/SI for a period of 12 months or until 12/01/2012 after successful MIT and subsequent report with well bore diagram is submitted.
- 2. This will be the only TA approval for this well.
- 3. Well must be returned to production or plans to P&A must be submitted by Dec. 1, 2012.
- 4. Notify BLM to witness setting of CIBP.