

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB No 1004-0137
Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS
**Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.**

SUBMIT IN TRIPLICATE – Other instructions on page 2

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other

2. Name of Operator
Mesquite SWD Inc.

3a. Address
P O Box 1479 Carlsbad NM 88221-1479

3b. Phone No. (include area code)
575-706-1840

4. Location of Well (Footage, Sec, T, R., M, or Survey Description)
Unit C Sec 22 T 24S R 28E
660 Fnl 1980EWL

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No
Willow Lake Com

9. API Well No.
30-015-21499

10. Field and Pool or Exploratory Area
SWD BonespringsSWD

11. Country or Parish, State
Eddy

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA



TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☒ Other <u>Change of operator</u>
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☐ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Bond # NMB000612 The undersign accepts all applicable terms, stipulations and restrictions concerning operations conducted on leased land or portion thereof, as described above.

Effective 1/05

NMB000612



**SUBJECT TO LIKE
APPROVAL BY BLM**

SEE ATTACHED FOR
CONDITIONS OF APPROVAL
Accepted for record
NMOC D

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)
Clay L Wilson

Title President

Signature

Date 11/13/2011

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

Conditions of Approval

**Mesquite SWD Inc.
Willow Lake Com. #1
NM020360
3001521499**

1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
2. All above ground structures and equipment on the lease shall be painted Shale Green (5Y 4/2). This is to be done within 90 days, if you have not already done so.
3. Submit for approval of water disposal method.
4. Submit updated facility diagrams as per Onshore Order #3
5. This agency shall be notified of any spill or discharge as required by NTL-3A.
6. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
7. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
8. Subject to like approval by NMOCD.
9. **Submit plan for approval of well operations within 30 days of this approval to change operator.**

43 CFR 3162.3-4 (C) requires that wells incapable of production in paying quantities be promptly plugged and abandoned....