_				
Submit I Copy To Appropriate District	State of New Me	xico	Form C-103	
Office District 1'- (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011 WELL API NO.	
1625 N French Dr , Hobbs, NM 88240 <u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION		30-015-22212	
811 S First St., Artesia, NM 88210 <u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE FEE	
1000 Rio Brazos Rd , Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NIVI 87303		6. State Oil & Gas Lease No.	
1220 S St Francis Dr , Santa Fe, NM 87505				
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name Anadarko Pardue Farms ANQ Com 8. Well Number		
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number		
2. Name of Operator		9. OGRID Number		
Yates Petroleum Corporation 3. Address of Operator			025575 10. Pool name or Wildcat	
105 South Fourth Street, Artesia, NM	1 88210		Indian Basin Upper Penn, Assoc.	
4. Well Location Unit Letter F: 2130 feet from the North line and 1980 feet from the West line				
Section 27	Section 27 Township 21S Range 24E NMPM Eddy County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
	3680		**************************************	
12. Check App	propriate Box to Indicate Nat	ture of Notice, I	Report or Other Data	
NOTICE OF INT		SUE REMEDIAL WOF	SSEQUENT REPORT OF: RK	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON ☐ CHANGE PLANS ☐	COMMENCE DR	RILLING OPNS. P AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	Notify OCD 24 hrs. prior	
DOWNHOLE COMMINGLE	•		The same of the prior	
			10 any work done	
OTHER:	tad aparations (Clearly state all s	OTHER:	lo any work done.	
13. Describe proposed or comple	work). SEE RULE 19.15.7.14 N	pertinent details, ar	nd give pertinent dates, including estimated le Completions: Attach wellbore diagram of	
13. Describe proposed or comple date of starting any proposed proposed completion or recon	work). SEE RULE 19.15.7.14 N npletion.	pertinent details, ar MAC. For Multip	io any work done.	
13. Describe proposed or comple date of starting any proposed proposed completion or recon Yates Petroleum Corporation plans to NOTE: Cap string and power cable in	work). SEE RULE 19.15.7.14 N npletion. plug and abandon this well as follow the hole, top of tubing at 5848'.	pertinent details, and MAC. For Multip	and give pertinent dates, including estimated le Completions: Attach wellbore diagram of	
13. Describe proposed or comple date of starting any proposed proposed completion or recon Yates Petroleum Corporation plans to NOTE: Cap string and power cable in 1. RIH with tubing open-ended to 54	work). SEE RULE 19.15.7.14 N npletion. plug and abandon this well as follow the hole, top of tubing at 5848'. 40' and spot a 200 sx Class "C" c	pertinent details, and MAC. For Multip	io any work done.	
13. Describe proposed or comple date of starting any proposed proposed completion or reconverse Petroleum Corporation plans to NOTE: Cap string and power cable in 1. RIH with tubing open ended to 54 plug, reset if necessary.	work). SEE RULE 19.15.7.14 N inpletion. plug and abandon this well as follow the hole, top of tubing at 5848'. 40' and spot a 200 sx Class "C" c Squz. of a 35 sx Class "C" cement plug for the spot a 25 sx Class "C" cement plug for the state of the spot a 25 sx Class "C" cement plug for the spot a 25 sx Class "C" cement pl	pertinent details, at MAC. For Multip lows: ement plug from 4	IO any work done. Indigive pertinent dates, including estimated le Completions: Attach wellbore diagram of additional across Glorieta ton.	
13. Describe proposed or comple date of starting any proposed proposed completion or reconverse Petroleum Corporation plans to NOTE: Cap string and power cable in 1. RIH with tubing open ended to 54 plug, reset if necessary. Packer 2. Load hole with plugging mud. Spot 3. Load hole with plugging mud. Spot 3. Load hole with plugging mud. Spot 3.	work). SEE RULE 19.15.7.14 N inpletion. plug and abandon this well as foll the hole, top of tubing at 5848'. 40' and spot a 200 sx Class "C" c Squz . of a 35 sx Class "C" cement plug for a 50 sx Class "C" cem	pertinent details, and MAC. For Multip lows: ement plug from 4 from 2324'-2524' afrom 1800'-2050' a	IO any work done. Ind give pertinent dates, including estimated le Completions: Attach wellbore diagram of a 340'-5440' in the 7" casing. WOC and tag	
13. Describe proposed or comple date of starting any proposed proposed completion or reconverse Petroleum Corporation plans to NOTE: Cap string and power cable in 1. RIH with tubing open ended to 54 plug, reset if necessary. Packer 2. Load hole with plugging mud. Spot 3. Load hole with plugging mud. Spot 3. Load hole with plugging mud. Spot 3.	work). SEE RULE 19.15.7.14 N inpletion. plug and abandon this well as foll the hole, top of tubing at 5848'. 40' and spot a 200 sx Class "C" c Squz . of a 35 sx Class "C" cement plug for a 50 sx Class "C" cem	pertinent details, and MAC. For Multip lows: ement plug from 4 from 2324'-2524' afrom 1800'-2050' a	Ind give pertinent dates, including estimated le Completions: Attach wellbore diagram of 340'-5440' in the 7" casing. WOC and tag across Glorieta top.	
13. Describe proposed or comple date of starting any proposed proposed completion or reconverse Petroleum Corporation plans to NOTE: Cap string and power cable in 1. RIH with tubing open ended to 54 plug, reset if necessary. Packer 2. Load hole with plugging mud. Spot 3. Load hole with plugging mud. Spot 4. Load hole with plugging mud. Spot and tag plug, reset if necessary.	work). SEE RULE 19.15.7.14 N inpletion. plug and abandon this well as foll the hole, top of tubing at 5848'. 40' and spot a 200 sx Class "C" c Squz . of a 35 sx Class "C" cement plug for a 50 sx Class "C" cem	pertinent details, ar MAC. For Multip lows: ement plug from 4 from 2324'-2524' a from 1800'-2050' a from 0-350' across	Ind give pertinent dates, including estimated le Completions: Attach wellbore diagram of 340'-5440' in the 7" casing. WOC and tag across Glorieta top. across intermediate casing shoe. Woc Tas surface casing shoe to the surface. WOC	
13. Describe proposed or comple date of starting any proposed proposed completion or reconverse Petroleum Corporation plans to NOTE: Cap string and power cable in 1. RIH with tubing open ended to 54 plug, reset if necessary. 2. Load hole with plugging mud. Spot 3. Load hole with plugging mud. Spot 4. Load hole with plugging mud. Spot and tag plug, reset if necessary.	work). SEE RULE 19.15.7.14 N impletion. plug and abandon this well as following at 5848'. 40' and spot a 200 sx Class "C" c Squz. of a 35 sx Class "C" cement plug for a 50 sx Class "C" cement plug for a 60 sx	pertinent details, ar MAC. For Multip lows: ement plug from 4 from 2324'-2524' a from 1800'-2050' a from 0-350' across	Ind give pertinent dates, including estimated le Completions: Attach wellbore diagram of 340'-5440' in the 7" casing. WOC and tag across Glorieta top.	
13. Describe proposed or completed date of starting any proposed proposed completion or reconverse Petroleum Corporation plans to NOTE: Cap string and power cable in 1. RIH with tubing open ended to 54 plug, reset if necessary. 2. Load hole with plugging mud. Spot 3. Load hole with plugging mud. Spot 4. Load hole with plugging mud. Spot and tag plug, reset if necessary. SEE ATTACHED CONDITIONS OF	work). SEE RULE 19.15.7.14 N impletion. plug and abandon this well as following at 5848'. 40' and spot a 200 sx Class "C" c Squz. of a 35 sx Class "C" cement plug for a 50 sx Class "C" cement plug for a 60 sx	pertinent details, at MAC. For Multip lows: ement plug from 4 from 2324'-2524' a from 1800'-2050' a from 0-350' across	Ind give pertinent dates, including estimated le Completions: Attach wellbore diagram of 340'-5440' in the 7" casing. WOC and tag across Glorieta top. across intermediate casing shoe. Woc Tas surface casing shoe to the surface. WOC	
13. Describe proposed or completed date of starting any proposed proposed completion or recompleted proposed completion or recompleted proposed completion or recompleted proposed completion or recompleted proposed completed proposed completed proposed pro	work). SEE RULE 19.15.7.14 N impletion. plug and abandon this well as follow the hole, top of tubing at 5848'. 40' and spot a 200 sx Class "C" capuz. of a 35 sx Class "C" cement plug for a 50 sx Class "C" cement plug for a 60 sx Class "C" ce	pertinent details, at MAC. For Multip lows: ement plug from 4 from 2324'-2524' afrom 1800'-2050' afrom 0-350' across	and give pertinent dates, including estimated le Completions: Attach wellbore diagram of 340'-5440' in the 7" casing. WOC and tag across Glorieta top. across intermediate casing shoe. WOC across intermediate casing shoe to the surface. WOC BECEIVED JAN 23 2012	
13. Describe proposed or completed date of starting any proposed proposed completion or reconverse Petroleum Corporation plans to NOTE: Cap string and power cable in 1. RIH with tubing open ended to 54 plug, reset if necessary. 2. Load hole with plugging mud. Spot 3. Load hole with plugging mud. Spot 4. Load hole with plugging mud. Spot and tag plug, reset if necessary. SEE ATTACHED CONDITIONS OF	work). SEE RULE 19.15.7.14 N impletion. plug and abandon this well as follow the hole, top of tubing at 5848'. 40' and spot a 200 sx Class "C" capuz. of a 35 sx Class "C" cement plug for a 50 sx Class "C" cement plug for a 60 sx Class "C" ce	pertinent details, at MAC. For Multip lows: ement plug from 4 from 2324'-2524' afrom 1800'-2050' afrom 0-350' across	and give pertinent dates, including estimated le Completions: Attach wellbore diagram of 340'-5440' in the 7" casing. WOC and tag across Glorieta top. across intermediate casing shoe. WOC across intermediate casing shoe to the surface. WOC BECEIVED JAN 23 2012	
13. Describe proposed or completed date of starting any proposed proposed completion or recompleted proposed completion or recompleted proposed completion or recompleted proposed completion or recompleted proposed completed plans to NOTE: Cap string and power cable in 1. RIH with tubing open ended to 54 plug, reset if necessary. 2. Load hole with plugging mud. Spot and tag plug, reset if necessary. SEE ATTACHED CONDITIONS OF APPROVAL I hereby certify that the information all SIGNATURE	work). SEE RULE 19.15.7.14 N impletion. plug and abandon this well as foll in the hole, top of tubing at 5848'. 40' and spot a 200 sx Class "C" c Squz. of a 35 sx Class "C" cement plug for a 50 sx Class "C" cement plug for a 60 sx Class "C" ce	pertinent details, at MAC. For Multip lows: ement plug from 4 from 2324'-2524' a from 1800'-2050' a from 0-350' across ets est of my knowled ulatory Complianc	Indigive pertinent dates, including estimated le Completions: Attach wellbore diagram of 340'-5440' in the 7" casing. WOC and tag across Glorieta top. across intermediate casing shoe. WOC surface casing shoe to the surface. WOC Surface casing shoe to the surface. WOC MOCD ARTESIA ge and belief. BECEIVED JAN 23 2012 NMOCD ARTESIA	
13. Describe proposed or completed date of starting any proposed proposed completion or recomplete date of starting any proposed proposed completion or recomplete date of the NOTE: Cap string and power cable in 1. RIH with tubing open ended to 54 plug, reset if necessary. Packer 2. Load hole with plugging mud. Spot 3. Load hole with plugging mud. Spot 4. Load hole with plugging mud. Spot and tag plug, reset if necessary. SEE ATTACHED CONDITIONS OF APPROVAL I hereby certify that the information all the starting and the proposed of the	work). SEE RULE 19.15.7.14 N impletion. plug and abandon this well as foll in the hole, top of tubing at 5848'. 40' and spot a 200 sx Class "C" c in a 35 sx Class "C" cement plug for a 50 sx Class "C" cement plug for a 60 sx Class "C" cement p	pertinent details, at MAC. For Multip lows: ement plug from 4 from 2324'-2524' a from 1800'-2050' a from 0-350' across ets est of my knowled ulatory Complianc	Indigive pertinent dates, including estimated le Completions: Attach wellbore diagram of 340'-5440' in the 7" casing. WOC and tag across Glorieta top. across intermediate casing shoe. WOC surface casing shoe to the surface. WOC Surface casing shoe to the surface. WOC MOCD ARTESIA ge and belief. BECEIVED JAN 23 2012 NMOCD ARTESIA	
13. Describe proposed or completed date of starting any proposed proposed completion or recompleted proposed completed plans to NOTE: Cap string and power cable in 1. RIH with tubing open ended to 54 plug, reset if necessary. 2. Load hole with plugging mud. Spot and tag plug, reset if necessary. SEE ATTACHED CONDITIONS OF APPROVAL I hereby certify that the information all SIGNATURE Type or print name Tina Huert	work). SEE RULE 19.15.7.14 N impletion. plug and abandon this well as following at 5848'. 40' and spot a 200 sx Class "C" c squz. of a 35 sx Class "C" cement plug for a 50 sx Class "C" cement plug for a 60 sx	pertinent details, at MAC. For Multip lows: ement plug from 4 from 2324'-2524' a from 1800'-2050' a from 0-350' across ets est of my knowled ulatory Complianc	and give pertinent dates, including estimated le Completions: Attach wellbore diagram of days across Glorieta top. across Glorieta top. across intermediate casing shoe. Woc across intermediate casing shoe. Woc across intermediate casing shoe to the surface. WOC PECEIVED JAN 23 2012 NMOCD ARTESIA ge and belief. e Supervisor DATE January 23, 2012 Im.com PHONE: 575-748-4168	