Submit I Copy To Appropriate District Office	State of New Mexico			Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283			WELL API NO.	
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-23815	
District III - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE □ FEE □	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505		STATE SEE 6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505			NM 703-69	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or U	nit Agreement Name
(DO NOT USE THIS FORM FOR PROPO	SALS TO DRILL OR TO DEEPEN OR PL	UG BACK TO A		3
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			DONNELLY KELLY ST	
1. Type of Well: Oil Well Gas Well Other			8. Well Number 3	
2. Name of Operator			9. OGRID Number	
Alamo Permian Resources. LLC			274841	
3. Address of Operator			10. Pool name or Wildcat	
415 W. Wall Street, Suite 500, Midland, TX 79701			RED LAKE; Q/GRYBG/SAN ANDRES	
4. Well Location				
Unit Letter O: 990	feet from the S line and 22'	70 feet from th	ne E line	
Section 8 Township 18S Range 28E NMPM County EDDY				
	11. Elevation (Show whether DR,			
		, , ,, ,		
12. Check	Appropriate Box to Indicate N	ature of Notice,	Report or Other Da	ata
NOTICE OF IN	ITENITION TO	1 0115		NDT 05
			SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON		TERING CASING	
TEMPORARILY ABANDON TEMPORARILY ABANDON	CHANGE PLANS	_	AND A	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	T JOB	
DOWNHOLE COMMINGLE				
OTHER:		OTHER: RE	TURN TO PRODUCTION	ON
	pleted operations. (Clearly state all I			
	ork). SEE RULE 19.15.7.14 NMAC	C. For Multiple Cor	mpletions: Attach well	lbore diagram of
proposed completion or rec	completion.			
1-26-12				
MIRU PU, long stroke pump and no pump action. Tried to pull rods and pump but pump was stuck. Worked pump until it freed up and				
POOH with rods and pump. Pull rod on pump was stuck. Secure well and SDFN.				
• •	• •			
<u>1-27-12</u>				
Dropped standing valve and pressured up on tubing. Tubing would not hold. ND WH and NU BOP. Pick up tubing to tag bottom and POOH with pipe. Laid down 7 joints with holes. RIH and POOH w/ bit and casing scraper. Secure well and SDFWE.				
POOH with pipe. Laid down 7 joint	s with holes. RIH and POOH w/ bit	and casing scraper.	Secure well and SDFV	VE.
1-30-12				
RIH and POOH with Bailer and clea	an out well. Hydro test tubing in the	hale ND ROP set	TAC and NIIWH Se	ocure well and SDFN
Terr and 1 0011 with Danes and clea	in our wen. Hydro test tubing in the	noic, 14D DOI, set	TAC, and NO WII. SC	cuic wen and 551 14.
<u>1-31-12</u>			ſ	DEOCUTED
RIH with new pump and rods. HWO	and RD PU. Clean location.			RECEIVED
				_ EED A A 2012
				7 FEB 0 9 2012
Spud Date:	Rig Release Da	ite:		NMOCD ARTESIA
<u></u>		<u> </u>	 -	MINOCO ALLEGIA
				
I hereby certify that the information	above is true and complete to the be	est of my knowledge	e and belief.	
SIGNATURE TITLE Regulatory Affairs Coordinator DATE 02/07/2012				
,				
Type or print name				
APPROVED BY THE DOT TO 100 DATE OF 110 DAT				
APPROVED BY DOTE OF APPROVED (if any): Conditions of Approval (if any): DATE OF				
Conditions of Approval (if any):		•		• /