Submit 1 Copy To Appropriate District	State of New Mexico		Form C-103	
Office District I – (575) 393-6161	Energy, Minerals and Natural Resources			vised August 1, 2011
1625 N. French Dr , Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			WELL API NO. 30-015-28'	750
811 S. First St., Artesia, NM 88210	First St., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd , Aztec, NM 87410	1220 South St. Francis Dr.		STATE 🛚	FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 875	05	6. State Oil & Gas Lease	No.
1220 S St Francis Di , Santa Fe, NM 87505				
	ICES AND REPORTS ON WELLS	S D A CIV TO A	7. Lease Name or Unit A	greement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Big George State		
PROPOSALS) 1. Type of Well: Oil Well Gas Well Other SWD		-	8. Well Number	
			3	
2. Name of Operator			9. OGRID Number	
COG Operating, LLC 3. Address of Operator			229137 10. Pool name or Wildcat	
550 W. Texas Ave., Suite 100, Midland, TX 79701		SWD; CISCO		
4. Well Location				
	650 feet from the South	line and 16	feet from the	East line
Section 12	Township 17S Ra	ange 28E	NMPM Cour	nty Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3710'				
12 (1 1	A	CNT C T	0.1 D.	
12. Check A	Appropriate Box to Indicate Nat	ture of Notice, I	Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
				Α 🗆
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL	CASING/CEMENT	JOB \square	
DOWNHOLE COMMINGLE				
		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
proposed completion or recompletion.				
proposed completion of re-				
A. MIRU Well Service un	nit, set Dbl, Manual BOP			
B. Unset packer and POOH w/ IPC tubing and packer.				
C. PU 2 7/8" work string with packer and plug.				
D. GIH and isolate casing leak, spot sand on top of plug, and GIH w/ Cmt retainer				
E. Cement Squeeze leak, drill out and additional cement.				
F. Run in hole with injection packer and IPC tubing.				
G. Un J from packer and spot packer fluid, J on to packer.				
H. Run MIT test to conform to NMOCD requirements.I. Put on disposal after NMOCD witness of MIT.				
1. Put on disposal after N	MOCD witness of MIT.			
				
Spud Date: 4/11/9°	Rig Release Date	e:		
<u>. </u>				
I hereby certify that the information	above is true and complete to the bes	t of my knowledge	and belief.	
\bigcirc				
	1/1			
SIGNATURE SAVOCO I	TITLE Reg	ulatory Analyst	DATE	3/2/12
SIGNATURE		ulatory Analyst	DATE	3/2/12
Type or print name <u>Chasity Jackso</u>			DATE	
- :				
Type or print name Chasity Jackson For State Use Only		cjackson@concho.	com PHONE: 432	<u>-686-3087</u>