			RECI	EIVED									
District 1	5 11 11	- 1			ate of i	New Mex	ico F	HOBBS O	CD			S C 141	
1625 N French District II	Dr , Hobbs, P	NM 88240	JUN 1	4 2012 St	nerals a	and Natura	l Resources			Rev		Form C-141 tober 10, 2003	
1301 W Grand	Avenue, Arte	sia, NM 882	210	Ziloigj Illi			וח	EC 192	7011			·	
1000 Rio Brazos	s Road, Azteo	. NM 8141	MOCD	ARTESIA	vation Div	vision		.011	District (Office u	appropriate accordance		
District IV				1220	South	n St. Francis Dr. with Rule 116 on t						116 on back side of form	
1220 S St Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 RECEIVED side of form													
			Rele	ease Notific	eation	and Co	rrective A	etion					
JAW 12	17.349	902				OPERA'	ΓOR	ĮX.	Initia	al Report		Final Report	
Name of Co			Y COMPA	NY 15490			CKIE MARTIN	EZ					
Address 3				9705	Telephone No (432)688-1709								
Facility Nar	ne OSAGE	30-015-2	Facility Type BATTERY										
Surface Owner BUREAU OF LAND MANAGEMENT al Owner BUREAU OF LAND MANAGEMENT ease No. NMNM90807													
LOCATION OF RELEASE													
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/Wes	t Line	County			
G	34	198	29E	1980	NORT		1980	EAST		EDDY			
	l <u></u>							<u> </u>					
LatitudeLongitude													
NATURE OF RELEASE													
Type of Rele		75	Volume of Release 30 BBLS Volume Recovered 0										
Source of Release VALVE Was Immediate Notice Given?						Date and Hour of Occurrence 9/24/ Date and Mour of Discovery SAME If YES, To Whom?							
was illilledia	ite Notice C		Yes [] No 🛛 Not Re	equired	11 1123, 10	W HOM?						
By Whom?						Date and Hour							
Was a Watercourse Reached?						If YES, Volume Impacting the Watercourse							
☐ Yes ☒ No													
If a Watercourse was Impacted, Describe Fully *													
N/A													
Decombe Cou	Describe Cause of Problem and Remedial Action Taken *												
					orter - F	Holley Energ	ov numns to suc	k oil from	tanks o	łown ninel	ine that	t was	
unaccounted	for by Ho	lley Energ	gy. No oil	was recovered			lus (Issues		L L I l				
Cause of problem Tank Valve malfunction causing Transporter - Holley Energy pumps to suck oil from tanks down pipeline that was unaccounted for by Holley Energy. No oil was recovered Remedial Action Taken. Emptied tank with Valve malfunction and repaired valve Unaccounted for 30 bbls which will be shown on C-115 and MMS OGOR report as Lost oil													
Describe Area Affected and Cleanup Action Taken *													
N/A													
												,	
				· · · · · · · · · · · · · · · · · · ·									
	I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and												
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability													
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health													
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.													
1 /	1 al (<u>Λ </u>	guiations				OIL CON	SERVA	TION	DIVISIO	N		
_ \		11 119	HATT/	MA .		OIL CONSERVATION DIVISION							
Signature	<u> </u>	$L \cup W$	WWW	W.		Approved by District Supervisor							
Printed Name	VICKIE N	MARTINE	EZ	ν	A	Approved by	District Supervis	or e u ,	·				
						JUN 2 1 2012							
Title ENGINEER TECH II						Approval Date Expiration Date							
E-mail Addres	s VMAR1	TINEZ@S	M-ENERC	Y COM	_ c	Conditions of	Approval			1	Г		

* Attach Additional Sheets If Necessary

Date 11/10/2011

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION

PROPOSAL NOT LATER THAN:

Phone (432)688-1709

2RP-1185

Attached [