Submit 1 Copy To Appropriate Dis Office		State of New M	lexico		Form C-103	
District I - (\$75) 393-6161	Energ	gy, Minerals and Na	tural Resources		Revised August 1, 2011	
1625 N French Dr., Hobbs, NM 88	3240			WELL API NO.	20.015.22041	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	1 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION			30-015-33841		
District III - (505) 334-6178	istrict III - (505) 334-6178 1220 South St. Francis Dr.		5. Indicate Type of STATE	FEE		
1000 Rio Brazos Rd , Aztec, NM 8 <u>District IV</u> – (505) 476-3460	7410	Santa Fe, NM	87505	6. State Oil & Ga		
1220 S. St. Francis Dr., Santa Fe, N	ΙМ			o. State Off & Ga	s Lease 140.	
87505		250000000000000000000000000000000000000				
SUNDRY (DO NOT USE THIS FORM FOR		REPORTS ON WELL		/. Lease Name or NMNM101361X	Unit Agreement Name	
DIFFERENT RESERVOIR. USE				111111111111111111111111111111111111111		
PROPOSALS)  1. Type of Well: Oil Well  Gas Well  Other WIW			8. Well Number	017		
1. Type of Well: Oil Well Gas Well Other WIW  2. Name of Operator					9. OGRID Number	
2. Name of Operator SM ENERGY COMPANY				9. OGRID Numb	er 154903	
3. Address of Operator <sub>3300 N</sub> "A" ST BLDG 7-200			10. Pool name or	Wildcat		
MID	DLAND, TX 79705	5		SHUGART DELA	WARE, EAST	
4. Well Location						
Unit Letter A		feet from the <u>NORTI</u>			n the EAST line	
Section 24			Range 31E	NMPM	County EDDY	
ينيع المنطق المستطيرة المناسبة المستعدد والمستعدد	11. Elevat	tion (Show whether D	R, RKB, RI, GR, e	etc.)	and the state of t	
12 CF	neck Annronriat	e Box to Indicate	Nature of Notic	e, Report or Other	Data	
				, <b>,</b>		
	OF INTENTION			JBSEQUENT_REI		
PERFORM REMEDIAL WO		D ABANDON 🔲	REMEDIAL WO		ALTERING CASING	
TEMPORARILY ABANDON	<del></del>		1	<del></del>	P AND A	
PULL OR ALTER CASING	MULTIPLE	E COMPL	CASING/CEME	ENT JOB		
DOWNHOLE COMMINGLE						
OTHER:	. 4		OTHER: CLEA	AN OUT	$\boxtimes$	
13. Describe proposed o				and give pertinent date	s, including estimated date	
13. Describe proposed o of starting any propo	sed work). SEE R		l pertinent details,		s, including estimated date	
13. Describe proposed o	sed work). SEE R		l pertinent details,	and give pertinent date	s, including estimated date	
13. Describe proposed o of starting any propo	sed work). SEE R		l pertinent details,	and give pertinent date	s, including estimated date	
13. Describe proposed o of starting any propoproposed completion 5/21-30/12 CLEAN OUT	osed work). SEE R n or recompletion.	ULE 19.15.7.14 NMA	l pertinent details, AC. For Multiple (	and give pertinent date Completions: Attach w	s, including estimated date rellbore diagram of	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT MIRU. PU. TOH W/2-3/8	osed work). SEE Rings or recompletion.  IN TBG AND 5-1/	ULE 19.15.7.14 NMA 2 IN PACKER. TIH	I pertinent details, AC. For Multiple (	and give pertinent date Completions: Attach w	s, including estimated date rellbore diagram of CLEANED OUT FILL	
13. Describe proposed o of starting any propoproposed completion 5/21-30/12 CLEAN OUT	osed work). SEE Rings or recompletion.  IN TBG AND 5-1/CULATE WELLB	ULE 19.15.7.14 NMA 2 IN PACKER. TIH Y ORE CLEAN. TOOH	I pertinent details, AC. For Multiple ( W/BIT AND WS. I W/BIT. TIH W/F	and give pertinent date Completions: Attach w TAG FILL @ 5,426'. C PKR. SET PKR AT 500	s, including estimated date rellbore diagram of CLEANED OUT FILL OF FT. ACIDIZED	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO	osed work). SEE RI n or recompletion. IN TBG AND 5-1/ CULATE WELLBO 142 FT W/4500 GA H W/PKR AND TI	ULE 19.15.7.14 NMA  2 IN PACKER. TIH Y  ORE CLEAN. TOOH  LS 15% NEFE HCL  BG. TIH W/BIT ANE	I pertinent details, AC. For Multiple ( W/BIT AND WS. I W/BIT. TIH W/F AND 500 GALS > O TAG PBTD (550	and give pertinent date Completions: Attach w TAG FILL @ 5,426'. C PKR. SET PKR AT 500 XYLENE DIVERTING 07 FT). TOH W/BIT. T	s, including estimated date rellbore diagram of CLEANED OUT FILL TO FT. ACIDIZED W/ROCK SALT.	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, S	IN TBG AND 5-1/CULATE WELLBOATE WELLBOATE WELLBOATE WITH WITH WITH WITH WITH WITH WITH WITH	ULE 19.15.7.14 NMA  2 IN PACKER. TIH Y  ORE CLEAN. TOOH  LS 15% NEFE HCL  BG. TIH W/BIT ANE	I pertinent details, AC. For Multiple ( W/BIT AND WS. I W/BIT. TIH W/F AND 500 GALS > O TAG PBTD (550	and give pertinent date Completions: Attach w TAG FILL @ 5,426'. C PKR. SET PKR AT 500 XYLENE DIVERTING 07 FT). TOH W/BIT. T	s, including estimated date rellbore diagram of CLEANED OUT FILL TO FT. ACIDIZED W/ROCK SALT.	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO	IN TBG AND 5-1/CULATE WELLBOATE WELLBOATE WELLBOATE WITH WITH WITH WITH WITH WITH WITH WITH	ULE 19.15.7.14 NMA  2 IN PACKER. TIH Y  ORE CLEAN. TOOH  LS 15% NEFE HCL  BG. TIH W/BIT ANE	I pertinent details, AC. For Multiple ( W/BIT AND WS. I W/BIT. TIH W/F AND 500 GALS > D TAG PBTD (550) TEST ANNULUS	and give pertinent date Completions: Attach w TAG FILL @ 5,426'. C PKR. SET PKR AT 500 XYLENE DIVERTING 07 FT). TOH W/BIT. T S TO 500# AND CHAF	s, including estimated date rellbore diagram of CLEANED OUT FILL TO FT. ACIDIZED W/ROCK SALT.	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, S	IN TBG AND 5-1/CULATE WELLBG HAY BY WELLBG W	ULE 19.15.7.14 NMA  2 IN PACKER. TIH Y  ORE CLEAN. TOOH  LS 15% NEFE HCL  BG. TIH W/BIT ANE  T AND PRESSURE	I pertinent details, AC. For Multiple ( W/BIT AND WS. I W/BIT. TIH W/F AND 500 GALS > D TAG PBTD (550) TEST ANNULUS	and give pertinent date Completions: Attach was TAG FILL @ 5,426'. OPKR. SET PKR AT 500 XYLENE DIVERTING TO 500# AND CHAF RECEIVED	s, including estimated date rellbore diagram of CLEANED OUT FILL TO FT. ACIDIZED W/ROCK SALT.	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIREST.	IN TBG AND 5-1/CULATE WELLBOARD FT W/4500 GAH W/PKR AND TISET PKR @ 5045 F	ULE 19.15.7.14 NMA  2 IN PACKER. TIH Y  ORE CLEAN. TOOH  LS 15% NEFE HCL  BG. TIH W/BIT ANE  T AND PRESSURE	I pertinent details, AC. For Multiple ( W/BIT AND WS. I W/BIT. TIH W/F AND 500 GALS > D TAG PBTD (550) TEST ANNULUS	and give pertinent date Completions: Attach w TAG FILL @ 5,426'. C PKR. SET PKR AT 500 XYLENE DIVERTING 07 FT). TOH W/BIT. T S TO 500# AND CHAF	s, including estimated date rellbore diagram of CLEANED OUT FILL TO FT. ACIDIZED W/ROCK SALT.	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIREXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE	IN TBG AND 5-1/CULATE WELLBOARD FT W/4500 GAH W/PKR AND TISET PKR @ 5045 F	ULE 19.15.7.14 NMA  2 IN PACKER. TIH Y  ORE CLEAN. TOOH  LS 15% NEFE HCL  BG. TIH W/BIT ANE  T AND PRESSURE	I pertinent details, AC. For Multiple ( W/BIT AND WS. I W/BIT. TIH W/F AND 500 GALS > D TAG PBTD (550 TEST ANNULUS	and give pertinent date Completions: Attach we TAG FILL @ 5,426'. OPKR. SET PKR AT 500 XYLENE DIVERTING TO 500# AND CHAP RECEIVED  JUN 11 2012	s, including estimated date rellbore diagram of CLEANED OUT FILL 20 FT. ACIDIZED W/ROCK SALT. THE W/5-1/2 IN PKR RTED FOR 30 MIN	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT  MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIPLACED WELL BACK O	IN TBG AND 5-1/CULATE WELLBOARD FT W/4500 GAH W/PKR AND TISET PKR @ 5045 F	ULE 19.15.7.14 NMA  2 IN PACKER. TIH Y  ORE CLEAN. TOOH  LS 15% NEFE HCL  BG. TIH W/BIT ANE  T AND PRESSURE  ATTACHED	I pertinent details, AC. For Multiple ( W/BIT AND WS. W/BIT. TIH W/F AND 500 GALS > D TAG PBTD (550 TEST ANNULUS	and give pertinent date Completions: Attach was TAG FILL @ 5,426'. OPKR. SET PKR AT 500 XYLENE DIVERTING TO 500# AND CHAF RECEIVED	s, including estimated date rellbore diagram of CLEANED OUT FILL 20 FT. ACIDIZED W/ROCK SALT. THE W/5-1/2 IN PKR RTED FOR 30 MIN	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIREST.	IN TBG AND 5-1/CULATE WELLBOARD FT W/4500 GAH W/PKR AND TISET PKR @ 5045 F	ULE 19.15.7.14 NMA  2 IN PACKER. TIH Y  ORE CLEAN. TOOH  LS 15% NEFE HCL  BG. TIH W/BIT ANE  T AND PRESSURE	I pertinent details, AC. For Multiple ( W/BIT AND WS. W/BIT. TIH W/F AND 500 GALS > D TAG PBTD (550 TEST ANNULUS	and give pertinent date Completions: Attach we TAG FILL @ 5,426'. OPKR. SET PKR AT 500 XYLENE DIVERTING TO 500# AND CHAP RECEIVED  JUN 11 2012	s, including estimated date rellbore diagram of CLEANED OUT FILL 20 FT. ACIDIZED W/ROCK SALT. THE W/5-1/2 IN PKR RTED FOR 30 MIN	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT  MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIPLACED WELL BACK O	IN TBG AND 5-1/CULATE WELLBOARD FT W/4500 GAH W/PKR AND TISET PKR @ 5045 F	ULE 19.15.7.14 NMA  2 IN PACKER. TIH Y ORE CLEAN. TOOH LS 15% NEFE HCL BG. TIH W/BIT ANE T AND PRESSURE  ATTACHED	I pertinent details, AC. For Multiple ( W/BIT AND WS. W/BIT. TIH W/F AND 500 GALS > D TAG PBTD (550 TEST ANNULUS	and give pertinent date Completions: Attach we TAG FILL @ 5,426'. OPKR. SET PKR AT 500 XYLENE DIVERTING TO 500# AND CHAP RECEIVED  JUN 11 2012	s, including estimated date rellbore diagram of CLEANED OUT FILL 20 FT. ACIDIZED W/ROCK SALT. THE W/5-1/2 IN PKR RTED FOR 30 MIN	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT  MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIPLACED WELL BACK O	IN TBG AND 5-1/CULATE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WORK AND THE SET PKR @ 5045 FOR TEST - CHARTON INJECTION.	ULE 19.15.7.14 NMA  2 IN PACKER. TIH  ORE CLEAN. TOOH  LS 15% NEFE HCL  BG. TIH W/BIT AND  T AND PRESSURE  ATTACHED  Rig Release I	I pertinent details, AC. For Multiple (Market Market) W/BIT AND WS. W/BIT. TIH W/FAND 500 GALS (Market) D TAG PBTD (550) TEST ANNULUS	and give pertinent date Completions: Attach w TAG FILL @ 5,426'. O PKR. SET PKR AT 500 XYLENE DIVERTING OF FT). TOH W/BIT. T S TO 500# AND CHAF RECEIVED  JUN 11 2012  MOCD ARTESIA	s, including estimated date rellbore diagram of CLEANED OUT FILL 20 FT. ACIDIZED W/ROCK SALT. THE W/5-1/2 IN PKR RTED FOR 30 MIN	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT  MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIPLACED WELL BACK O	IN TBG AND 5-1/CULATE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WORK AND THE SET PKR @ 5045 FOR TEST - CHARTON INJECTION.	ULE 19.15.7.14 NMA  2 IN PACKER. TIH  ORE CLEAN. TOOH  LS 15% NEFE HCL  BG. TIH W/BIT AND  T AND PRESSURE  ATTACHED  Rig Release I	I pertinent details, AC. For Multiple (Market Market) W/BIT AND WS. W/BIT. TIH W/FAND 500 GALS (Market) D TAG PBTD (550) TEST ANNULUS	and give pertinent date Completions: Attach w TAG FILL @ 5,426'. O PKR. SET PKR AT 500 XYLENE DIVERTING OF FT). TOH W/BIT. T S TO 500# AND CHAF RECEIVED  JUN 11 2012  MOCD ARTESIA	s, including estimated date rellbore diagram of CLEANED OUT FILL 20 FT. ACIDIZED W/ROCK SALT. THE W/5-1/2 IN PKR RTED FOR 30 MIN	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT  MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIPLACED WELL BACK O	IN TBG AND 5-1/CULATE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WORK AND THE SET PKR @ 5045 FOR TEST - CHARTON INJECTION.	ULE 19.15.7.14 NMA  2 IN PACKER. TIH YORE CLEAN. TOOH LS 15% NEFE HCL BG. TIH W/BIT AND T AND PRESSURE  ATTACHED  Rig Release I	W/BIT AND WS. W/BIT AND WS. W/BIT. TIH W/F AND 500 GALS X D TAG PBTD (550 TEST ANNULUS	and give pertinent date Completions: Attach w TAG FILL @ 5,426'. O PKR. SET PKR AT 500 XYLENE DIVERTING OF FT). TOH W/BIT. T S TO 500# AND CHAF RECEIVED  JUN 11 2012  MOCD ARTESIA	s, including estimated date rellbore diagram of CLEANED OUT FILL 20 FT. ACIDIZED W/ROCK SALT. THE W/5-1/2 IN PKR RTED FOR 30 MIN	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT  MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIPLACED WELL BACK O	IN TBG AND 5-1/CULATE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WELLBOUGHTE WORK AND THE SET PKR @ 5045 FOR TEST - CHARTON INJECTION.	ULE 19.15.7.14 NMA  2 IN PACKER. TIH YORE CLEAN. TOOH LS 15% NEFE HCL BG. TIH W/BIT AND T AND PRESSURE  ATTACHED  Rig Release I	I pertinent details, AC. For Multiple (Market Market) W/BIT AND WS. W/BIT. TIH W/FAND 500 GALS (Market) D TAG PBTD (550) TEST ANNULUS	TAG FILL @ 5,426'. CPKR. SET PKR AT 500 XYLENE DIVERTING TO 500# AND CHAF RECEIVED  JUN 11 2012  MOCD ARTESIA	s, including estimated date rellbore diagram of CLEANED OUT FILL 20 FT. ACIDIZED W/ROCK SALT. THE W/5-1/2 IN PKR RTED FOR 30 MIN	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT  MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIPLACED WELL BACK OF Spud Date:	IN TBG AND 5-1/CULATE WELLBOYSET W/4500 GAH W/PKR AND THE SET PKR @ 5045 FT TEST - CHART ON INJECTION.	2 IN PACKER. TIH ORE CLEAN. TOOH LS 15% NEFE HCL BG. TIH W/BIT AND PRESSURE  ATTACHED  Rig Release I	W/BIT AND WS. W/BIT AND WS. W/BIT. TIH W/F AND 500 GALS > TAG PBTD (550 TEST ANNULUS  Date:  Date:  INEER TECH II	TAG FILL @ 5,426'. CPKR. SET PKR AT 500 XYLENE DIVERTING TO 500# AND CHAP AND CHAP JUN 11 2012  MOCD ARTESIA	s, including estimated date rellbore diagram of CLEANED OUT FILL 200 FT. ACIDIZED SEW/ROCK SALT. STH W/5-1/2 IN PKR RTED FOR 30 MIN	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT  MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIREXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIPLACED WELL BACK OF Spud Date:  I hereby certify that the information of the proposed completion of the proposed complete in the proposed completion of the proposed completion of the proposed completion in the	IN TBG AND 5-1/CULATE WELLBOYSET W/4500 GAH W/PKR AND THE SET PKR @ 5045 FT TEST - CHART ON INJECTION.	2 IN PACKER. TIH ORE CLEAN. TOOH LS 15% NEFE HCL BG. TIH W/BIT AND PRESSURE  ATTACHED  Rig Release I	W/BIT AND WS. W/BIT AND WS. W/BIT. TIH W/F AND 500 GALS > TAG PBTD (550 TEST ANNULUS  Date:  Date:  INEER TECH II	TAG FILL @ 5,426'. CPKR. SET PKR AT 500 XYLENE DIVERTING TO 500# AND CHAF RECEIVED  JUN 11 2012  MOCD ARTESIA	s, including estimated date rellbore diagram of CLEANED OUT FILL 200 FT. ACIDIZED SEW/ROCK SALT. STH W/5-1/2 IN PKR RTED FOR 30 MIN	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT  MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIR EXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIPLACED WELL BACK OF Spud Date:	IN TBG AND 5-1/CULATE WELLBOYSET W/4500 GAH W/PKR AND THE SET PKR @ 5045 FT TEST - CHART ON INJECTION.	2 IN PACKER. TIH ORE CLEAN. TOOH LS 15% NEFE HCL BG. TIH W/BIT AND PRESSURE ATTACHED  Rig Release I  and complete to the  E-mail addre	W/BIT AND WS. W/BIT AND WS. W/BIT. TIH W/F AND 500 GALS > TAG PBTD (550 TEST ANNULUS  Date:    NI   NI   NI   NI   NI   NI   NI   N	TAG FILL @ 5,426'. CPKR. SET PKR AT 500 XYLENE DIVERTING D7 FT). TOH W/BIT. TS TO 500# AND CHAF RECEIVED JUN 11 2012 MOCD ARTESIA  edge and belief.  DA  Z@SM-ENERGY.CPM	s, including estimated date relibore diagram of cleaned out fill to fill the fill to fill the	
13. Describe proposed of starting any proposed completion 5/21-30/12 CLEAN OUT  MIRU. PU. TOH W/2-3/8 TO PBTD (5507 FT). CIREXISTING PERF 5082-52 SWAB LOAD BACK. TO AND 2-3/8 IN IPC TBG, STEST. HELD PRESSURE 5/31/12 CONDUCTED MIPLACED WELL BACK OF Spud Date:  I hereby certify that the information of the proposed completion of the proposed complete in the proposed completion of the proposed completion of the proposed completion in the	IN TBG AND 5-1/CULATE WELLBOWN	2 IN PACKER. TIH ORE CLEAN. TOOH LS 15% NEFE HCL BG. TIH W/BIT AND PRESSURE  ATTACHED  Rig Release I	W/BIT AND WS. W/BIT AND WS. W/BIT. TIH W/F AND 500 GALS > TAG PBTD (550 TEST ANNULUS  Date:    NI   NI   NI   NI   NI   NI   NI   N	TAG FILL @ 5,426'. CPKR. SET PKR AT 500 XYLENE DIVERTING D7 FT). TOH W/BIT. TS TO 500# AND CHAF RECEIVED JUN 11 2012 MOCD ARTESIA  edge and belief.  DA  Z@SM-ENERGY.CPM	s, including estimated date rellbore diagram of CLEANED OUT FILL 200 FT. ACIDIZED SEW/ROCK SALT. STH W/5-1/2 IN PKR RTED FOR 30 MIN	

