

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUL 12 2012

NMOCD ARTESIA

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

nJMW 1219534727 OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	550 W. Texas, Suite 100, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	Folk Federal Lease	Facility Type	Flowlines

Surface Owner	Federal	Mineral Owner		Lease No. (API#)	30-015-36862
				Closest well location	

LOCATION OF RELEASE

Folk Fed #10

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	17	17S	29E					Eddy

Latitude 32.83623 Longitude 104.09164

NATURE OF RELEASE

Type of Release	Produced fluid	Volume of Release	5bbls oil 5bbls water	Volume Recovered	Obbls Majority consumed in fire
Source of Release	Burned flowlines	Date and Hour of Occurrence	07/05/2012	Date and Hour of Discovery	07/05/2012 3:30 P.M.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD Jim Amos-BLM Terry Gregston-BLM		
By Whom?	Michelle Mullins	Date and Hour	07/06/2012 10:46 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A lighting storm caused a fire on our Folk Federal lease burning several flowlines, which caused the release of fluid. We are in the process of replacing all impacted flowlines.

Describe Area Affected and Cleanup Action Taken.\*

Initially approximately 10bbls were released from the burned flowlines on our Folk Federal Lease due to a lighting fire. We were unable to recover any of the fluid from the flowlines because the majority of the fluid was consumed in the fire. Tetra Tech will sample the spill site area to delineate any possible contamination from the release and we will present a remediation workplan to the NMOCD/BLM for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Josh Russo		Approved by District Supervisor: Signed By 	
Title: HSE Coordinator		Approval Date: JUL 13 2012	Expiration Date:
E-mail Address: jrusso@conchoresources.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 07/12/2012	Phone: 432-212-2399		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. SUBMIT REMEDIATION  
PROPOSAL OT LATER THAN:  
12

2RP-1224