

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

SEP 07 2012

Form C-141  
Revised October 10, 2003

Submit to the appropriate District Office in accordance with 19.15.29 NMAC

NMOCD ARTESIA

Release Notification and Corrective Action

nJM/W1225740956

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating	269324	Contact: Joe Hernandez
Address: 2130 W. Bender Hobbs, NM 88240		Telephone No.: 575-738-1739
Facility Name: HE West A # 32		Facility Type: Oil

Surface Owner: Federal	Mineral Owner: Federal	API No.: 3001528324
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	03	17S	31E	2622	North	1330	East	Eddy

Latitude: 32.86356 Longitude: -103.85255

NATURE OF RELEASE



Type of Release: Oil / Produced Water	Volume of Release: 1 / 1	Volume Recovered: 0 / 0
Source of Release: Poly Pipeline	Date and Hour of Occurrence: 08/12/2012 11am	Date and Hour of Discovery: 08/12/2012 11:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? M. Bratcher-NM OCD Terry Gregston-BLM	
By Whom? Joe Hernandez	Date and Hour 09/04/2012 7:35am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*:

Describe Cause of Problem and Remedial Action Taken.\*: Was checking wells spotted a 3" poly leaking from where pipe was fused together, leak was caused by age and heat exposure, put clamp to stop it from leaking while it got repaired, clamp did not hold so had to shut in well.

Describe Area Affected and Cleanup Action Taken.\*: sprayed about a 15'x15' spot. West of well head. Initial assesment pending/ BLM okayed to move forward on cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Joe Hernandez	Approved by District Supervisor: Signed By 	
Title: Production Foreman	Approval Date: SEP 13 2012	Expiration Date:
E-mail Address: jhernandez@linenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 09/07/2012 Phone: 575-942-9492		

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN:

October 13, 2012

2RP-1292