

SUNDRY NOTICES AND REPORTS ON WELLS

OGD Artesia

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals

SUBMIT IN TRIPLICATE - Other instructions on page 2

1 Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other SWD WELL		5. Lease Serial No. NM 014103
2 Name of Operator DEVON ENERGY PRODUCTION COMPANY, LP		6 If Indian, Allottee or Tribe Name
3a. Address 333 West Sheridan Avenue, Oklahoma City, OK 73102-5015	3b. Phone No. (include area code) 405-552-4615	7 Unit or CA Agreement Name and No
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 330 FSL 710 FWL 22 T18S R31E		8 Well Name and No Littlefield AB Federal #5
		9 API Well No. 30-015-20001
		10. Field and Pool, or Exploratory Area Shugart
		11 County or Parish, State Eddy NM

12. CHECK APPROPRIATE BOX(es) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA


TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Withdraw P&A
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal deepens directionally or recompletes horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)

Withdraw approved sundry to plug and abandon wellbore dated 4/21/12.

Devon Energy wished to withdraw the sundry that was approved for plug and abandonment dated 4/21/12.

This well was retested on 5/6/12, making 8 BOPD, 35 BWPD, AND .5 MCFD. Devon has returned this well to active producing status.



14. I hereby certify that the foregoing is true and correct Name: Ronnie Slack	Title: Operations Technician
Signature: <i>Ronnie Slack</i>	Date: 8/7/2012

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by: <i>James L. Ames</i>	Title: SEPS	Date: 9-9-12
Conditions of approval, if any are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct or operations thereon.	Office: CFD	

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212 make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

At 9/17/2012

Accepted for record
NMOCD