

NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop Cabinet Secretary Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Field hispection Program "Preserving the integral of Our Eurobergmann"

03-Aug-05

YATES PETROLEUM CORPORATION

105 S 4TH ST

ARTESIA NM 88210

NOTICE OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION

PENNZOIL MZ FEDERAL No.001	D-11-18S-30E	30-0 1 5-2318 8 -00-00
Inspection	*Significant	Corrective

Chris Beadle

Date

08/02/2005

Type Inspection Routine/Periodic Inspector

Violation? Yes

Non-Compliance? No

ctive Action Due By:

9/2/2005

Inspection No. iCLB0521449851

Violations

Tank Battery Equipment (Rules 114, 115)

Surface Damage/Restoration

Surface Leaks/Spills

Comments on Inspection:

Large area of pasture impacted by partially remediated spill from tank battery. Chloride residues inside fence and berm area of tank battery. Southern wall of tank battery has new material on slope above excavated area between road and tank battery. Contamination extends across road to fence line approximately 75-100 yards south east of tank battery. Center tank of tank battery actively leaking from flange, this area heavily saturated.

PENNZOIL MZ FEDERAL No.002

C-11-18S-30E

30-015-27591-00-00

Inspection Date

08/02/2005

Type Inspection
Routine/Periodic

Inspector

Chris Beadle

*Significant
Violation? Non-Compliant

Non-Compliance?

Corrective Action Due By: 9/2/2005

Inspection No. iCLB0521449012

Violations

Surface Damage/Restoration

Surface Leaks/Spills

Comments on Inspection:

Spill event in April 2002 reportedly 8bbl near separator without remediation actions. Slope behind separator contaminated to old road, approximately 45 feet. Heavy smell of hydrocarbons from old road into fenced area. The area inside the bern contaminated. Wellhead contaminated with produced fluids which have run off to the east (approximately 15 feet) and south (approximately 25 feet). Remediation is required on all areas showing visible contamination. Contact NMOCD

District 2 Environmental Compliance Officer to discuss remediation requirements.

Yes

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from Eeld inspector data entries - not all blanks will contain data.

*Significant Non-Compliance events are reprorted directly to the EPA, Region VI, Dallas, Texas.