

**SUNDRY NOTICES AND REPORTS ON WELLS**

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

<b>SUBMIT IN TRIPLICATE- Other instructions on reverse side.</b>		5. Lease Serial No. NM-025777
1. Type of Well <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other		6. If Indian, Allottee or Tribe Name
2. Name of Operator St. Mary Land & Exploration		7. If Unit or CA/Agreement, Name and/or No.
3a. Address 580 Westlake Park Blvd, Ste 600 Houston, TX 77079		8. Well Name and No. Geronimo Federal Well #11
3b. Phone No. (include area code) (281) 677-2771		9. API Well No. 30-015-25803
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)  990' FSL & 330' FEL Sec 24, SESB, T18S, R31E		10. Field and Pool, or Exploratory Area Shuggart Delaware East
		11. County or Parish, State Eddy County, New Mexico

RECEIVED

AUG 12 2005

**12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA**

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

7/20/05 1. Notify BLM 7/21/05 2. Tag TOC @ 4565'. 3. Circulate hole w/ MLF. 4. Spot 25 sx. cmt. 3575' - 3329'. 5. Spot 25 sx. cmt. @ 2281'. 7/22/05 6. Tag TOC @ 2081'. 7. Circulate 45 sx. cmt. 414' - surface. 7. RDMO. Cut off wellhead & anchors, install dry hole marker, and clean location.

Approved as to plugging of the well bore  
liability under bond is retained until  
surface restoration is completed.


**APPROVED**  
  
 AUG 10 2005  
  
 LES BABYAK  
 PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Roger Massey

Title Agent

Signature



Date 7/27/05

**THIS SPACE FOR FEDERAL OR STATE OFFICE USE**

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)