

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-33628	
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name Beretta 26 State Com	
8. Well Number 1	
9. OGRID Number 025482	
10. Pool name or Wildcat Loco Hills NW; Wolfcamp	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator Xeric Oil & Gas Corporation

3. Address of Operator P. O. Box 352, Midland, TX 79702

4. Well Location
Unit Letter B : 660 feet from the North line and 1650 feet from the East line
Section 26 Township 18S Range 28E NMPM Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
GR 3476'

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Change Formations ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

7/8/05 POOH w/tbg & pkr. Set CIBP @ 8700'. RIH w/cement bailer & dump 16' cmt on top of CIBP to isolate Wolfcamp formation.
7/9/05 Perf Bonespring with 2 spf from 6806'-6820'. Set packer @ 6709'. Swab well dn to pkr. SI, waiting on acid.
7/12/05 Open well. Swab. Acidize perms w/2,000 gal. 15% HCl. Flow back acid & swab well. SI for night.
7/13/05 Open well, flow then swab. POOH w/pkr. Perf Bonespring with 2 spf from 6506'-6520'. Set RBP @ 6700'. Set pkr @ 6432'. SD for night.
7/14/05 Open well & swab well dry. Acidize perms w/2000 gal HCL. Open well, flow then swab.
7/17/05 Do chemical job to unlock formation & flush w/kcl wtr. SI well.
7/20/05 POOH w/Pkr & RBP. RIH w/ tbg.
7/21/05 RIH w/production string & set pump jack. SI waiting on electrical installation.
8/6/05 Turn well on.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Angie Crawford TITLE Production Analyst DATE 8/31/05

Type or print name Angie Crawford E-mail address: ACrawford@xericcoil.com Telephone No. 432-683-3171

For State Use Only

FOR RECORDS ONLY

APPROVED BY: _____ TITLE _____ DATE SEP 08 2005

Conditions of Approval (if any):