Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103 October 13, 2009		
District 1 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-10312		
District III	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE 🛛 FEE 🗌		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NM 87505			STATE 647		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			 Lease Name or Unit Agreement Name STATE 647 		
PROPOSALS.)	Gas Well 🔲 Other	8. Well Number 203			
2. Name of Operator			9. OGRID Number		
Alamo Permian Resources. LLC			274841 10. Pool name or Wildcat		
3. Address of Operator 415 W. Wall Street, Suite 500, Midland, TX 79701			ARTESIA; Queen-Grayburg-San Andres		
4. Well Location	······································				
Unit Letter P : 330 feet	from the S line and 330 feet from	the <u>E</u> line			
Section 25	Township 17S	Range 28E	NMPM County EDDY		
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data					
NOTICE OF INTENTION TO: SUE PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN DOWNHOLE COMMINGLE COMMINGLE					
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
* See Attached	Notify QCD 24 h	rs. prior	NOV 20 2012		
	To any work d	ione.	NMOCD ARTESIA		
I hereby certify that the information	above is true and complete to the be	est of my knowledge	e and belief		
	•	• •			
SIGNATURE Them Fe	hit TITLE Regula	atory Affairs Coor	dinator DATE NOV 15, 2012		
Type or print name THOMAS FULVI E-mail address: tfulvi@alamoresources.com PHONE: 432.897.0673					
For State Use Only	Approval Granted pr is complete by 2./	oviding work			
APPROVER BY:	TITLE	/	_DATE_/// 26/2012		

Conditions of Approval (if any):


٠....: د

.

State 647 #203 P&A Procedure

- On 11-8-12 we MIRU PU to determine integrity of casing.
 - 11-9-12 We MIRU Black Warrior Wireline and ran a 42 arm Multi Sensor Casing Inspection Log and a Cement Bond Gamma Ray/Collar Log.
 - It was determined that there were no apparent "holes" in the 4 ½" production casing and the TOC is at 1,720'.
- We then ran an RBP, set at 2,000' (320' below the TOC), and a Tension Packer to double check the integrity of the casing and check for any type of casing leak and found that we had a casing leak in between 420' and 607'.
- As we were preparing to retrieve the RBP to set up the well for a Squeeze Job, on 11-13-12, we found that we could not get the retrieving head down past 607'. Upon inspecting the retrieving head and seeing a half moon shaped imprint, it has been determined that the 4 ½" production casing is parted at 607'. We then tried to get back in the casing open ended with 2 3/8" tbg and a collar on the bottom and were successful to run down to 1950'.
- I believe it would be in our best interest to not pull back through the parted casing and risk not being able to get back in, and proceed with the following P&A procedure:
- 1. MIRU Cementing CO.
- 2. Spot a 60 sack cement plug on top of the RBP at 2000' up to TOC around 1720'.
- 3. WOC and tag to ensure cement set.
- 4. Fill casing with mud to 800'.
- 5. Through Research done by our Geologist, it has been found that the Top of salt is at 257' with a few small stringers up to 160', and the base of the salt is at 640'.
- 6. RU Wireline Co. and RIH through 2 3/8" tbg and perforate 4 3 1/8" perforations at 650'.
- 7. POOH with tbg, RIH with tension packer and tbg to 350' and set packer.
- Squeeze the casing until we get good cement circulation coming out of the 8 5/8" x 4 ½" annulus valve, flush tbg to the bottom of the packer, shut tbg valve allowing cement to set and not creating a U-Tube effect.
- 9. Unset Packer and POOH filling 4 ½" casing to surface
- 10. Top off cement to surface.
- 11. Remove BOP.
- 12. Cut off well Head and verify cement to surface in all strings, top off any voids with cement.
- 13. Install P&A marker.
- 14. Clean and Reclaim Location.

ALAMO PERMIAN RESOURCES, LLC WELLBORE DIAGRAM



Originally Drilled as State 647 #203 by International-Yates, Artesia, NM.	Cumulative Prod. (12/31/11):	
	OIL	36.848 MBO
Workover 02/16-20/2012 found 95' of fill, ran new pump & returned to production.	GAS	26.874 MMCF
	WATER	82.634 MBW
	INJECT.	MBW

HPS: 11/10/2012

NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Alamo Permian Rosources LLC Well Name & Number: <u>5767e 647</u> #203 API #: 30-015-10312

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.

8. Cement Retainers may not be used.

- 9. Squeeze pressures not to exceed 500 psi., unless approval is given by NMOCD Plugging Supervisor.
- 10. Plugs may be combined after consulting with NMOCD P & A Supervisor.
- 11. Minimum WOC time for tag plugs will be 4 hrs.

DG

Date: 11/26/2012