Date

	UNITED STATES EPARTMENT OF THE II	NTERIOR C	OCD Artesia	OMB	NO. 1004-0135 es: July 31, 2010
BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				5. Lease Serial No. NMNM12833	
			6. If Indian, Allotte	e or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Ag	greement, Name and/or No.
I. Type of Well ☐ Oil Well ☐ Other				8. Well Name and N ARROW ARW	No. FEDERAL COM 1
2. Name of Operator Contact: TINA HUERTA YATES PETROLEUM CORPORATIONE-Mail: tinah@yatespetroleum.com				9. API Well No. 30-015-28898	 }
3a. Address 105 SOUTH FOURTH STREE ARTESIA, NM 88210	3b. Phone No. (include Ph: 575-748-4168) Fx: 575-748-4585	·	10. Field and Pool, PENASCO; V		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			REUI	- I County or Paris	h, and State
¹ Sec 11 T19S R25E NWSE 19	•	NOV 2	9 20 2 EDDY COUN	TY, NM	
				ARTESIA	
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE NATU	JRE-OF-NOT	TCE, REPORT, OR OTH	ERDATA :
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent	☐ Acidize	□ Deepen		Production (Start/Resume)	☐ Water Shut-Off
☐ Subsequent Report	Alter Casing	Fracture Tre	_	Reclamation	□ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair ☐ Change Plans	☐ New Constr ☐ Plug and At	لنسا	Recomplete	□ Other
I mai Abandonment Notice	Convert to Injection	☐ Flug and At	ب	Temporarily Abandon Water Disposal	
13. Describe Proposed or Completed Op		_		-	proximate duration thereof.
If the proposal is to deepen direction Attach the Bond under which the wo following completion of the involved testing has been completed. Final Aldetermined that the site is ready for f	ally or recomplete horizontally, rk will be performed or provide I operations. If the operation re bandonment Notices shall be fil	give subsurface location the Bond No. on file wit sults in a multiple compl	is and measured a th BLM/BIA. Re letion or recomple	and true vertical depths of all pe equired subsequent reports shall etion in a new interval, a Form reclamation, have been complet	ertinent markers and zones. I be filed within 30 days 3160-4 shall be filed once ed, and the operator has
REVISED		UBJECT TO LI		APPROVI	<u>-U</u>
Yates Petroleum Corporation 1. MIRU WSU and all safety of the safety of	equipment as needed. Ni ipment if any exists.; then set a 7" CIBP at 76; 6180'(77). acker at 6100' and acidize	J BOP. 32' and cap it with 35 e with 2000g 20% H	l 5' Class "H" co CL with 2g/M	gellingragent F I AN MAN	MOD OF IAGEMENT DEFICE
6. Move tools to straddle perf agent, cationic surfactant, cor	s 5960'-5994' and acidize	with 2000g 20% HO	CL with 2g/M on the bottom	gelling om	- Jan recost
ing, Periew See	Alfached Co	A 11/28/12	-JAM	ACCOC!	ed for record
14.1 hereby certify that the foregoing is	Electronic Submission #				
For YATES PETROLEUM CORP Committed to AFMSS for processing by Name (Printed/Typed) TINA HUERTA			DEBORAH MCKINNEY on 11/13/2012 ()		
Name (Printed/Typed) TINA HUE	IN IA	Title	REG REPO	TING SUPERVISOR	
Signature (Electronic S		Date	11/12/2012		
	THIS SPACE FO	OR FEDERAL OR	STATE OF	FICE USE	• • • • • • • • • • • • • • • • • • • •

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Office Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Title

Additional data for EC transaction #160056 that would not fit on the form

32. Additional remarks, continued


perf and over flush by 75 bbls.
7. Move tools to straddle perfs 5760'-5790' and acidize with 2000g 20% HCL with 2g/M gelling agent, cationic surfactant, corrosion inhibitor and iron control additives. Flush to the bottom


agent, cationic surfactant, corrosion innibitor and iron control additives. Plush to the bottom perf and over flush by 75 bbls.

8. Move the tools to straddle all the perfs and swab test and evaluate and consider turning the well over to production or pumping a 30,000g acid frac.

9. POOH with tubing and tools. TIH with TAC, SN and 2-7/8" tubing. TIH with pump and rods and hand well off. Turn well over to production.

Wellbore schematics attached





Conditions of Approval

Yates Petroleum Corporation Arrow ARW Federal Com 1 API 3001528898, T19S-R25E, Sec 11

November 28, 2012

- 1. The communization agreement for this well (NM100705) does not include the Wolfcamp pay. Amendments to that agreement may be necessary. Check For: A new "Well Location and Acreage Dedication Plat" (NMOCD Form C-102) is required with the notice of intent package when opening another pay zone.
- 2. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 3. Subject to like approval by the New Mexico Oil Conservation Division.
- 4. Notify BLM 575-200-7902 before plug back procedures. The procedures are to be witnessed. If no answer, leave a voice mail with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 5. Surface disturbance beyond the existing pad must have prior approval.
- 6. A closed loop system is required. The operator shall properly dispose of drilling/circulating contents at an authorized disposal site. Tanks are required for all operations, no excavated pits.
- 7. Functional H₂S monitoring equipment shall be on location.
- 8. A minimum of 3000 (3M) BOPE shall be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M) Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. All waste (i.e. trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 10. The BLM PET witness is to run the tally and agree to cement placement. Sample each plug for cement curing time and tag and/or pressure test (WOC time of 4 hours recommended) as requested by BLM PET witness.

- 11. Class H > 7500ft & C < 7500ft) cement plugs(s) will be necessary. The minimum pumped volume of 25 sacks of cement slurry is to exceed a 100ft cement plug across the drilled wellbore. Add 10% to the 100ft slurry volume for each 1000ft of plug depth when calculations indicate the need. For any plug that requires a tag or pressure test a minimum WOC time of 4 hours(C) & 8 hours(H) is recommended. Formation isolation plugs of Class "C" to be mixed 14.8#/gal, 1.32 ft³/sx, 6.3gal/sx water and "H" to be mixed 15.6#/gal, 1.18ft³/sx, 5.2gal/sx water.
- 12. Step 3 Set a balanced (25sx minimum) Class "H" plug on the CIBP to be set at 7632. Tag this plug with tubing at 7452 or higher, covering the Canyon formation top.
- 13. Provide BLM with an electronic copy (Adobe Acrobat Document) cement bond log record from 6500 or below to top of cement. The CBL may be attached to a pswartz@blm.gov email.
- 14. Minimum requirement for mud placed between plugs is 25 sacks of salt water gel per 100 barrels in 9 lb/gal brine.
- 15. Cover the DV Tool (7008) with a balanced cement plug (25sx minimum) set at 7058. Tag this plug at 6942 or higher.
- 16. After setting the top plug and before perforating, perform a BLM PET witnessed (charted) casing integrity test of 700 psig. Pressure leakoff may require correction for approval. Include a copy of the chart in the subsequent sundry for this workover.
- 17. File intermediate **subsequent sundry** Form 3160-5 within 30 days of any interrupted workover procedures and a complete workover subsequent sundry.
- 18. Submit C-102 with BLM Form 3160-4 Recompletion Report within 30 days of the date all BLM approved procedures are complete.
- 19. Review Comm Agreement requirements.

Access information for use of Form 3160-5 "Sundry Notices and Reports on Wells"

NM Fed Regs & Forms - http://www.blm.gov/nm/st/en/prog/energy/oil and gas.html

§ 43 CFR 3162.3-2 Subsequent Well Operations.

§ 43 CFR 3160.0-9 (c)(1) Information collection.

§ 3162.4-1 (c) Well records and reports.