
Submit I Copy To Appropriate District	State of New Me	exico	Form C-103			
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised Angust 1, 2011			
1625 N. French Dr., Hobbs, NM-88240 District II - (575) 748-1283			WELL API NO.			
811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-00464 5. Indicate Type of Lease			
District III - (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE S FEE			
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87	7505	6. State Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM 87505		B3635				
	TICES AND REPORTS ON WELLS	ongong programatifikasi vi kuru programatin kangan artin disebut di kurun di anggan terbesia di di antah di di Li k	7. Lease Name or Unit Agreement Name			
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			GULF KEPPLE			
1. Type of Well: Oil Well Gas Well Other			8. Well Number 1			
2. Name of Operator	9. OGRID Number					
Alamo Permian Resources, LLC			274841			
3. Address of Operator 415 W. Wall Street, Suite 500, Midland, TX 79701			10. Pool name or Wildcat LOGAN DRAW; SA			
4. Well Location	LOOM STORY, SA					
	feat from the S. line and 27	110 Faat Grain	tha Éc lina			
Unit Letter J : 1980 feet from the S line and 2210 feet from the E line Section 19 Township 17S Range 27E NMPM County EDDY						
Section 19 Tow	nship 17S Range 27E 11. Elevation (Show whether DR)					
The state of the state of	Tr. Bievación (Bristo Arterior BA)	, AAD, AT, OA, etc)			
12. Check	Appropriate Box to Indicate N	lature of Notice	Report or Other Data			
그는 사람들은 사람들이 되었다. 그는 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은						
NOTICE OF I	BSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK [TEMPORARILY ABANDON [] PLUG AND ABANDON ⊠] CHANGE PLANS □	REMEDIAL WOI	RK ☐ ALTERING CASING ☐ ☐ RILLING OPNS.☐ P AND A ☐			
PULL OR ALTER CASING		CASING/CEMEN				
DOWNHOLE COMMINGLE		0, 10, 10, 02, 11, 11	tund			
·						
OTHER:	. []	OTHER:				
13. Describe proposed or con	pleted operations. (Clearly state all	ם ח pertinent details, a	nd give pertinent dates, including estimated date			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of						
proposed completion or re	ecompletion,					
See Attached.			RECEIVED			
See Attached.	Note	OCD 24 hrs. Y work don	1444 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0			
	Molity C	OCD 24 L	" JAN 0 9 2013			
	To an	V Wand Mrs.	Prior AMAGOD ADTON			
		y work don	NMOCD ARTESIA			
		- '				
	1					
Spud Date:	Rig Release Da	ate:				
<u> </u>						
Thereby certify that the informatio	n above is true and complete to the b	est of my knowled	ge and belief.			
SIGNATURE ON O STATLE Regulatory Affairs Coordinator DATE 1/09/2013						
Type or print name CARIE ST	OKER E-mail address: cstoker	@helmsoil.com	PHONE: 432.664.7659			
A)	The same		DITT 1/14/2013			
APPROVED BY: You Conditions of Approval (if any):	autei TITLE		DATE 1/14/2013			
Conditions of Approval (it any):			,			
i i	i de la companya de	Amazonal A	1 13			

Approval Granted providing work is complete by 4/14/2013

Proposed P&A Procedure

- Notify NMOCD 24 hours prior to pulling unit RU.
- Have open top frac tank on location and a 20 lb. bag of sugar in case of circulation.
- RU pulling unit, install a 2M BOP and TIH with tubing to 1835' (TD).
- Circulate hole with clean FW.
- Spot a neat Class C cement plug in open hole (1304' to 1835') up to 1200'.
- PUH and WOC for 4 hrs.
- Tag cement plug at 1200' or shallower.
- POOH filling 7" casing with neat Class C cement to 100'.
- MIRU Wireline and shoot 4 perforations at 75. 125'
- Open all annuli valves, RIH with packer and set at 40′, and try to establish a rate for cement circulation. If circulation is established then pump cement until it comes out each annulus valve.
- POOH filling casing with cement to surface.
- Remove BOP.
- Get approval from NMOCD before RD pulling unit.
- Notify NMOCD 4 Hours prior to wellhead cut off. (Wellhead should be cut off within 10 days of plugging job)
- Cut off wellhead and install a P&A marker.
- Reclaim Location.



NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator	A lamo	Permiar	Resoure	-s, LLC
Well Nam	e & Number	: Gulf	Kepple	#/
API #:	30-0	15-0046	4	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- **6.** If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.

8. Cement Retainers may not be used.

- 9. Squeeze pressures not to exceed 500 psi., unless approval is given by NMOCD Plugging Supervisor.
- 10. Plugs may be combined after consulting with NMOCD P & A Supervisor.

11. Minimum WOC time for tag plugs will be 4 hrs.

Date: 1/14/2013