

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 10 2013

NMOCD ARTESIA

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company COG OPERATING LLC 229137 Contact Pat Ellis
Address 600 West Illinois Avenue, Midland, TX 79701 Telephone No. 432-230-0077
Facility Name Folk Federal B Facility Type Tank Battery



Surface Owner Federal Mineral Owner Lease No. (API#) 30-015-36862
Closest well

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	17	17S	29E					Eddy

Latitude 32 50.183 Longitude 104 5.516

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	90bbls Oil 100bbls Produced water	Volume Recovered	70bbls Oil 80bbls Produced Water
Source of Release	Heater treater	Date and Hour of Occurrence	12/30/2012	Date and Hour of Discovery	12/30/2012 4:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD Jim Amos-BLM Terry Gregston-BLM		
By Whom?	Michelle Mullins	Date and Hour	12/31/2012 9:30 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
The fire-tube gasket malfunctioned on the heater treater and caused the release of fluid. The heater treater has been repaired and returned to service.					
Describe Area Affected and Cleanup Action Taken.*					
Initially 190bbls were released from the heater treater at the facility and we were able to recover 150bbls with a vacuum truck. The majority of the release was contained inside the lined facility. There was some overspray from the release in the adjacent pasture area outside of the facility berm. The facility has been returned to its prior condition. Tetra Tech will sample the release area outside of the lined facility to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD/BLM for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: 		OIL CONSERVATION DIVISION			
Printed Name: Josh Russo		Approved by District Supervisor: Signed By 			
Title: Senior Environmental Coordinator		Approval Date: JAN 18 2013		Expiration Date:	
E-mail Address: jrusso@concho.com		Conditions of Approval:		Attached <input type="checkbox"/>	
Date: 01/10/2013 Phone: 432-212-2399		Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION PROPOSAL NO LATER THAN: February 18, 2013		2RP-1506	

* Attach Additional Sheets If Necessary