

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

FEB 08 2013

Form C-141
Revised October 10, 2003

NMOCD ARTESIA

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW 1303948269

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company	COG OPERATING LLC 229137	Contact	Pat Ellis
Address	600 West Illinois Avenue, Midland, TX 79701	Telephone No.	432-230-0077
Facility Name	SRO SWD #101	Facility Type	SWD

Surface Owner	State	Mineral Owner		Lease No. (API#)	30-015-26105
---------------	-------	---------------	--	------------------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	5	26S	28E					Eddy

Latitude 32 04.387 Longitude 104 06.437

NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	25bbbs	Volume Recovered	20bbbs
Source of Release	4" Victaulic clamp	Date and Hour of Occurrence	01/26/2013	Date and Hour of Discovery	01/26/2013 9:00 p.m.
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-OCD		
By Whom?	Michelle Mullins	Date and Hour	01/28/2013 5:29 a.m.		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*


A 4" Victaulic clamp failed inside the facility allowing the release of produced water. The 4" Victaulic clamp has been replaced and returned to service.

Describe Area Affected and Cleanup Action Taken.*

Initially 25bbbs of produced fluid were released from the faulty 4" Victaulic clamp and we were able to recover 20bbbs with a vacuum truck. The spill was completely contained inside the lined facility walls. All free fluid has been recovered. Any contaminated gravel has been removed, the liner has been steam cleaned, and we have replaced with fresh gravel as necessary. This facility has been returned to its prior condition.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:



Printed Name: Josh Russo

Title: Senior Environmental Coordinator

E-mail Address: jrusso@concho.com

Date: 02/08/2013 Phone: 432-212-2399

OIL CONSERVATION DIVISION

Approved by District Supervisor:

Signed By



Approval Date: FEB 08 2013

Expiration Date:

Conditions of Approval:

Attached ☐

* Attach Additional Sheets If Necessary

2RP-1549

Accepted for record
NMOCD