Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned_well._Use Form 3160 - 3 (APD) for such proposals.

NM 25365 6. If Indian, Allottee or Tribe Name


and the second s			Anna Carlo C				
SUBMIT IN TRIPLICATE- Other instructions on reverse side.						7. If Unit	or CA/Agreement, Name and/or No.
1. Type of Well Gas Well Wither Injection						Vame and No.	
2. Name of Operator OXY USA Inc.		16696				Well 9. APIV	Federal #3
3a. Address P.O. Box 50250 Midland, TX 79710		3b. Phone No. (include area code) 432-685-5717 :					on Solution of Exploratory Area
4. Location of Well (Footage, Sec.,	tion)			•	Living	eston Riche Velaware	
430 FNL 760 F	nc manac) Sec 25	5 Taz	s R	SIE	11. Count	ly or Parish, State
12. CHECK AI	PROPRIATE BOX(ES)	TO INDICATE	NATURE C	OF NO	TICE, I	REPORT, C	OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent Subsequent Report Final Abandonment Notice	Change Plans Plug and Abandon Temporarily Abandon						Water Shut-Off Well Integrity Wother Replace PKR, Run MIT
If the proposal is to deepen dire Attach the Bond under which the following completion of the invitesting has been completed. Find determined that the site is ready Provide RECEIVE FEB 12 2013 MMOCD ARTES	ctionally or recomplete horizone work will be performed of folved operations. If the operation Abandonment Notices shart for final inspection.)	ontally, give subsurfar provide the Bond No ation results in a multill be filed only after a see ATTAC	ce locations and on file with B iple completion. Il requirements	d measus BLM/Bi nor reconst, include	ared and to A. Requi	nuc vertical de red subsequer in a new inter nation, have b	work and approximate duration thereof. pths of all pertinent markers and zones. It reports shall be filed within 30 days eval, a Form 3160-4 shall be filed once been completed, and the operator has TED FOR RECORD FEB 9 2013 J OF LAND MANAGEMENT RESBAD FIELD OFFICE
14. Thereby certify that the fore Name (Printed/Typed) David Stewart	going is true and correct		Title Regul	atory	Advisor		
Signature .	and the second		Date	ιI	30	13	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
			m:.1				D. (
Approved by Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon				Title Date Office			Date
mid 10 TT 0 0 0 11 1001 1 TT	10 110 0 0 1 1010				1 1110		Cd 77 '- 1

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to anymatter within its jurisdiction.



Date Remarks

- 11/26/12 MIRU WSU. RU Renegade WL & TIH w/ 1.78 Plug set. TOH RD WL. NDWH, PU 2' Tbg sub & Set more compression on Pkr. (18 pts on pkr.). SITP was 500 psi. Tested Casing to 720 psi. Charted for 30 min Lost 10 psi in first 10 min & Stabilized Did not loose any more pressure in 20 min. Bled down Csg to 250 PSI run Chart for 30 min Did not loose any or gain pressure. Closed in & Left 250 Psi on csg
- 11/27/12 SITP- 0 psi, SICP- 275 psi (Gained 25 psi over night). Bled csg off. PU on tbg & tbg started to flow, set back down, flow stopped. Put pressure gauge in tbg, PU on tbg, Check pressure 400 psi. Flowed back 10 bbls Close in Preesured up to 400 psi. Set tbg back down Flow shut off & Pressure bled off. RU WL & TIH Pull Blanking plug. Had 400 psi on tbg.
- 11/28/12 SITP- 460 psi. Test Csg to 700 psi held 30 min. Bled off & test again to 700 psi lost 40 psi in 30 min. Since we can't get Pkr to consistently test, going to pull pkr. WO WL, RU TIH Blanking plug.
- 11/29/12 SITP- 460 psi. ND WH, PU on Tbg, did not try to flow. NU BOPE. Un Jay on-off tool. Circ hole w/ 12# mud. Latch on-off tool back onto pkr, release pkr. LD 1- jt Tbg. RU Renegade & TIH Fish Plug. TOH W/ plug & RD WL. TOH w/ 2 7/8" Composite Lined tbg (Stand back in derrick on Rubber mats w/ thread protectors). LD pkr. TIH W/ RTBP & 2 7/8" L80 WS tbg. Set RTBP 5555'.
- 11/30/12 Circ Mud out of hole. Test casing to 540 psi. Gained 5 psi in 30 Min. Test Csg to 780 psi. Gained 20 Psi in 30 min.
- 12/1/12 Sent out trk to run chart in the morn. Test to 630 psi lost 10 psi in 30 min.
- 12/3/12 RU Kill Trk with Different Chart recorder. Test csg to 560 psi for 1 hr. Lost 10 psi. ND Kill Trk & Circ 12# mud. Latch on to RTBP & Release TOH W/ Tbg & RTBP. PU Arrowset x-1 Inj Pkr w/ Pump out plug in Place. & TIH w/ WS Tbg set pkr @ 5555'. Lay down 1- jt.
- 12/4/12 TOH.Laying Down Workstring tbg. TIH w/ On-Off tool & 2 7/8" Composite Lined tbg. Circ mud out of hole w/ Packer fluid.
- 12/5/12 ND BOPE & Latch on pkr ND Well head W/ 18 pts Compression on pkr. Pump ot Plug @ 3800 psi. CITP-830 psi. Test csg to 615 psi for 1- hr did not loose any pressure. Called Richard Inge with the OCD He gave permission to run MIT Test today since we were rigged up on Well. Test csg to 620 psi for 30 min. Did not loose any pressure. RD PU, Turned well over to pumper to put back on inj.



Cuatro Transportation, inc.

DATE RAC NOTIFIED 12-5-12

DATE TESTED 12-5-12

TBG PSI 230psi CSG PSI 620

Mile Kischwich 5 Urfa (e (sg - Opsi

Richard Inge w/ the OCD SAVE

Permission to Run Chapet Since we had

125-12 @ 10:36 Am