Form 3160-5 (August 2007)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT FEB 26 2013

FORM APPROVED
OMB No. 1004-013
Evniron: July 21, 201

5. Lease Serial No. NM NM 58034

6. If Indian, Allottee or Tribe Name

SUNDRY	NOTICES AND	REPORTS ON	WELCE	ARTESIA
Do not use this	form for propo	sals to drill or	to re-ent	er an
ahandoned well	lise Form 316	0-3 (APD) for s	such prop	neale

abandoned well. Use Form 3160-3 (APD) for such proposals.								
SUBMIT IN TRIPLICATE – Other instructions on page 2.				7. If Unit of CA/Agreement, Name and/or No.				
1. Type of Well			Half-rood and room in the control		0.117.11.21			
✓ Oil Well ☐ Gas Well ☐ Other			8. Well Name and No. Pecos Federal # 4					
2. Name of Operator RKI Exploration & Production					9. API Well No. 30-015-25436			
3a. Address 3b. Phone No. (include area code)			de)	10. Field and Pool or Exploratory Area				
210 Park Ave Suite 900 Oklahoma City, OK 73102 405-996-5771, 405-996-5772			2	Brushy Draw-Delaware East				
4. Location of Well (Footage, Sec., T., R.,	M., or Survey Description	i)			11. Country or Parish, State			
Sec 27 T26S R29E SESW 860FSL 2180FWL				Eddy County, NM				
12. CHECK	THE APPROPRIATE BO	OX(ES) TO INDI	CATE NATURI	E OF NOTIC	E, REPORT OR OTHI	ER DATA		
TYPE OF SUBMISSION			TY	PE OF ACTI	ON			
✓ Notice of Intent	Acidize		Deepen Produ		uction (Start/Resume) Water Shut-Off		•	
	Alter Casing	Fractu	re Treat	Recla	mation	Well Integrity		
Subsequent Report	Casing Repair New Construction Re		Recor	nplete	Other			
Subsequent report	Change Plans	✓ Plug a	nd Abandon	Temp	orarily Abandon	Drilling Operation	on .	
Final Abandonment Notice	Convert to Injection	Plug E	ack	☐ Water	Disposal			
testing has been completed. Final Ab determined that the site is ready for fi 01-09-13 - RIH, partedf casing @ 359/01-10-13 - pump 100 sks @ 2203 disp 01-11-13 - RIH, tag plug @3537, 01-17-13 - lay down 3525' of 4-1/2 cas 01-18-13 - RIH tag @ 3470', pump 10 tag 01-21-13 - circ 35 sks of salt gel @ 26 01-22-13 - Talk to TRRC RIH, to 614' circulate 70 sks of cmt to surface.	inal inspection.) 2' place to 3500' sing, RIH, to 3617' pump 0 sks of salt gel , pump 97', shoot perfs @ 550' circ 10 sks @ salt gel p	p 40 sks displac 70 sks @ 2907'	e to 3470' displace to 26 splace to 244'	S55', WOC F ', pressure u Ac	lH tag @ 2697', pres p to 500 psi, RIH, tag	ssure up to 500psi good te g @ 225' shoot perfs @ 60 ing of the well hore, is retained until	est, good	
14. I hereby certify that the foregoing is true Robert Hold Signature	/prl	-	Date		-8-130	TED FOR AFT	NAC N	
	THIS SPACE	FUR FEDER	KAL OR ST	A IE OFF	ICE USE	· or · · · · · · ·		
Approved by Conditions of approval, if any, are attached, that the applicant holds legal or equitable title entitle the applicant to conduct operations the Title 18 U.S.C. Section 1001 and Title 43	e to those rights in the subjection. S.C. Section 1212, make it a	ct lease which wou	old; Office.	nd willfully to		DefteEB 2.3 2013	s any false,	