Form 3160-5 (August 3007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135

7-	Expires.	July
Lease	Serial No.	
IMALA	C050365	

Do not use this form for proposals to drill or to re-drief an OCD ARTES!

If Indian, Allottee or Tribe Name abandoned well. Use form 3160-3 (APD) for such proposals. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side. NMNM68294X Well Name and No. BIG EDDY UNIT 151 1. Type of Well ☑ Oil Well ☐ Gas Well ☐ Other Name of Operator TRACIE J CHERRY API Well No. Contact: BOPCO LP 30-015-33157 E-Mail: ticherry@basspet.com 3a. Address 3b. Phone No. (include area code) 10. Field and Pool, or Exploratory P O BOX 2760 Ph: 432-221-7379 CARLSBAD, EAST (STRAWN) MIDLAND, TX 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, and State Sec 30 T21S R28E SENE 1650FNL 990FEL EDDY COUNTY COUNTY, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize □ Deepen ☐ Production (Start/Resume) ■ Water Shut-Off Notice of Intent ■ Alter Casing ☐ Fracture Treat ☐ Reclamation ■ Well Integrity ■ Subsequent Report Casing Repair ■ New Construction Recomplete □ Other ☐ Final Abandonment Notice □ Change Plans ☐ Plug and Abandon □ Temporarily Abandon ■ Convert to Injection □ Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Accepted for record BOPCO, LP respectfully requests approval to recomplete and fracture stimulate the referenced well. The existing Morrow and Strawn perforations will be abandoned and the Wolfcamp formation will be perforated, acidized and fracture stimulated. Tracers will be injected into frac fluid during each stage to track proppant. All depths correlated to SLB GR/CCL dated 11-09-06. Procedure is as follows: 1. MIRU workover unit. Bleed off any pressure. NU SEE ATTACHED FOR CONDITIONS OF APPROVAL 2. POH with pkr and LD 2-3/8 tbg. ND BOP. FEB 2 2 2013 3. MIRU wireline and crane. RU lubricator and wireline BOP. RIH w/10K CIBP, set @ 11625 on top of Is/ Chris Walls pkr @11625. RIH w/tbg and tag. Spot 176 sx Class H cmt to 10550. WOC & tag. BUREAU OF LAND MANAGEMENT 14. I hereby certify that the foregoing is true and correct Electronic Submission #198915 verified by the BLM Well Information System For BOPCO LP, sent to the Carlsbad Committed to AFMSS for processing by KURT SIMMONS on 02/19/2013 () Name(Printed/Typed) TRACIE J CHERRY Title REGULATORY ANALYST (Electronic Submission) Signature Date 02/14/2013 THIS SPACE FOR FEDERAL OR STATE OFFICE USE Date Approved By Title. Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

## Additional data for EC transaction #198915 that would not fit on the form

## 32. Additional remarks, continued

- 4. Pressure test 5-1/2 csg and plug to 8500 psi. Load hole w/KCL and hang off tbg until frac date.
- 5. MIRU. Spot 7.5% HCL across proposed perf interval
- 6. RIH GR/CCL tool, log from PBTD @ 10515.
- 7. Perf 1st set of Wolfcamp perfs 10223 10388 w/3-1/8 csg guns in 4 clusters (6 SPF, 48 holes total). Break down perfs at a rate 3-4 bpm, displace acid into perfs. Frac down csg w/149808 bbls fluid & 103000# propant at a max pressure of 7500 psi at 80 BPM. RIH w/5-1/2 composite plug, set @ 10190. Close rams, test csg and plug to 5000 psi. Spot 1000 gals 7.5% acid across next perf interval.
- 8. Perf 2nd set of Wolfcamp perfs 10048 10110 w/3-1/8 csg guns in 4 clusters (6 SPF, 48 holes total). Break down perfs at a rate 3-4 bpm and displace acid into perfs. Frac down 5-1/2 csg w/149514 bbls fluid & 103000# propant at a max pressure of 7500 psi at 80 BPM. RIH w/5-1/2 composit plug, set @ 9970. Close rams, test csg and plug to 5000 psi. Spot 1000 gals 7.5% acid across next perf interval.
- 9. Perf 3rd set of Wolfcamp perfs 9754 9886 w/3-1/8 csg guns in 4 clusters (6 SPF, 48 holes total). Break down perfs at a rate 3-4 bpm and displace acid into perfs. Frac down 5-1/2 csg w/149514 bbls fluid & 103000# propant at a max pressure of 7500 psi at 80 BPM. RIH w/5-1/2 composit plug, set @ 9970. Close rams, test csg and plug to 5000 psi.
- 10. RD Frac crew. NU 10K BOP on 7-1/16 tbg head. RIH w/coil tbg. Wash and cleanout sand through perfs. Drill out CBPs to last plug at 10450 (do not drill out last plug). RIH w/ spectral GR on wireline. Log across perfed interval.
- 11. RIH w/reconditioned 5-1/2 Baker Hornet 10K pkr on wireline. Set @ 9700. RIH w/2-7/8 L80 prod tbg. latch on to pkr, land tbg. Pump out plug and open well to flow back tanks.
- 12. RDMO

## Big Eddy Unit 151 30-015-33157 BOPCO LP Conditions of Approval

- 1. Surface disturbance beyond the originally approved pad must have prior approval.
- 2. Closed loop system required.
- 3. 10,000 (10M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 4. Operator to have H2S monitoring equipment on location as H2S has been reported from wells in the area.
- 5. Completion report and subsequent sundry with well test and wellbore schematic required.
- 6. The proposed well is not within a participating area. A commercial well determination must be submitted to the BLM Carlsbad Office.

CRW 022213