

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED

MAR 28 2013

NMOC D ARTESIA

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

### Release Notification and Corrective Action

#### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd. 16696	Contact	CJ Summers
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216
Facility Name	Sand Dunes 34 Federal #2	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		Lease No.	NM 43744

#### LOCATION OF RELEASE

30-015-27239

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	34	23S	31E					Eddy

Latitude N 32.26192° Longitude W 103.75925°

#### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	20 bbls	Volume Recovered	0 bbls
Source of Release	Power failure at the transfer pump caused frac tank overflow	Date and Hour of Occurrence	03/25/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Jennifer Van Curen, James Amos-BLM and Mike Bratcher-OCD		
By Whom?	Chancey Summers	Date and Hour	03/25/2013 @ 10:18 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Power failure at the transfer pump caused the frac tank to overflow and spill 20 bbls of produced water onto the ground. No fluids were recovered and power to the transfer pump was restored.

Describe Area Affected and Cleanup Action Taken.\*  
Power failure at the transfer pump caused the frac tank to overflow and spill 20 bbls of produced water onto the ground. No fluids were recovered and power to the transfer pump was restored. Remediation will be performed in accordance with an approved plan from the NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

#### OIL CONSERVATION DIVISION

Signature:	Approved by District Supervisor:	
Printed Name: Chancey Summers	Signed By: <i>Mike Bratcher</i>	
Title: HES Specialist	Approval Date: APR 10 2013	Expiration Date:
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 3-27-13	Phone: (575) 397-8216	

\* Attach Additional Sheets If Necessary

Remediation per OCD Rule &  
Guidelines. SUBMIT REMEDIATION

PROPOSAL NO LATER THAN:

May 10, 2013

2RP-1610