


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit this form to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

JMW 1307252124

Name of Company	Oxy Permian Ltd. 16696	Contact	CJ Summers	<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Address	1017 W. Stanolind Rd, Hobbs, NM	Telephone No.	(575) 397-8216		
Facility Name	Pure Gold A Federal #2 Battery	Facility Type	Gathering		
Surface Owner	BLM	Mineral Owner		Lease No.	NM 38464

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	21	23S	31E	660	South	330	West	Eddy

Latitude N 32.28428° Longitude W 103.79005

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	15 bbls	Volume Recovered	0 bbls
Source of Release	Tank overflow	Date and Hour of Occurrence	3/5/2013	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher- OCD; James Amos & Jennifer Van Curen- BLM		
By Whom?	Chancey Summers	Date and Hour	3/6/13 @ 3:40 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The loss of gas caused a tank overflow spilling 15 bbls of oil onto the ground. No fluids were recovered and the source of the release was corrected.

Describe Area Affected and Cleanup Action Taken.*

The area affected is approximately 40' x 90'. The loss of gas caused a tank overflow spilling 15 bbls of oil onto the ground. No fluids were recovered and the source of the release was corrected. Remediation will be performed in accordance with an OCD and BLM approved remediation plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Chancey Summers	Approved by District Supervisor:	Signed By: <i>Mike Bratcher</i>	
Title: HES Specialist	Approval Date: MAR 13 2013	Expiration Date:	
E-mail Address: Chancey.Summers@oxy.com	Conditions of Approval:	Attached <input type="checkbox"/>	
Date: 3-12-13	Phone: (575) 397-8216		

* Attach Additional Sheets If Necessary

Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION**

PROPOSAL NO LATER THAN:

April 13, 2013

2RP-1585