		OCD Arte	_					
	UNITED STATES PARTMENT OF THE IN UREAU OF LAND MANAG	OMB	FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010					
MAY 06 2013	5. Lease Serial No. NMLC068282	5. Lease Serial No. NMLC068282B						
Do not use this NMOCD A用语面的ied wer	6. If Indian, Allotte	6. If Indian, Allottee or Tribe Name						
SUBMIT IN TRI	7. If Unit or CA/Ag	7. If Unit or CA/Agreement, Name and/or No.						
Type of Well     Gas Well □ Oth		8. Well Name and No. GOLDEN SPUR WC 25 2H						
Name of Operator     CONOCOPHILLIPS COMPAN	9. API Well No. 30-015-41235	9. API Well No. 30-015-41235-00-X1						
3a. Address 400 PENBROOK SUITE 351 ODESSA, TX 79762		3b. Phone No. (include area code Ph: 432-688-6913	10. Field and Pool, RED HILLS	10. Field and Pool, or Exploratory RED HILLS				
4. Location of Well (Footage, Sec.; T	11. County or Paris	11. County or Parish, and State						
Sec 25 T26S R31E SESE 535	EDDY COUN	EDDY COUNTY, NM						
12. CHECK APPE	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, REPORT, OR OTH	ER DATA				
TYPE OF SUBMISSION	TYPE OF ACTION							
■ Notice of Intent	☐ Acidize	Deepen	☐ Production (Start/Resume)	■ Water Shut-Off				
<del>-</del>	☐ Alter Casing	☐ Fracture Treat	■ Reclamation	■ Well Integrity				
☐ Subsequent Report	□ Casing Repair	■ New Construction	■ Recomplete	☑ Other Change to Original A PD				
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon					
	Convert to Injection	Plug Back	■ Water Disposal					
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi	ally or recomplete horizontally, gind will be performed or provide the operations. If the operation resupports and on ment Notices shall be filed	ve subsurface locations and measure Bond No. on file with BLM/BI/ lts in a multiple completion or reco	ired and true vertical depths of all per A. Required subsequent reports shall completion in a new interval, a Form 3	tinent markers and zones. be filed within 30 days 160-4 shall be filed once				
We have experienced loss circ the 12 ?? hole section. Conoc	culation in Delaware Sands oPhillips respectfully reque	on HnP486 Golden spur W sts a change in our approve		5/6/2013				
ConocoPhillips is proposing to	pump 2 stage cement job	on 9 5/8? CSG with DV sta	ge Tool + ECP.	epted for record				
- 13 3/8? CSG cemented	d to surface and set at 1,04	Oft		NMOCD				
- While drilling 12 ?? lost returns around 4,274ft MD								
<ul> <li>Reducing MW from 10.</li> </ul>	- Reducing MW from 10.2ppg to 9.6ppg and pumped LCM Pill. Healed losses. Gained returns.							
- Planning to do a wiper	trip SEE ATTAC	HED FOR		MAY 3 2013				

SEE ATTACHED FOR

CONDITIONS OF APPROVAL					MA' L JOHNAGA		
14. I hereby certify that the foregoing is true and correct.  Electronic Submission #206075 verifie  For CONOCOPHILLIPS COM  Committed to AFMSS for processing by KU			e BLM Well Information Syste sent to the Carlsbad	m 5942SE)	BUREARISEAD FIELD OWNER		
Name(Printed/Typed)	SUSAN B MAUNDER	Title	SR. REGULATORY SPEC				
Signature	(Electronic Submission)	Date	05/03/2013				
THIS SPACE FOR FEDERAL OR STATE OFFICE USE							
Approved By EDWARD FERNANDEZ		TitleF	PETROLEUM ENGINEER		Date 05/03/2013		
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office	Carlsbad				
Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.							

\*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\* BLM REVISED \*\*

## Additional data for EC transaction #206075 that would not fit on the form

## 32. Additional remarks, continued

- Planning to Run open hole logs
- RIH 9 5/8? 40# L80 BTC Casing with the DV Tool and Casing Packer placed +/- 215ft above the weak zone @ 4,060ft
- Cement Job ? Stage #1 (5BPM): Pump 60bbl of fresh water and 60blls of polymer Ultra Seal Spacer (with LCM); pump 600ft of 14.8ppg Tail (204 sacks with 1.33 yield including 25% Excess) + KolSeal LCM
- Open DV tool, Circulate excess cement from the stage #1, Set ECP Packer;
- Cement Job Stage #2 (5BPM: Pump 10.5ppg 30bbl of gel spacer (No LCM to avoid plugging off DV tool ports) + 300ft 14.8ppg Tail (138 sacks with 1.33 yield including 50% Excess) + 12.9ppg lead (1246 sacks with 1.88 yield including 150% Excess) all the way to surface
- WOC 18hrs

We are planning to run CSG in hole tomorrow late afternoon and probably cement on Saturday morning. I appreciate your help on getting this sundry approved.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

## CONDITIONS OF APPROVAL

Sundry dated 05/03/2013

OPERATOR'S NAME: Conoco Phillips LEASE NO.: NMLC-068282B

WELL NAME & NO.: | Golden Spur WC 25 2H -3001541235

SURFACE HOLE FOOTAGE: 0535' FSL & 0965' FEL BOTTOM HOLE FOOTAGE 0330' FNL & 0330' FEL

LOCATION: | Section 25, T. 26 S., R 31 E., NMPM

**COUNTY:** | **Eddy County, New Mexico** 

## Original COA still applies with the following changes

1. The minimum required fill of cement behind the 9-5/8 inch intermediate casing is:

Operator has proposed DV tool at depth at approximately 3845' or 215 above weak zone at 4060', but will adjust cement proportionately if moved. The upper most tool (DV tool and /or Annulus Casing Packer and Stage Tool) shall be set a minimum of 50' below previous shoe.

- a. First stage to DV tool:
- □ Cement to circulate. If cement does not circulate, contact the appropriate BLM office before proceeding with second stage cement job. Operator should have plans as to how they will achieve circulation on the next stage Additional cement shall be required as excess calculates to 1%.
- b. Second stage above DV tool:
- Cement to surface. If cement does not circulate, contact the appropriate BLM office.

If operator is not able to establish cement circulation in either stage, then the operator shall run a CBL and submit to BLM. The operator shall also submit a copy of the service company cement report.

Formation below the 9-5/8" shoe to be tested according to Onshore Order 2.III.B.1.i. Test to be done as a mud equivalency test using the mud weight necessary for the pore pressure of the formation below the shoe (not the mud weight required to prevent dissolving the salt formation) and the mud weight for the bottom of the hole. Report results to BLM office.

EGF 050313