
			MAY	IVED	1		
						FORM APPROVED OMB NO. 1004-0135 Expires: July <u>31</u> , 2010	
SUNDRY NOTICES AND REPORTS ON WELLS					3. Lease Serial No. NMLC029342A		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well Gas Well Other					8. Well Name and No. WOOLLEY FEDERAL 001		
2. Name of Operator Contact: DAVID A EYLER COG OPERATING, LLC E-Mail: DEYLER@MILAGRO-RES.COM					9. API Well No. 30-015-04369		
3a. Address 600 W. ILLINOIS AVE. MIDLAND, TX 79701	3b. Phone No. (include area code Ph: 432-687-3033			e)	10. Field and Pool, or Exploratory LOCO HILLS ABO		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County		11. County or Parish,	ty or Parish, and State	
Sec 21 T17S R30E SWSW 6		EDDY COUNTY, NM		Y, NM			
	ROPRIATE BOX(ES) TO	) INDICAT			EPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
B Notice of Intent				_	tion (Start/Resume)	Water Shut-Off	
Subsequent Report	Casing Repair		cture Treat	C Reclam		Well Integrity	
G Final Abandonment Notice			New Construction B Plug and Abandon		arily Abandon	C Other	
	Convert to Injection		g Back				
following completion of the involve testing has been completed. Final A determined that the site is ready for 1) SET 5-1/2" CIBP @ 6,650' 2) CUT X PULL 5-1/2" CSG. 3) PUMP 60 SXS. CMT. @ 44 4) PUMP 50 SXS. CMT. @ 3, 5) PUMP 45 SXS. CMT. @ 2, 6) PUMP 80 SXS. CMT. @ 2, 6) PUMP 80 SXS. CMT. @ 2, 6) PUMP 80 SXS. CMT. @ 3, 8) MIX X CIRC. TO SURF. A 9) DIG OUT X CUT OFF WEI * fection 4840, S CCC C C C C C C C C C C C C C C C C C	bandonment Notices shall be file final inspection.) ; PUMP 25 SXS CMT. @ ( @ +/-4/000 <sup>4</sup> . 41/0 5 3 270°-2,030°(5-1/2°CSG.CU 235°-3,105°(T/SA.); WOC 300°-2,180°(T/QN.). 258'-1,035°(T/YATES X B/ 45'-412°(T/SALT X 13-3/8° 110 SX. CMT. PLUG @ 3 LIHEAD 3' B.G.L.; WELD GZ. CHT. PLUG @ 3 LIHEAD 3' B.G.L.; WELD GZ. CHT. + 0 4' b I c Mached Correct. Electronic Submission #1 For COG O Committed to AFMSS for EYLER	ed only after all 3,650'-6,490 T X 8-5/8°C X TAG. /SALT); WO CSG.SHOE 30'-3': ON STEEL 70 0	requirements, inclu ; CIRC.WELL W SG.SHOE); WO C X TAG. ; WOC X TAG. PLATE X INSTA C G L C . ; C by the BLM We	ILL DHM. C X TAG.	n, have been completed A A A A A A I D 3 - 3 95 RECLAMA A A A A A A A A A A A A A	and the operator has S TION PROCEDURE TTACHED FOR	
	THIS SPACE FO	R FEDER/	the second s		SE		
	00		l -	- 40		2-27-13	
Approved By Conditions of approval, if any, are attache certify that the applicant holds legal or eq which would excide the applicant to cond	ed. Approval of this notice does nitable title to those rights in the	not warrant or subject lease	Title SE	D D	· · · ·	Date	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a statements or representations as	crime for any j to any matter v	erson knowingly an vithin its jurisdiction	d willfully to m	ake to any department o	r agency of the United	
** OPERAT	FOR-SUBMITTED ** OI	PERATOR	SUBMITTED '	* OPERAT	OR-SUBMITTED	90	
			Accepted AM	tor Jacon BCD /	Bode 5/.	14/2013	

# COG Operating LLC



12/18/2012

Woolley Federal #1 Wellbore diagram.xls


SH

### COG Operating LLC

Lease & Well # Woolley Federal #1

SPUD - 6/4/60

Elevation - 3637'



C 1% S25, 5% sit. Survey TOC @ 5800'.

12/18/2012

Woolley Federal #1 Wellbore diagram.xls

DAE relializ

SĤ



## United States Department of the Interior

BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

#### **Reclamation Objectives and Procedures**

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

#### **Inspection & Enforcement**

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Mike Burton Environmental Protection Specialist 575-234-2226

Jeffery Robertson Natural Resource Specialist 575-234-2230

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Doug Hoag Civil Engineering Technician 575-234-5979

Linda Denniston Environmental Protection Specialist 575-234-5974

#### Realty, Compliance

Randy Pair Environmental Protection Specialist 575-234-6240

#### **Permitting**

Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Tanner Nygren Natural Resource Specialist 575-234-5975

Amanda Lynch Natural Resource Specialist 575-234-5922

Leg1on Brumley Environmental Protection Specialist 575-234-5957

### Requirements for ground level dry hole markers <u>Well Identification Markers</u> Conditions of Approval (COA)

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) Requires that ground level dry hole markers be placed on well within the Lesser Prairie Chicken habitat area.. The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. An 8 inch X 8 inch steel plate 1/8 to 3/16 of an inch thick is to be placed on the old dry hole marker stand pipe 2 inches from ground level, in the Lesser Prairie Chicken habitat area.
- 2. Steel plate may be welded or bolted approximately 2 inches from ground level on the stand pipes. If plates are bolted to the stand pipe, the person installing the plate will be required to weld a pipe collar on the plate and place a minimum of two set screws/bolt on each collar. Aluminum data plates may be bolted with minimum ¼ inch bolt and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
  - a. First row: Operators name
  - b. Second row: Well name and number
  - c. Third row: Legal location to include 1/4 1/4, Section, Township, and
  - range. If the legal location cannot be placed on one row it can be split into two rows with the 1/4 1/4 (example: 1980 FNL 1980 FWL) being on the top row.
  - d. Fourth row: Lease Number and API number.
    - i. Example marker plate: (attached)

NMOCD Order No. R-12965 also required the operator to notify NMOCD when this type of dry hole marker is used. This can be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a ground level dry hole marker was installed as required in the COA's from the BLM.