DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE - Other instructions on reverse side. 1. Type of Well ☐ Oil Well Gas Well Other 2. Name of Operator YATES PETROLEUM CORPORATIONE-Mail: tinah@yatespetroleum.com 3a. Address 105 SOUTH FOURTH STREET ARTESIA, NM 88210 3b. Phone No. (include area code) Ph: 575-748-4168 Fx: 575-748-4585 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				 Expires: July 31, 2010 5. Lease Serial No. NMNM100549 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. BLAST BLA FEDERAL 1 9. API Well No. 30-015-36136 10. Field and Pool, or Exploratory WILDCAT; WOLFCAMP 11. County or Parish, and State 	
Sec 17 T26S R27E NWSE 1980FSL 1650FEL MAY 13 2013				EDDY COUNTY, NM	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NOT BE OF NOTICE REPORT, OR OTHER DATA					
TYPE OF SUBMISSION					
 Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Oper If the proposal is to deepen directional 	 Acidize Alter Casing Casing Repair Change Plans Convert to Injection 	 Deepen Fracture Treat New Construction Plug and Abandon Plug Back tails, including estimated startic subsurface locations and measurements 	 Production (Start/Resume) Reclamation Recomplete Temporarily Abandon Water Disposal Ing date of any proposed work and approximation of any proposed work and approximation of any proposed work and period 		 Water Shut-Off Well Integrity Other
 Attach the Bond under which the wor following completion of the involved testing has been completed. Final At determined that the site is ready for final Yates Petroleum Corporation J MIRU any safety equipment Load hole as necessary with Set a CIBP at 12,044 ft and (134). Set packer at 9752 ft. Swa Pump 5000g 7-1/2 percent sealers spaced out evenly thro Flow well back until it clean Turn well over to production 	operations. If the operation results bandonment Notices shall be filed or inal inspection.) plans to plugback and recom that as needed. NU BOP. th treated water to POOH wit d cap with 35 ft of cement. P boughout the acid. Flush to the sup. n.	in a multiple completion or re nly after all requirements, inclu plete this well as follows: h tubing and packer. erforate Wolfcamp 10,00 2000 scf/bbl. Drop 75 1.	completion in a nuding reclamation : 2 ft - 10,122 ft 3 SG RCN bal	EE ATTACH CONDITIONS	50-4 shall be filed once and the operator has
14. I hereby certify that the foregoing is Name(<i>Printed/Typed</i>) TINA HUE	Electronic Submission #1986 For YATES PETROLE Committed to AFMSS for p	UM CORPORÁTION, sent rocessing by KURT SIMM	to the Carlsba	d 2013 ()	
Signature (Electronic S	ubmission)	Date 02/12/	2013	APPR	OVED
	THIS SPACE FOR	FEDERAL OR STATE	OFFICE US	SE	
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equival which would entitle the applicant to condu Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	itable title to those rights in the sub oct operations thereon. U.S.C. Section 1212, make it a crim	ject lease Office le for any person knowingly an		BUREAU OF LAND CARLSBAD FI	ELD OFFICE

Ŷ

•


** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Additional data for EC transaction #198616 that would not fit on the form


5

32. Additional remarks, continued

Wellbore schematics attached



, _{ј;} , , ,



L_____.

Blast BLA Federal 1 30-015-36136 Yates Petroleum Corporation May 07, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by August 07, 2013.

- 1. Set CIBP at 12,044' and place a 220' plug of neat class H cement on top. Tag at approximately 11,824'.
- 2. Must conduct a casing integrity test before any perforating can be done. Submit results to BLM. The CIT is to be performed on the production casing per Onshore Oil and Gas Order 2.III.B.1.h.
- 3. Make arrangements 24 hours before the test for BLM to witness. E-mail Paul R. Swartz <u>pswartz@blm.gov</u> or phone 575-200-7902, if there is no response, 575-361-2822. If no answer, leave a voice mail or email with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 4. Submit evidence to support your determination that the well has been returned to active "beneficial use" for BLM approval on the Sundry Notice Form 3160-5.
- 5. Should "beneficial use" not be achieved submit for BLM approval a plan for plug and abandonment
- 6. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 7. Surface disturbance beyond the originally approved pad must have prior approval.
- 8. Closed loop system required.
- 9. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.

- 10. Operator to have H2S monitoring equipment on location.
- 11. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 12. Submit subsequent sundry required detailing work done and completion report for the new formation. Operator to include well bore schematic of current well condition when work is complete.
- 13. Submit C-102 form with new formation.

JAM 050713