	L ED STATE DEPARTMENT OF THE BUREAU OF LAND MAN	INTERIOR	OCD Artesia	5. Lease Seria	FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007	
SUNDRY	NOTICES AND RE	PORTS ON WE	LLS	NM0560		
Do not use th	his form for proposals rell. Use Form 3160-3 (to drill or to re-e	enter an	6. If Indian	, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE- Other instructions on reverse side.				7. If Unit or	 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. LANDRUSH "12" FED. COM #2 9. API Well No. 3001531903 10. Field and Pool, or Exploratory Area WOLFCAMP 	
Oil Well□ □ ✓ Gas Well□□ Cther						
2. Name of Operator CHI OPERATING, INC			9. API We			
3a. Address 3b. Phone No. (include area code) P.O. BOX 1799, MIDLAND, TEXAS 79702 432-685-5001			10. Field an			
4. Location of Well (Footage, Sec.,	T., R., M., or Survey Description)		,			
660' FNL & 660' FEL N-12-T19S-R30E				EDDY	or Parish, State	
12. CHECK A	PPROPRIATE BOX(ES) TO) INDICATE NATUI	RE OF NOTICE,	REPORT, OR	COTHER DATA	
TYPE OF SUBMISSION		TY	PE OF ACTION			
Subsequent Report	Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction Plug and Abandon	Production Reclamation Recomplete		Water Shut-Off Well Integrity	
Final Abandonment Notice	Convert to Injection	V Plug Back	Water Dispo	osal .		
	inal Abandonment Notices shall be	results in a multiple com			II, a Form 3160-4 shall be filed one on completed, and the operator has	
testing has been completed. F determined that the site is read PLUG BACK FROM MC MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst	inal Abandonment Notices shall be	n results in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H	oletion or recomplet ments, including rec t good. Perf Wolf	camp, 2spf, 88 h	n completed, and the operator has oles, f/9986-10,030'. Set pkr @	
testing has been completed. F determined that the site is read PLUG BACK FROM MC MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst	inal Abandonment Notices shall be y for final inspection.) DRROW TO WOLFCAMP: set @ 11,71'0', cap w/3sx cmt, good. Acidize Wolfcamp perf	n results in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H	oletion or recomplet ments, including red t good. Perf Wolf CL w/Iron contro	camp, 2spf, 88 h r fro 10,000ppm.	n completed, and the operator has oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr	
testing has been completed. F determined that the site is read PLUG BACK FROM MC MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst	inal Abandonment Notices shall be y for final inspection.) DRROW TO WOLFCAMP: set @ 11,71'0', cap w/3sx cmt, good. Acidize Wolfcamp perf	n results in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H	oletion or recomplet ments, including red t good. Perf Wolf CL w/Iron contro	camp, 2spf, 88 h r fro 10,000ppm.	n completed, and the operator has oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr	
testing has been completed. F determined that the site is read PLUG BACK FROM MC MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst TIH w/Prod String. NU V	inal Abandonment Notices shall be by for final inspection.) DRROW TO WOLFCAMP: set @ 11,110', cap w/3sx cmt, good. Acidize Wolfcamp perf WH, RD PU. 8-22-06 hang wel	n results in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H l on pump.	oletion or recomplet ments, including red t good. Perf Wolf CL w/Iron contro	camp, 2spf, 88 h r fro 10,000ppm.	n completed, and the operator has oles, f/9986-10,030'. Set pkr @	
testing has been completed. F determined that the site is read PLUG BACK FROM MG MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst TIH w/Prod String. NU V	inal Abandonment Notices shall be y for final inspection.) DRROW TO WOLFCAMP: set @ 11,11'0', cap w/3sx cmt, good. Acidize Wolfcamp performed WH, RD PU. 8-22-06 hang well WH, RD PU. 8-22-06 hang well CONTROL 5/24/75 CONTROL 5/24/75 CONTROL 5/24/75	n results in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H l on pump.	oletion or recomplet ments, including red t good. Perf Wolf CL w/Iron contro	camp, 2spf, 88 h r fro 10,000ppm.	n completed, and the operator has oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr	
testing has been completed. F determined that the site is read PLUG BACK FROM MG MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst TIH w/Prod String. NU V	inal Abandonment Notices shall be by for final inspection.) DRROW TO WOLFCAMP: set @ 11,110', cap w/3sx cmt, good. Acidize Wolfcamp perf WH, RD PU. 8-22-06 hang wel WH, RD PU. 8-22-06 hang wel CONTROL STATISTICS WM SCD DW MARCE WIT	n results in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H l on pump.	oletion or recomplet ments, including red t good. Perf Wolf CL w/Iron contro	camp, 2spf, 88 ht I fro 10,000ppm.	oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr OR RECORD 8 2013	
testing has been completed. F determined that the site is read PLUG BACK FROM MC MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst TIH w/Prod String. NU V DATE PRO duc MALL MC	inal Abandonment Notices shall be by for final inspection.) DRROW TO WOLFCAMP: set @ 11,110', cap w/3sx cmt, good. Acidize Wolfcamp perf WH, RD PU. 8-22-06 hang wel WH, RD PU. 8-22-06 hang wel CONTROL STATISTICS WM SCD DW MARCE WIT	n results in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H l on pump.	oletion or recomplet ments, including red t good. Perf Wolf CL w/Iron contro	camp, 2spf, 88 h I fro 10,000ppm. EPTED F MAY 1 IREAU OF LAN	oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr OR RECORD 8 2013 D MANAGEMENT	
testing has been completed. F determined that the site is read PLUG BACK FROM MG MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst TIH w/Prod String. NU V	inal Abandonment Notices shall be by for final inspection.) DRROW TO WOLFCAMP: set @ 11,110', cap w/3sx cmt, good. Acidize Wolfcamp perf WH, RD PU. 8-22-06 hang wel WH, RD PU. 8-22-06 hang wel CONTROL STATISTICS WM SCD DW MARCE WIT	n results in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H l on pump.	oletion or recomplet ments, including red t good. Perf Wolf CL w/Iron contro	camp, 2spf, 88 h I fro 10,000ppm. EPTED F MAY 1 IREAU OF LAN CARLSBAD F	oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr OR RECORD 8 2013	
testing has been completed. F determined that the site is read PLUG BACK FROM MG MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst TIH w/Prod String. NU V MANNA PTO CUCC MANNA PTO CUCCC MANNA PTO CUCC MANNA PTO CUCC MANNA PTO CUCC MANNA PTO CUCC MANNA PTO CUCC MANNA PTO CUCC MANNA PTO CUCCC MANNA PTO CUCC MANNA PTO CUCCCUCCUCCUCCUCCUCCUCCUCCUCCUCCUCUCUCUC	inal Abandonment Notices shall be by for final inspection.) DRROW TO WOLFCAMP: set @ 11,110', cap w/3sx cmt, good. Acidize Wolfcamp perf WH, RD PU. 8-22-06 hang wel WH, RD PU. 8-22-06 hang wel CONTROL STATISTICS WM SCD DW MARCE WIT	n results in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H l on pump.	oletion or recomplet ements, including rec t good. Perf Wolf CL w/Iron contro ACC	camp, 2spf, 88 h I fro 10,000ppm. EPTED F MAY 1 IREAU OF LAN CARLSBAD F	oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr OR RECORD 8 2013 D MANAGEMENT	
testing has been completed. F determined that the site is read PLUG BACK FROM MG MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst TIH w/Prod String. NU V MALL NO MALL NO 14. Thereby certify that the for Name (Printed/Typed) Dianna Be	inal Abandonment Notices shall be by for final inspection.) DRROW TO WOLFCAMP: set @ 11,110', cap w/3sx cmt, good. Acidize Wolfcamp perf WH, RD PU. 8-22-06 hang wel WH, RD PU. 8-22-06 hang wel CONTROL STATISTICS WM SCD DW MARCE WIT	n results in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H l on pump.	t good. Perf Wolf CL w/Iron contro ACC 9 8 8 8 8 9 8 9 8 9 8 9 8 9 8 9 8 9 8	camp, 2spf, 88 h I fro 10,000ppm. EPTED F MAY 1 IREAU OF LAN CARLSBAD F CLERK	oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr OR RECORD 8 2013 D MANAGEMENT	
testing has been completed. F determined that the site is read PLUG BACK FROM MC MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst TIH w/Prod String. NU V DANA Product MALL MC 14. I hereby certify that the for Name (Printed/Typed) Dianna Be Signature Manua Approved by Conditions of approval, if any, are	inal Abandonment Notices shall be by for final inspection.) DRROW TO WOLFCAMP: set @ 11,11'0', cap w/3sx cmt, good. Acidize Wolfcamp perf WH, RD PU. 8-22-06 hang wel 420 cele 5/24/75 CC Fried for record e NMOCD DM KARCE W/2 egoing is true and correct // BCC THIS SPACE FOR e attached. Approval of this notice	mesults in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H I on pump.	t good. Perf Wolf CL w/Iron contro ACC 9 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Camp, 2spf, 88 h fro 10,000ppm. EPTED F MAY 1 REAU OF LAN CARLSBAD F CEUSE	oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr OR RECORD 8 2013 D MANAGEMENT	
testing has been completed. F determined that the site is read PLUG BACK FROM MC MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst TIH w/Prod String. NU N NON PRODUC MALL IN COMMANDA IA. I hereby certify that the for Name (Printed/Typed) Dianna Be Signature Manua Approved by Conditions of approval, if any, arc certify that the applicant holds leg which would entitle the applicant	inal Abandonment Notices shall be by for final inspection.) DRROW TO WOLFCAMP: set @ 11,11'0', cap w/3sx cmt, good. Acidize Wolfcamp performed WH, RD PU. 8-22-06 hang well WH, RD PU. 8-20 hang well WH, RD	mesults in a multiple com e filed only after all require pressure tst t/1000#, ts s w/5000gal 15% IC H I on pump.	t good. Perf Wolf CL w/Iron contro ACC 9 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Camp, 2spf, 88 h fro 10,000ppm. EPTED F MAY 1 MAY 1 CARLSBAD F CLERK 3 CE USE	n completed, and the operator has oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr OR RECORD 8 2013 2013 2014 ID MANAGEMENT IELD OFFICE	
testing has been completed. F determined that the site is read PLUG BACK FROM MC MIRU PU, TIH w/CIBP, 9893', tst pkr t/1000#, tst TIH w/Prod String. NU V MAND PTO duc MAND PT	inal Abandonment Notices shall be by for final inspection.) DRROW TO WOLFCAMP: set @ 11,11'0', cap w/3sx cmt, good. Acidize Wolfcamp perf WH, RD PU. 8-22-06 hang wel 420 cele 5/24/75 certific for record e NMOCD DW KARCE W/2 egoing is true and correct HIS SPACE FOR e attached. Approval of this notic al or equitable title to those rights to conduct operations thereon. tle 43 U.S.C. Section 1212, make it	pressure tst t/1000#, ts s w/5000gal 15% IC H l on pump. FEDERAL OR S e does not warrant or in the subject lease a crime for any person h	t good. Perf Wolf CL w/Iron contro ACC 9 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	Camp, 2spf, 88 h fro 10,000ppm. EPTED F MAY 1 MAY 1 CARLSBAD F CLERK 3 CE USE	n completed, and the operator has oles, f/9986-10,030'. Set pkr @ Unset pkr, TOH w/tbg & pkr OR RECORD 8 2013 2013 2014 ID MANAGEMENT IELD OFFICE	

. .

•

.

· · · ·