Form 3160-5 (August 2007) UNITED STATES OCD Artesia DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					
				ottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				Agreement, Name and/or No.	
1. Type of Well Image: State of Well Image: State of Well Image: State of Well Image: State of Well				nd No. NT 965	
2. Name of Operator Contact: DENISE PINKERTON CHEVRON U.S.A. INC. E-Mail: leakejd@chevron.com			9. API Well No 30-015-34		
3a. Address 3b. Phone No. 15 SMITH ROAD Ph: 432-68 MIDLAND, TX 79705 Ph: 432-68			code) 10. Field and Po FREN	ool, or Exploratory	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. Countý or P	Parish, and State	
Sec 15 T17S R31E Mer NMP 990FSL 990FWL				UNTY, NM	
12. CHECK AP	PROPRIATE BOX(ES) TO) INDICATE NATURE	OF NOTICE, REPORT, OR O	THER DATA	
TYPE OF SUBMISSION		TYPE OF ACTION			
X Notice of Intent	🗖 Acidize	🗖 Deepen	Production (Start/Resun	ne) 🔲 Water Shut-Off	
Subsequent Report	☐ Alter Casing	S Fracture Treat	Reclamation	U Well Integrity	
Final Abandonment Notice	 Casing Repair Change Plans 	New Construction Plug and Abando	— 1	Other	
	Convert to Injection	Plug Back	Water Disposal		
Attach the Bond under which the w following completion of the involv- testing has been completed. Final <i>a</i> determined that the site is ready for CHEVRON U.S.A. INC. INTI	ork will be performed or provide ed operations. If the operation res Abandonment Notices shall be file final inspection.) ENDS TO FRACTURE STII THE INTENDED PROCED MOCD.	the Bond No. on file with BLN ults in a multiple completion o d only after all requirements, in MULATE THE SUBJECT URE, THE WELLBORE	neasured and true vertical depths of all //BIA. Required subsequent reports sl recompletion in a new interval, a For iccluding reclamation, have been comp WELL. DIAGRAM; AND THE C-144 Cl	all be filed within 30 days m 3160-4 shall be filed once leted, and the operator has	
CROOLE 5/24/13 Accepted for record MAY 202013 MOCD ARTESIA SEE ATTACHED FOR CONDITIONS OF APPROVAL					
14. I hereby certify that the foregoing is true and correct. Electronic Submission #204826 verified by the BLM Well Information System For CHEVRON U.S.A. INC., sent to the Carlsbad Committed to AFMSS for processing by Name(Printed/Typed) DENISE PINKERTON					
Signature (Electronic	Submission)	Date 04/	9/2013 APF	PROVED	
	THIS SPACE FO	R FEDERAL OR STA			
Approved By Conditions of approval, if any, are attach certify that the applicant holds legal or e which would entitle the applicant to cond Title 18 U.S.C. Section 1001 and Title 4 States any false, fictitious or fraudulen	quitable title to those rights in the duct operations thereon. 3 U.S.C. Section 1212, make it a c	subject lease Office	and willfully to make to any departm	1 6 2013 Date AND MANAGEMENT DATE I D OFFICE ent or agency of the United	
States any raise, nethous of fraudulen	contento or representations as	to any matter writin its jurisuit			

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **


Skelly Unit 965

الجب سندب

Paddock Frac Procedure

- 1. POH w/ rods, pump and tubing.
- 2. Set CBP at 5220'.
- 3. Perforate the Paddock formation from 5020-5198.5'.
- 4. Frac stimulate the Paddock formation w/ 102,000 gallons gelled water and 129,600# 16-30 sand.
- 5. Flow back load.
- 6. Drill out CBP.
- RIH w/ tubing, pump and rods.
 Return well to production.

Skelly Unit #965 Wellbore Diagram



6,120 - 6,320

Skelly Unit 965 30-015-34647 Chevron U.S.A. Inc. May 16, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by August 16, 2013.

1.1

- Must conduct a casing integrity test before any work can be done. Submit results to BLM. The CIT is to be performed on the 5-1/2" production casing per Onshore Oil and Gas Order 2.III.B.1.h. Make arrangements 24 hours before the test for BLM to witness. E-mail Paul R. Swartz <u>pswartz@blm.gov</u> or phone 575-200-7902, if there is no response, 575-361-2822. If no answer, leave a voice mail or email with the API#, workover purpose, and a call back phone number. Note the contact, time, & date in your subsequent report.
- 2. If CIT does not fail work is approved as proposed by operator.
- 3. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 4. Surface disturbance beyond the originally approved pad must have prior approval.
- 5. Closed loop system required.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Operator to have H2S monitoring equipment on location.

- 8. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 9. Subsequent sundry required detailing work done and completion report. Operator to include well bore schematic of current well condition when work is complete.

.

JAM 051613

x . • •