						Use Naver		
District I 1625 N. French Dr., Hobbs, NM 88240				New Mexico			$\mathcal{M} \xrightarrow{Form C-141}_{Revised March 17, 1999}$	
<u>District II</u> 1301 W. Grand Avenue, Artesia, NM 88210								
<u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410	Oil Conservation Division						Submit 2 Copies to appropriate District Office in accordance	
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	1220 South St. Francis Dr.						with Rule 116 on back side of form	
Iz20 S. St. Francis Dr., Santa Fe, NM 87505 Santa Fe, NM 87505 Side of form Release Notification and Corrective Action								
nJMW 1315429438 OPERATOR Initial Report Final Report								
Name of Company Devon Energy 6/37 Contact Daniel Suniga, Foreman								
Address P. O. Box 250				Telephone No.575-390-5850				
Artesia, NM 88211								
Facility Name Todd 22B Fed #2 30-015-32203			Facility Type Oil Well					
Surface Owner Mineral Owne				er Lease No.				
	יוחו	N OF RELEASE Includ			APT # *			
Unit Letter Section Township Range Fe			South Line	Feet from the	East/We		County	
B 22 23S 31E 51	0 ·· N	lorth		1980	East		Eddy County	
NATURE OF RELEASE								
				Release 70bbls	ls Volume Recovered 60bbls PW/ 5bbls Oil			
Source of Release 60 bbls of Produced Water, 5bbls of Oil							Date and Hour of Discovery 05/11/13, 10:00AM	
Was Immediate Notice Given?	ired	If YES, To Whom? BLM – Lorraine Chavez, OCD – Mike Bratcher						
By Whom? Wesley Ryan, Assistant Foreman		Date and Hour 05/13/2013, BLM 8:49AM, OCD 8:30AM						
Was a Watercourse Reached?				If YES, Volume Impacting the Watercourse.				
N/A						Ht		
						MAY 30 2013		
Describe Cause of Problem and Remedial Action Taken.*							CD ARTESIA	
(Spill Class II No-SIF) At the Todd 22B Fed #2 battery, a lease operator arrived to discover an open top vent tank running-over resulting in a spill-of 60bbls of produced water and 5bbls of oil.								
Describe Area Affected and Cleanup Action Taken.*								
(Spill Class II No-SIF) At the Todd 22B Fed #2 battery, a lease operator arrived to discover an open top vent tank running over resulting in a spill of								
60bbls of produced water and 5bbls of oil. After investigating the cause of the spill the operator discovered that some rubber had caused a back pressure valve on the separator to plug off, over pressure the separator and send all gas and fluid to the vent tank. The spill remained on the caliche location. A								
vacuum truck was called to pick as much fluid as possible. The truck was able to pick up 60bbls of produced water and 5bbls of oil. The total fluid lost was								
10bbls of produced water and 5bbls of oil.								
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger								
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other								
federal, state, or local laws and/or regulations.								
			OIL CONSERVATION DIVISION					
Signature: Orientica Ted								
Printed Name: Veronica Teel			Approved by District Supervisor Signed By Mille Benerice					
Title: Field Admin. Support			JUI pproval Date	0 3 2013	Exp	viration D	ate:	
Date: 05/13/13 Phone: (575) 748-9933		С	onditions of	Approval:			Attached	
Attach Additional Sheets If Necessary				ion per OCD			2RP-1671	
			Guidelines. SUBMIT REMEDIATION					
	- PROPOS	PROPOSAL NO LATER THAN: ULU 3, 2013						
	.•		min -	, min				

• •