Form 3160-5 (August 2C27) DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.				FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 5. Lease Serial No. NMNM048344 6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Ø Oil Well Other				8. Well Name and No. PIGLET 21 FEDERAL 12	
2. Name of Operator Contact: JENNIFER A DUARTE OXY USA WTP LP E-Mail: jennifer_duarte@oxy.com				9. API Well No. 30-015-40716	
3a. Address 3b. Phone No. (inc PO BOX 4294 Ph: 713-513-66 HOUSTON, TX 77210 Ph: 713-513-66)	10. Field and Pool, or Exploratory ARTESIAN; GLORIETA-YESO	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) Sec 21 T17S R28E NWNE 445FNL 1865FEL				11. County or Parish, and State EDDY COUNTY, NM	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA					
TYPE OF SUBMISSION	TYPE OF ACTION				
 Notice of Intent Subsequent Report Final Abandonment Notice 	Alter Casing Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction Plug and Abandon Plug Back	 Productio Reclamation Recompletion Temporar Water Discontrol 	ete ily Abandon	 Water Shut-Off Well Integrity Other
 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) 03/18/2013 ? RU SCHLUMBERGER WIRELINE MADE ONE CBL RUN, TAG TD @ 4677' WE LOGGED CBL FROM TD TO SURFACE @ 1000 PSI WITH A 300 FT REPEAT PASS OFF BOTTOM WITH NO PRESSURE, (NOTE: WE TAG 129' HIGHER THAN PBTD 4806' BOTTOM PERF IS 4719 - 4727.7' RESULTS: CEMENT IS OK RD WIRELINE. LOAD CASING MUITH 2 BBL FRESH WATER PRESSURE UP ON CASING TO 5500 PSI, HOLD PRESSURE TEST CASING AND RECORD RESULTS) WE PRESSURE (STATE AND FEDERAL REGULATIONS REQUIRE PRESSURE TEST CASING AND RECORD RESULTS) WE PRESSURE TEST CASING TO 1500 PSI RUN A CHART FOR 30 MINUTES WITH A GOOD TEST. 03/25/2013 & 03/26/2013 ? 1a:4719' - 4727.7' & 1b:4568' - 4576.7', 2a:4404.3' - 4413' & 2b. 4297.3', 3a:4073.3' - 4082 & 3b:3986 - 3994.7', 4a:3802' - 3810.7' & 4b:378.3' - 3737', 5a:36:43: a' 3652' & 56.3577' 3585.7', 5SPF (300 holes); 0.48' EHD. Frac with: Fluid - 111,024 gals Water Frac F-R (linear gel); 501,762 gals Hybor G - R (crosslinked gel); 9,500 gals 15% HCl. Sand - 19,999 bis 100 mesh; 901,911 lbs 16/30 brown SD 03/28/2013 ? MIRU CLEANOUT RIG. BEGIN AFTER FRAC CLEANOUT. 14. Thereby certify that the foregoing is true and correct.					
				0050777	
Signature (Electronic S		Date 05/23/20	i		OR RFCORD
THIS SPACE FOR FEDERAL OR STATE OFFICE USE					
Approved By Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to condu- thich would entitle the applicant to condu- Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	e Office y person knowingly and	willfully to make	BUREAU OF LAVE		
<u></u>					

** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED ** OPERATOR-SUBMITTED **

Additional data for EC transaction #208410 that would not fit on the form

32. Additional remarks, continued

04/01/2013 ? COMPLETE AFTER FRAC CLEANOUT TO PBTD. 04/02/2013 ? Run production equipment.