

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

RECEIVED
OIL CONSERVATION DIVISION
JUN 26 2013
1220 South St. Francis Dr.
Santa Fe, NM 87505
HOBBSOCD

WELL API NO. 30-015-02889
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name State
8. Well Number #2
9. OGRID Number 14070
10. Pool name or Wildcat Cave Pool GB/SA
11. Elevation (Show whether DR, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
State of New Mexico formerly Marks And Garner

3. Address of Operator
811 S. First Street Artesia, NM 88210

4. Well Location
Unit Letter C : 990 feet from the North line and 1980 feet from the West line
Section 4 Township 17S Range 29E NMPM Eddy County

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

5/24/2013 MIRU and lay down rods.
5/27/2013 Install BOP. Talley OOH and made scrapper run. Set CIBP at 2272'. Circulated hole with mud and spotted 25 sx cement on CIBP. POOH with tubing and perforated at 1650'. RIH with packer and pressured up on perfs. Would not take fluid. Released packer and spotted 25 sx cement at 1701'. POOH and SION.
5/28/2013 RIH and tagged at 1423'. POOH and perf at 331'. Pumped 105 sx cement down 4 1/2" casing to perfs and up annulus. No cement to surface. SION
5/29/2013 Cut off wellhead 1 inched annulus and filled ud 4 1/2" casing to surface. Installed marker and cut off anchors.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE _____ TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY [Signature] TITLE DIST. MGR DATE 6-26-2013

Conditions of Approval (if any):

JUN 26 2013