

Submit 1 Sopy To Appropriate District Office	State of New Mex		Form C-103
District 1 (575) 393-6161	Energy, Minerals and Natura	al Resources	Revised August 1, 2011 ELL API NO.
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> ÷ (575) 748-1283	bs, NM 88240 283 NM 88210 178 tec, NM 87410  DIL CONSERVATION DIVISION 1220 South St. Francis Dr. South Fo. NM 87505		P-015-21151
811 S. First St., Artesia, NM 88210		DIVISION $\frac{1}{5}$	Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE FEE X
District IV - (505) 476-3460	Santa Fe, NM 875	6.	State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			
SUNDRY NOTION (DO NOT USE THIS FORM FOR PROPOSE)	CES AND REPORTS ON WELLS	G BACK TECHAL	Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	CATION FOR PERMIT" (FORM C-101)	CI	ROW FLATS 16 STATE
	Gas Well X Other	≥ Ω 8. ∞ M	Well Number
2. Name of Operator	LORADO	<b>∞</b> − 000	OGRID Number
CIMAREX ENERGY CO. OF COL	LORADO		2683
3. Address of Operator	100		. Pool name or Wildcat
600 N. MARIENFELD, SUITE 600	J, MIDLAND, TEXAS 79701	A	TOKA GAS WILDCAT
4. Well Location			
,		ine and 1977 feet from	
Section 16		Range 28E	NMPM EDDY County
	11. Elevation (Show whether DR, a 3,568' - G	•	
किन्नकार से से स्वरंग । इसे हर्ने के किन्नकार के कार्य के किन्नकार के स्वरंग के किन्नकार के किन्नकार के किन्नक किन्नकार से से से किन्नकार के किन्नकार के किन्नकार के समस्य के किन्नकार के किन्नकार के किन्नकार के किन्नकार के	3,300 G		(2) 数据的证明 (2) 现代的基本 資本數據解釋的管理 (2) (2) (2) (2) (4)
12. Check A	appropriate Box to Indicate Na	ture of Notice. Re	oort or Other Data
NOTICE OF IN			QUENT REPORT OF:
PERFORM REMEDIAL WORK	[	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON PULL OR ALTER CASING		COMMENCE DRILLING CASING/CEMENT JO	
DOWNHOLE COMMINGLE	MOLTIPLE COMPL	CASING/CEMENT JC	PB ∐
· —	_		_
OTHER:		OTHER:	o mantinant datas impludina antinatad data
	rk). SEE RULE 19.15.7.14 NMAC.		ye pertinent dates, including estimated date
proposed completion or reco	•	To Munipie Compi	Alons. Attach wendore diagram of
1) SET 5-1/2" CIBP @ 9,000';	· DLIMD 25 SYS CMT @ 0 000' 8	810' CIDC WELL W	Approved for plugging of well hore only.
2) PUMP 25 SXS, CMT, @ 6.832'-6.672' (T/WC): WOC X TAG CMT, PLUG.			
3) PERF. X ATTEMPT TO SOZ. 60 SXS. CMT. @ 5,387'-5,237' (T/ABO). which may be found at OCD Web Page to			
4) PERF. X ATTEMPT TO SQZ. 50 SXS. CMT. @ 3,355'-3,225' (T/GLOR.).  Forms, www.cmmrd.state.nm.us/ocd.			
<ul> <li>5) CUT X PULL 5-1/2" CSG. @ +/-1,900'.</li> <li>6) PUMP 45 SXS. CMT. @ 1960'-1,840' (5-1/2" CSG.STUB X 8-5/8" CSG.SHOE); WOC X TAG CMT. PLUG.</li> </ul>			
7) PUMP 35 SXS. CMT. @ 39 8) MIX X CIRC. TO SURF. 2:	93'-293' (T/ANHY. X 13-3/8" CSG. 5 SXS. CMT. @ 63'-3'.	SHOE), WOU A TAC	CMT. FLOG.
		EEL PLATE TO CSO	SS. X INSTALL DRY HOLE MARKER.
		CONDITION	ONS OF APPROVAL ATTACHED
			I Granted providing work is
Spud Date:		C	ad by
spaa bate.	Rig Release Date	e: Complet	1 2 - 2014
	Rig Release Dat	e: Complet	July 2-2014
			July 2-2019
I hereby certify that the information a			July 2-2019
			July 2-2019
		st of my knowledge an	July 2-2019
I hereby certify that the information a	above is true and complete to the bes	et of my knowledge an	d belief.  DATE: 06/25/13
I hereby certify that the information a  SIGNATURE  Type or print name: DAVID A. EYI	above is true and complete to the bes	et of my knowledge an	d belief.  DATE: 06/25/13
I hereby certify that the information a	TITLE: AGE  LER E-mail address: DEYLI	ENT ER@MILAGRO-RES	DATE: 06/25/13  COM PHONE: 432.687.3033
I hereby certify that the information a  SIGNATURE  Type or print name: DAVID A. EYI	above is true and complete to the bes	et of my knowledge an	DATE: 06/25/13  COM PHONE: 432.687.3033





## NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

## CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operator: Cimarex Energy Co. of Colorado Well Name & Number: Crow Flats 16 State 1 API#: 30-015-21151

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- **4.** Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

- 9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
- 10. Plugs may be combined after consulting with and getting approval from NMOCD.

11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: July 2, 2013

APPROVED BY: PROCE

## **GUIDELINES FOR PLUGGING AND ABANDONMENT**

## DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub
  plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
  - o Fusselman
  - o Devonian
  - o Morrow
  - o Wolfcamp
  - o Bone Spring
  - o Delaware
  - Any Salt Section (Plug at top and bottom)
  - o Abo
  - o Glorieta
  - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section. Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).