Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

OCD Artesia

FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010

5. Lease Serial No. NMLC063622

6. If Indian, Allottee or Tribe Name

## Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. I. Type of Well 8. Well Name and No. Oil Well Other Gas Well CEM Federal #1 2. Name of Operator Devon Energy Production Co., LP 9. API Well No. 30-015-05803 3b. Phone No. (include area code) 10. Field and Pool or Exploratory Area 3a. Address 333 W Sheridan Avenue, Oklahoma City, OK 73102 Hackberry; Yates-7 Rvrs, North 405-228-8364 4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) 660' FNL & 1980' FEL: Sec 29-T19S-R31E 11. Country or Parish, State Eddy, NM 12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF ACTION TYPE OF SUBMISSION Acidize Deepen Production (Start/Resume) Water Shut-Off Notice of Intent Well Integrity Alter Casing Fracture Treat Reclamation Casing Repair New Construction Recomplete Subsequent Report Change Plans ✓ Plug and Abandon Temporarily Abandon Plug Back Water Disposal Final Abandonment Notice Convert to Injection 13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.) P&A: 5/3/2013 MIRU. On tbg set CIBP @ 2,120'. 5/6/2013 Circulate hole with 2% KCI. Spot 35 sx cement on plug Displace to 1783'. WOC tag plug @ 1815'. 5/7/2013 Run CBL to confirm TOC. Perforate @ 840' sgz 360 sx out of 5 1/2 & 8 5/8 to surface. 5/8/2013 Top off 5 1/2 w/ 20 sx RDMO. 5/13/2013 Cut off wellhead. Set dry hole marker ACCEPTED FOR RECORD RECLAMATION DUE 11-9-13 Attachments: P&A wellbore schematics. Accepted as to plugging of the well bors. RECEIVED Liability under bond is retained until U OF LAND MANAGEMENT Surface restoration is completed. JUL 01 2013 CARLSBAD FIELD OFFICE 14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed) Derek Berg Title Operations Technician Date 06/10/2013 Signature THUS SPACE FOR FEDERAL OR STATE OFFICE USE Approved by Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false,

(Instructions on page 2)

entitle the applicant to conduct operations thereon.

fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

