Submit 1 Copy To Appropriate District Office	State of New Mex		Form C-103
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 8824)	ECEIVED and Natur	ral Resources	Revised August 1, 2011 WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	JUL OIL CONSERVATION 1220 South St. Fran	DIVISION	30-015-05017
District III – (505) 334-6178			5. Indicate Type of Lease STATE FEE □
1000 Rio Brazos Rd., Aztec, NM 874 0 <u>District IV</u> – (505) 476-3460	IOCD ARTESIA ^{Te, NM 87}	505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505			E-5300
SUNDRY NOTIO (DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC.			7. Lease Name or Unit Agreement Name CONSTATE
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other		8. Well Number 001
2. Name of Operator	Jus Well Other	· · · · · · · · · · · · · · · · · · ·	9. OGRID Number
Alamo Permian Resources. LLC			274841
3. Address of Operator 415 W. Wall Street, Suite 500, Mic	dland TX 79701		10. Pool name or Wildcat QUEEN; SAN ANDRES
4. Well Location	- Tanu, 1 A 19101		QUEEN, SAN ANDRES
Unit Letter C: 330 feet from the N line and 2310 feet from the W line			
Section 36 Township 16S Range 31E NMPM County EDDY			
· · · · · · · · · · · · · · · · · · ·	11. Elevation (Show whether DR, GL 4157'	RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
•		,	•
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WORK COMMENCE DRIL CASING/CEMENT	LING OPNS. P AND A
DOWNHOLE COMMINGLE			
OTHER:		 OTHER: RETUR ⊠	N TO PRODUCTION
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
06/25/13 MIRU; Unhang well. Tried to work stuck pump free without success. Pulled 10,000# tension on rods & left if overnight.			
06/26/13			
Pump still stuck. Install back-off tool on polish rod. Backed off rods. POOH w/rods & pump barrel. ND WH, NU BOP. Unset TAC. Tag fill & POOH w/tbg. Fill @ 2951'. SWI. SDFN.			
06/27/13 No SIWP; PU 4-3/4" bit, bit sub & (6) 3-1/2" drill collars, crossover on 2-3/8" TBG; tagged fill @ 3954'; NU stripperhead & RU swivel; cleaned out to 4011'; circ sand, scale, iron sulphide; gas & approx. 3 bbls oil; RD swivel & ND stripperhead; POOH w TBG; laid dwn drill collars; SWISDON			
6/28/13 PU production TBG BHA; trouble setting 1st TAC; partially set would not hold; POOH & exchange TAC; ND BOP; NU WH; set TAC w/ 6000 lbs tension; eOT @ 3933'; PU & RIH w/ pump & rods; seated pump; spaced out rods; HWO; Load & test pump to 500 PSI. OK			
SIGNATURE TITLE Regulatory Affairs Coordinator DATE 07/08/2013			
Type or print name CARIE STOK	E-mail address: carie@st		PHONE: 432.664.7659
APPROVED BY: Conditions of Approval (if any):	CL TITLE 15T	Hopervi	502 DATE July 11, 2013