


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised August 8, 2011

**Release Notification and Corrective Action**

*NTMW1319929753*

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-105 The spill location is 1912 ft. S.E. of the well location on lease road to tank Battery JRU-19	Facility Type: Exploration and Production

Surface Owner: State of NM	Mineral Owner: State of NM	API No. 30-015-37064
----------------------------	----------------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter J	Section 36	Township 22S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.346486 Longitude W 103.833236

**NATURE OF RELEASE**

Type of Release: Crude oil and produced water	Volume of Release: 2 bbls oil and 6 bbls water	Volume Recovered: 2 bbls total fluid
Source of Release: 2 7/8" flow line	Date and Hour of Occurrence 5/19/13 time unknown	Date and Hour of Discovery 5/19/13 10:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The flow developed a leak due to external corrosion, a temporary repair clamp was placed on the line. The bad section of pipe will be replaced.

Describe Area Affected and Cleanup Action Taken.\*

Approximately 300 sq.ft. of road and approximately 200 sq.ft. of pasture area. The free standing fluid was recovered. The spill area will be remediated in accordance to the NMOC D guidelines for the remediation of spills.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOC D rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOC D marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOC D acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist Signed By: <i>Mike Benavides</i>	
Title: Waste Management and Remediation Specialist	JUL 18 2013	Approval Date: Expiration Date:
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	
Date: 7/14/13 Phone: 432-556-8730	Remediation per OCD Rule & Guidelines. <b>SUBMIT REMEDIATION PROPOSAL NO LATER THAN:</b>	
	Attached <input type="checkbox"/>	

\* Attach Additional Sheets If Necessary

**August 18, 2013**

*2RP-1731*