<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

2RP-1738

Oil Conservation Division 1220 South St. Francis Dr.

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

1220 5. 51. 114						e, NM 8/5			and the spines when the spine	with any factor of the second	The second business of the con-	N. Sa affinisant increase in south
			Rele	ease Notific	cation	and Co	orrective A	ction	1			
Name of Company GP II Energy, Inc. \$359						OPERATOR [			Initial Report  Final Repor			
Name of Co	ompany (	GP'II Energy		Contact Chris Richardson								
Address 113 Corporate Dr. Facility Name Littlefield Federal BO #2						Telephone No. 432-967-8950						
Facility Na	me Little	field Federal	BO #2		1_	Facility Typ	e Tank Batter	y	<del></del>			
Surface Ow	ner Feder	al		Mineral C	)wner	Federal			API No	. 30-015-	24529	
				LOCA	TIO	OF RE	LEASE			,		
Unit Letter									t/West Line   County			
В				Nor	orth 660 Ea			st Eddy				
	<u> </u>	<u> </u>		<u> </u>								
			La	titude <u>32 . 🔗</u>	033	_ Longitud	le-(03.96	554				
				NAT	TIRE	OF REL	EASE					
Type of Rele	ase Water	CICO	Volume of	Volume R	Volume Recovered 8-10 Bbls.							
Source of Re	lease Wat					Date and Hour of Discovery						
Was Immedia	nte Notice (		6July2013 If YES, To			6July2013	9:30 am					
was militedia	aic Notice C		Yes 🔽	No □ Not Re	equired	11 123, 10	whom:					
By Whom?		·	<u> </u>	Date and Hour								
Was a Water	course Read		If YES, Volume Impacting the Watercourse.									
			Yes 🗹	No								* *
If a Watercou	irse was Im	pacted, Descr	ibe Fully.*	*		<del></del>			DE	CEI	/r-n	
	•								Inc	CEN	/こし	
									j	UL 22 2	2013	
			<del></del>				<del></del>					<del> </del>
Describe Cause of Problem and Remedial Action Taken.*									NMOCD ARTESIA			
Power switch	ed off on tr	ansfer pump	caused wa	iter storage tank to	overflo	w. Vacuume	ed up spill inside	berm.	6			- Target
Describe Are	a Affected a	and Cleanup A	Action Tak	cen *								
				area. Operator ha	s contac	ted Basin En	vironmental to ev	aluate a	nd remediat	e contamin	ation.	
				is true and compl								
				id/or file certain re e of a C-141 repo								
should their o	perations ha	ave failed to a	dequately	investigate and re	mediate	contamination	on that pose a thre	eat to gr	ound water,	surface wa	ter, huma	an health
				tance of a C-141 r	eport do	es not relieve	e the operator of r	esponsi	bility for co	mpliance w	ith any o	ther
federal, state,	or local lav	vs and/or regu	lations.				OIL CONS	SEDV	ATION	DIVISIO	NI	
20 4						OIL CONSERVATION DIVISION						
Signature:	- De		mple	-~						11		
Printed Name: JOE COMPTON						Approved by Environmental Specialist: Signed By Mily Brance						
	1		JUL 2 3 2013									
Title:	AGEN	<u>T</u>	<del></del>	<del></del>	A	approval Date	2:	<u> </u>	Expiration D	Pate:		
E-mail Addre	ss: Cao vi	noton (	ම්. අත්	Zenergy.	Chan C	Conditions of	Approval:		•			
	_	1	4.1	JI	1	Remediatio	n per oco kuie	& Guid	elines, &	Attached	L	
Date:	ر بر بر ر اعتادات	ZOI		432-684-47	48	ike approva	I by BLM. SUBM	IT REM	EDIATION	455		
Attach Addit	ionai snee	is ii necessa	uy 😮	EXT. 7.9		→ PRC	POSAL NO LATE	K I DA	3.	1PI	) 1	and

EXT. 29