Form 3:160- 5 (August, 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED

OMB No. 1004- 0137

Expires: July 31, 2010

L'ease Serial No.


SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.	
SUBMIT IN TRIPLICATE - Other Instructions on page 2.	

NMNM121474	
If Indian, Allottee, or Tribe Name	
If Unit or CA. Agreement Name and/or No.	

SUBMIT IN:	7. If Unit or	7. If Unit or CA. Agreement Name and/or No.				
I. Type of Well X Oil Well Gas Well	Other		8. Well Nam	e and No.		
2. Name of Operator COG Production LLC	a.		Coppo 9. API Well	erhead 31 Federal Com #1H		
3a. Address 2208 W. Main Street	area code) 3-6940	30-015-38532 10. Field and Pool, or Exploratory Area Delaware River; Bone Spring 11. County or Parish, State Eddy County NM				
Artesia, NM 88210. 4. Location of Well (Footage, Sec., T., R., M.	Del					
SHL: 480' FSL & 480' FEL, Un						
12. CHECK APPROPRIATE BOX	S) TO INDICATE NATUR	E OF NOTICE, REPORT	Γ, OR OTHER DATA	;		
TYPE OF SUBMISSION	E OF ACTION	i				
Notice: of Intent	Acidize	Deepen	Production (Start/ Resume)	Water Shut-off		
, 5, %	Altering Casing	Fracture Treat	Reclamation	Well Integrity		
X Subsequent Report	Casing Repair	New Construction	Recomplete	X Other		
A pro-	Change Plans	Plug and abandon	Temporarily Abandon	Site Facility		
Final Abandonment Notice	Convert to Injection	Plug back	Water Disposal	and the second s		
13. Describe Proposed or Completed Or	peration (clearly state all pertino	nt details including estimated	d starting date of any proposed	work and approximate duration thereof.		

If the proposed or Completed Operation (clearly state all pertinent details including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths or pertinent markers and sands. Attach the Bond under which the work will performed or provide the Bond No. on file with the BLM/ BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Finally Abandonment Notice shall be filed only after all requirements; including reclamantion, have been completed, and the operator has determined that the site is ready for final inspection.)

Please see attached Site Facility Diagram.



RECARRADA JUL 25 2013
NMOCE, ATTACES

JUL 2 5 2013


NMOCD ARTESIA

Accepted for Record Purposes.

Approval Subject to Onsite Inspections.

						٠.	#4 # j	
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)				· · · · · · · · · · · · · · · · · · ·	٠.			
Amy Avery		Title: Reg	ulatory [Fechnician		•	. '.'	
Signature: Amy Avery	e de la companya de l	Date: 5/-1/	13 10	OFOTER			1	
THIS SPACE F	OR FEDER	RAL OR ST	ALENDA	FICE USE	FUK KEU	UKU		5
/s/ Jerry Blakley		Title:		grander Grander	Date:			
Conditions of approval, if any are attached. Approval of this notice doe certify that the applicant holds legal or equitable title to those rights in which would is entitle to the applicant to those conduct operations.	the subject lea	śe Office: • •	. A	JUL2-2	3 2013			
Title 18 U.S.C. Section 1001 AND Title 43 U.S.C. Section 1212, mal	ke it a crime	for any perso	1			_1	or agency of	the United
States any, false, fictitious or fraudulent statements or représentations as to any ma (Instructions on page 2)	mer,wanin itsjui	asdiction.			ND MANAGEME FIELD OFFICE	NT		*





Copperhead 31 Federal Com #1H

COG Production LLC Copperhead 31 Federal Com #1H NMNM121474 30-015-38532 Sec 31-T26S-R29E Eddy County, NM

1. Production Phase (OT#1)

- A. Valves #1,#2,#4,#5,#7 Open
- B. Valve #3 Closed and Sealed
- C. Valve #6 Closed
- D. Valves on OT #2 Positioned:
 - 1. Valves #1, #3 Closed and sealed

Production Phase (OT #2)

- A. Valves #1,#2,#4,#5,#7 Open
- B. Valve #3 Closed and Sealed
- C. Valve #6 Closed
- D. Valves on OT #1 and #3 Positioned:
 - 1. Valves #1.#3 & #4 Closed and Sealed

II. Sales Phase (OT#1)

- A. Valves #1,#2 and #4 Closed and Sealed
- B. Valve #3 on OT #1 Open
- C. Valves on OT #2 Positioned:
- 1. Valve #1 Open
 - 2. Valve#2, #3 and #4 Closed and Sealed

Sales Phase (OT#2)

- A. Valves #1,#2and #4 Closed and Sealed
- B. Valve #3 on OT #2 Open
- C. Valves on OT #1 Positioned:
 - 1. Valve #1 Open
 - 2. Valve #2, #3 and #4 Closed and Sealed

Production Phase (OT #3)

- A. Valves #1,#2,#4,#5,#6 & #8 Open
- B. Valve #3 Closed and Sealed
- C. Valve #7 Closed
- D. Valves on OT #2 and #1 Positioned:
 - 1. Valves #1,#2, #3 & #4 Closed and Sealed

Sales Phase (OT#3)

- A. Valves #1,#2and #4 Closed and Sealed
- B. Valve #3 on OT #3 Open
- C. Valves on OT #1 and #2 Positioned:
 - 1. Valve #1 and #2 Open
 - 2. Valve #3 and #4 Closed and Sealed