MECEIVED

	State of field thing	exico	Form C-103			
Office District I	Energy, Minerals and Natu	Fala Resources DTCCL	June 19, 2008			
1625 N. French Dr., Hobbs, NM 88240		IAINIOCD YULEAD	LE API NO.			
District II	OIL CONSERVATION		T5-40988			
1301 W. Grand Ave., Artesia, NM 88210 District III	1220 South St. Fran	l 🤊 ir	dicate Type of Lease			
1000 Rio Brazos Rd., Aztec, NM 87410			STATE STATE FEE			
District IV	Santa Fe, NM 87	6. Si	tate Oil & Gas Lease No.			
1220 S. St. Francis Dr., Santa Fe, NM						
87505	ICES AND REPORTS ON WELLS	7 1	ease Name or Unit Agreement Name			
	SALS TO DRILL OR TO DEEPEN OR PLU		LEY STATE			
	CATION FOR PERMIT" (FORM C-101) FO		LEISIAIE			
PROPOSALS.)		L	/ell Number #26			
1. Type of Well: Oil Well	Gas Well Other					
2. Name of Operator		9. O	GRID Number 281994			
LRE OPERATING, LLC						
3. Address of Operator	•	Pool name or Wildcat				
c/o Mike Pippin LLC, 3104 N. Sul	Red I	Red Lake, Glorieta-Yeso NE (96836)				
		Red L	Red Lake, Queen-Grayburg-San Andres (51300)			
4. Well Location						
Unit Letter L : 1655 fo	eet from the SOUTH line and	990 feet from the	WEST line			
Section 30		Range 28-E NMPM				
Section 30	11. Elevation (Show whether DR,		Ludy County			
	Ref. I	(KKB, KI, GK, etc.)				
	3598' GL					
12. Check	Appropriate Box to Indicate N	ature of Notice, Repo	rt or Other Data			
NOTICE OF IN	ITENTION TO:	SUBSEQ	UENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON 📋	☐ ALTERING CASING ☐				
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING	OPNS.□ P AND A □			
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT JOB				
		1				
DOWNHOLE COMMINGLE		1				
DOWNHOLE COMMINGLE 🔀						
OTHER: Acidize Yeso, Open San	Andres, & DHC	OTHER:				
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of	perations. (Clearly state all pertinent details,	and give pertinent dates, including	g estimated date of starting any proposed work).			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple C	perations. (Clearly state all pertinent details, Completions: Attach wellbore diagram of pro	and give pertinent dates, including posed completion or recompletion	on,			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple C LRE would like to acidize the existi	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of prong Yeso perfs, recomplete into the F	and give pertinent dates, including posed completion or recompletion Red Lake, Queen-Graybur	on. g-San Andres (51300), and DHC as			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple C LRE would like to acidize the existifollows: MIRUSU. TOH w/rods, p	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of prong Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If r	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple C LRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3	perations. (Clearly state all pertinent details, Completions: Attach wellbore diagram of prong Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If results a process of the Process of t	and give pertinent dates, including posed completion or recompletion Red Lake, Queen-Grayburnecessary, treat Yeso perfsion. (Existing Yeso perfs ar	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple C LRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of prong Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If r	and give pertinent dates, including posed completion or recompletion Red Lake, Queen-Grayburnecessary, treat Yeso perfsion. (Existing Yeso perfs ar	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 holds.	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of prong Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If 1310' & PT csg & CBP to ~ 3500 pses. Stimulate with ~2500 gal 15% I	and give pertinent dates, including posed completion or recompletion Red Lake, Queen-Grayburnecessary, treat Yeso perfs. (Existing Yeso perfs ar HCL acid & frac w/~83,000	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel.			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 holes a 5-1/2" CBP @ ~2634' & PT of Set a 5-1/2" C	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of prong Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If r \$130' & PT csg & CBP to ~ 3500 ps es. Stimulate with ~2500 gal 15% If sg & CBP to ~3500 ps.	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfsoi. (Existing Yeso perfs ar HCL acid & frac w/~83,00 e San Andres @~2400'-2	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel.			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 holes a 5-1/2" CBP @ ~2634' & PT of Set a 5-1/2" C	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of prong Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If 1310' & PT csg & CBP to ~ 3500 pses. Stimulate with ~2500 gal 15% I	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfsoi. (Existing Yeso perfs ar HCL acid & frac w/~83,00 e San Andres @~2400'-2	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel.			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of prong Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If results are the scale in the scale i	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfision. (Existing Yeso perfis and HCL acid & frac w/~83,00 e San Andres @~2400'-2 ed gel.	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 90# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If results are the state of the scale	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs and LCL acid & frac w/~83,00 e San Andres @~2400'-2 ed gel.	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 90# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of prong Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If results are the scale in the scale i	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs and LCL acid & frac w/~83,00 e San Andres @~2400'-2 ed gel.	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 90# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 holes a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c ~3000 gal 15% HCL acid & frac w/	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Fourier, & tog & inspect for scale. If results in the Fourier of the Four	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs is: (Existing Yeso perfs and ACL acid & frac w/~83,000 e San Andres @~2400'-2 ed gel. The San Andres @~2070'-25 ed gel.	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/CO after frac & drill out CBPs @ 2	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Fourier, & ting & inspect for scale. If results in the Fourier of the Property	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs in (Existing Yeso perfs are HCL acid & frac w/~83,000 e San Andres @~2400'-2 ed gel. To @ 4875'. Land 2-7/8"	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 671' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/CO after frac & drill out CBPs @ 2 & rods & release workover rig. Coefficients	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Fourier, & ting & inspect for scale. If results are the scale in the Fourier of the scale in the s	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs in (Existing Yeso perfs are HCL acid & frac w/~83,000 e San Andres @~2400'-2 ed gel. To @ 4875'. Land 2-7/8" Andres oil well. Work wi	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 371' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/CO after frac & drill out CBPs @ 2 & rods & release workover rig. Coefficients	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Fourier, & ting & inspect for scale. If results in the Fourier of the Property	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs in (Existing Yeso perfs are HCL acid & frac w/~83,000 e San Andres @~2400'-2 ed gel. To @ 4875'. Land 2-7/8" Andres oil well. Work wi	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 371' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c ~3000 gal 15% HCL acid & frac w/ CO after frac & drill out CBPs @ 2 & rods & release workover rig. Coapplication in Santa Fe is approved.	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If results are perfectly as a scale of the scale of	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburg necessary, treat Yeso perfs and HCL acid & frac w/~83,00 e San Andres @~2400'-2 ed gel. To @ 4875'. Land 2-7/8" Andres oil well. Work wick system. See the attache	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 371' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC d wellbore diagram.			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c ~3000 gal 15% HCL acid & frac w/ CO after frac & drill out CBPs @ 2 & rods & release workover rig. Coapplication in Santa Fe is approved. Spud Date: 2/6/13	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If results are the scale in the Foundation of the scale in the s	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs and Existing Yeso perfs and Yeso p	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 871' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC d wellbore diagram. 2/12/13			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c ~3000 gal 15% HCL acid & frac w/ CO after frac & drill out CBPs @ 2 & rods & release workover rig. Coapplication in Santa Fe is approved.	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If results are the scale in the Foundation of the scale in the s	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs and Existing Yeso perfs and Yeso p	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 871' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC d wellbore diagram. 2/12/13			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c ~3000 gal 15% HCL acid & frac w/ CO after frac & drill out CBPs @ 2 & rods & release workover rig. Co application in Santa Fe is approved. Spud Date: 2/6/13 Thereby certify that the information	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If results in the Foundation of the Property	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfissi. (Existing Yeso perfis and CL acid & frac w/~83,00 e San Andres @~2400'-2 ed gel. To @ 4875'. Land 2-7/8" Andres oil well. Work wick system. See the attache Rig Release Date:	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 671' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC d wellbore diagram. 2/12/13 pelief.			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c ~3000 gal 15% HCL acid & frac w/ CO after frac & drill out CBPs @ 2 & rods & release workover rig. Coapplication in Santa Fe is approved. Spud Date: 2/6/13	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Foump, & tbg & inspect for scale. If results in the Foundation of the Property	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs and Existing Yeso perfs and Yeso p	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 871' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC d wellbore diagram. 2/12/13			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~2 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c ~3000 gal 15% HCL acid & frac w/ CO after frac & drill out CBPs @ 2 & rods & release workover rig. Coapplication in Santa Fe is approved. Spud Date: 2/6/13 Thereby certify that the information SIGNATURE	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Fourier, & ting & inspect for scale. If results are the scale in the Fourier of the Four	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs in (Existing Yeso perfs and HCL acid & frac w/~83,000 e San Andres @~2400'-2 ed gel. To @ 4875'. Land 2-7/8" Andres oil well. Work wick system. See the attache Rig Release Date: est of my knowledge and the eum Engineer - Agent	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 871' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC d wellbore diagram. 2/12/13 pelief. DATE			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~2 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/CSET SET SET SET SET SET SET SET SET SET	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Fourier, & ting & inspect for scale. If results are the scale in the Fourier of the Four	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs in (Existing Yeso perfs and HCL acid & frac w/~83,000 e San Andres @~2400'-2 ed gel. To @ 4875'. Land 2-7/8" Andres oil well. Work wick system. See the attache Rig Release Date: est of my knowledge and the eum Engineer - Agent	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 671' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC d wellbore diagram. 2/12/13 pelief. DATE			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~2 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c ~3000 gal 15% HCL acid & frac w/ CO after frac & drill out CBPs @ 2 & rods & release workover rig. Coapplication in Santa Fe is approved. Spud Date: 2/6/13 Thereby certify that the information SIGNATURE	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Fourier, & ting & inspect for scale. If results are the scale in the Fourier of the Four	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs in (Existing Yeso perfs and HCL acid & frac w/~83,000 e San Andres @~2400'-2 ed gel. To @ 4875'. Land 2-7/8" Andres oil well. Work wick system. See the attache Rig Release Date: est of my knowledge and the eum Engineer - Agent	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 871' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC d wellbore diagram. 2/12/13 pelief. DATE			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~3 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/ Set a 5-1/2" CBP @ ~2385' & PT c ~3000 gal 15% HCL acid & frac w/ CO after frac & drill out CBPs @ 2 & rods & release workover rig. Cot application in Santa Fe is approved. Spud Date: 2/6/13 Thereby certify that the information SIGNATURE Mike Pippir For State Use Only	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Fourier, & ting & inspect for scale. If results are the scale in the Fourier of the Four	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs in (Existing Yeso perfs and HCL acid & frac w/~83,000 e San Andres @~2400'-2 ed gel. To @ 4875'. Land 2-7/8" Andres oil well. Work wick system. See the attache Rig Release Date: est of my knowledge and the eum Engineer - Agent	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 671' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC d wellbore diagram. 2/12/13 pelief. DATE 7/24/13 PHONE: 505-327-4573			
OTHER: Acidize Yeso, Open San 13. Describe proposed or completed of SEE RULE 1103. For Multiple CLRE would like to acidize the existifollows: MIRUSU. TOH w/rods, pas required. Set a 5-1/2" CBP @ ~2 Andres @ ~2650'-2891' w/ ~24 hold Set a 5-1/2" CBP @ ~2634' & PT c ~2200 gal 15% HCL acid & frac w/CSET SET SET SET SET SET SET SET SET SET	perations. (Clearly state all pertinent details, completions: Attach wellbore diagram of proing Yeso perfs, recomplete into the Fourier, & ting & inspect for scale. If results are the scale in the Fourier of the Four	and give pertinent dates, including posed completion or recompletic Red Lake, Queen-Grayburnecessary, treat Yeso perfs in (Existing Yeso perfs and HCL acid & frac w/~83,000 e San Andres @~2400'-2 ed gel. To @ 4875'. Land 2-7/8" Andres oil well. Work wick system. See the attache Rig Release Date: est of my knowledge and the eum Engineer - Agent	on. g-San Andres (51300), and DHC as w/calcium sulfate converter & acidize e @ 3154'-4560'). Perf lower San 00# 16/30 sand in 20# X-linked gel. 617' w/~20 holes. Stimulate with 871' w/~28 holes. Stimulate with production tbg @ ~4679'. Run pump ll not commence until the DHC d wellbore diagram. 2/12/13 pelief. DATE			

District I 1625 N. French Dr., Hobbs, NM 88240 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV

State of New Mexico Energy, Minerals & Natural Resources Present Ent VED OIL CONSERVATION DIVISION 25 2013 Submit to Appropriate District Office State Lease - 4 Copies Santa Fe, NM 87505 NMOCD ARTESIA

Revised October 12, 2005

Fee Lease - 3 Copies

Form C-102

1220 S. St. Francis	Dr., Santa	re, MM 8/3	905			-		L] AME	NUEU KEPUK I	
			WELL LO	CATIO	N AND ACE	REAGE DEDIC	CATION PLA	ΛT.			
¹ API Number ² 1				² Pool Cod	Pool Code ³ Pool Name						
30-	015-409	88		51300	51300 Red Lake, Queen-Grayburg-San Andres						
⁴ Property Code					⁵ Property	Name			6 W	Vell Number	
309874	4				STALEY STATE			1	26		
⁷ OGRID N	Vo.				⁸ Operator Name			⁹ Elevation		Elevation	
281994				LRE OPERATING, LLC				3598' GL		598' GL	
					¹⁰ Surface	Location					
UL or lot no.	Section	Township					Feet from the	East/West	East/West line County		
L	30	17-S	28-E	3	1655	SOUTH	990'	WES	T	EDDY	
		· · · · · · · · · · · · · · · · · · ·	11 Bc	ottom Ho	ole Location I	f Different Fro	m Surface				
UL or lot no.	Section	Township		Lot Ide		North/South line	Feet from the	East/West	t line	County	
		-									
12 Dedicated Acres	13 Joint o	r Infil)	14 Consolidation	Code 15 C	l Irder No.		i				
40											
No allowable v	vill be ac	signed to	this complet	tion until (Il interests have	been consolidated	or a non standa	rd unit has	hoon on	proved by the	
division.	viii de as	signed to	uns complei	Jon until 2	iii iiiteresis iiave	been consolidated	or a non-standa	ra unn nas	оеен ар	proved by the	
		T					17 0	PERATOI	CERT	TFICATION	
							B			d herein is true and complete	
					l li		to the best of my knowledge and belief, and that this organization either				
						owns a workin	owns a working interest or unleased mineral interest in the land including				
				İ			1			ght to drill this well at this	
							II .			of such a mineral or working	
							J)			or a compulsory pooling	
								ore entered by the	1	7/24/13	
				ŀ				Wike to	ppen	/ 	
							Signature	·	•	Date	
				į			Mike Pipp	oin .			
							Printed Nam			· · · · · · · · · · · · · · · · · · ·	
				1			- Anna Anna Anna Anna Anna Anna Anna Ann				
				30 —			18CI ID	VEVOD	CEDT	IFICATION	
				İ						tion shown on this	
							11	• •		of actual surveys	
0003							11			sion, and that the	
990'							li i				
	7						li .	ue ana correc	i io ine be	st of my belief.	
	1 1			-			12/27/12			·	
<u>, , , , , , , , , , , , , , , , , , , </u>							Date of Surv	•			
							i i	nd Seal of Profes	ssional Surv	eyor:	
				1			Filmon F. Ja	ramillo			
1655'	1										
=							1				
Ì		i i					12797				
j							Certificate N	umber			