Submit I Copy To Appropriate District Office	State of New Mexico	Form C-103
Office <u>District 1</u> – (575) 393-6161 RECEIVE 1625 N. French Dr., Hobbs, NM 88240	(Resources), Minerals and Natural Resources	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240		WELL API NO. 30-015-24887
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 SEP 20 20 BL CONSERVATION DIVISION		5. Indicate Type of Lease
District III = (505) 334-6178 1290 South St. Francis Dr.		STATE S FEE
1000 Rio Brazos Rd., Azted NMOCD ARTESIA Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		B-5862
SUNDRY NOTICES AND		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		HUDSON SAIKEN STATE
1. Type of Well: Oil Well Gas Well	Other	8. Well Number 2
2. Name of Operator ALAMO PERMIAN RESOURCES LLC		9. OGRID Number 274841
3. Address of Operator 415 W. WALL ST., SUITE 500 MIDLAND, TX 79701		10. Pool name or Wildcat
		RED LAKE; Queen-Grayburg-San Andres
4. Well Location		
Unit Letter \underline{E} : 2310 feet from the	N line and 990 feet from the W line	
Section 31 Township	<u>17S</u> Range <u>28E</u> NMP	M County EDDY
₩ 11. Elev	ration (Show whether DR, RKB, RT, GR, etc.)	The second second
. 12 Cl. 1 A	D (I I' (NI (CNI (' D	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK 🗌 PLUG A	ND ABANDON 🔲 REMEDIAL WOR	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐		
	LE COMPL	「JOB □
DOWNHOLE COMMINGLE		
OTHER:	☐ OTHER: ⊠RI	ETURN TO PRODUCTION
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
09/13/13		
MIRU PU. Unhang well & POOH w/rods. Had trouble getting out of the hole w/pump due to paraffin. ND WH, NU BOP. Rel TAC &		
tag fill @ 1893'. POOH w/tbg. SWI. SDFWE.		
00/16/13		
09/16/13 No SI well pressure. RIH w/OE tbg. MIRU hot	ail unit & alaan 2 2/0" tha u/75 DEW & no	waffin calvant DOOLL w/kha DIII
w/production BHA. Drop stdg valve. Test tbg t		
The state of the s	over post. Bled on ou post. No test, got same	testisi i een mag. emi een m
09/17/13		
MIRU Empire Tubing Testers. Test tbg to 5000 psi below the slips. RD testers. ND BOP, NU WH. RIH w/pump & rods. Seat pump &		
HWO. Load tbg & pressure pump to 500 psi, ok. Clean location. RDMO.		
•		
I hamaha agarifa that the information of any is two		
THEREBY CELLLY MALTINE INTOLINATION ABOVE IS THE	o and a surple of the back of the large	
	e and complete to the best of my knowledge	and belief.
SIGNATURE CONIO STOR	e and complete to the best of my knowledge TITLE Regulatory Affairs Coording	
SIGNATURE CONIO STOR	TITLE Regulatory Affairs Coordina	ator DATE <u>09/18/13</u>
C_{-} C_{+}	TITLE Regulatory Affairs Coordinates: carie@stokeroilfield.com PHONE: 432 6	ator DATE <u>09/18/13</u> 64 7659
SIGNATURE Carie Stoker E-mail addres	TITLE Regulatory Affairs Coordina	ator DATE <u>09/18/13</u> 64 7659