

Submit 1 Copy To Appropriate District Office  
District I – (575) 393-6161  
1625 N. French Dr., Hobbs, NM 88240  
District II – (575) 748-1283  
811 S. First St., Artesia, NM 88210  
District III – (505) 334-6178  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV – (505) 476-3460  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised August 1, 2011

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-015-01850
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B819614
7. Lease Name or Unit Agreement Name COWTOWN UNIT
8. Well Number 301
9. OGRID Number 274841
10. Pool name or Wildcat ARTESIA;QU-GB-SA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) GL 3559'

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator  
Alamo Permian Resources, LLC

3. Address of Operator  
415 W. Wall Street, Suite 500, Midland, TX 79701

4. Well Location  
Unit Letter N : 660 feet from the S line and 1980 feet from the W line  
Section 13 Township 18S Range 28E NMPM County EDDY

11. Elevation (Show whether DR, RKB, RT, GR, etc.)  
GL 3559'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☒ RETURN TO PRODUCTION

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

09/30/2013

MIRU RIG. UNHANG WELL AND POOH WITH PUMP AND RODS. SHOP PUMP. ND WELLHEAD. NU BOP. UNSET; TAC, TAGGED FILL AND POOH WITH TUBING. TAGGED @ 2950'. SWI. SDON.

10/01/2013

NO SHUT IN PRESSURE. MIRU TUBING TESTERS; RIH WITH MULE SHOE JOINT, SEATING NIPPLE AND 2 JOINTS OF TUBING. PU TEST TOOLS, TROUBLE GETTING TEST TOOLS; IN TUBING CAUSING TUBING TO FALL. WAIT ON OVERSHOT AND FISHED BHA OUT OF WELL. RIH WITH TUBING TESTING TO 5000 PSI. FOUND 4 BAD JOINTS AND CRACKED TUBING COLLAR. REPLACED BAD TUBING. SET TAC. ND BOP. NU WELLHEAD; PREP FOR RODS. SWISDON;

*Is depth?*

10/2/13

PU AND RIH WITH PUMP AND RODS. SPACED; OUT PUMP. TEST PUMP TO 500 PSI. OK. RDMO.

Spud Date:

Rig Release Date:

RECEIVED

OCT 07 2013

NM OGD ARTESIA

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Carie Stoker*

TITLE

Regulatory Affairs Coordinator

DATE 10/03/2013

Type or print name

CARIE STOKER

E-mail address: carie@stokeroilfield.com

PHONE: 432.664.7659

APPROVED BY:

*RL Dade*

TITLE

*Dis. R. Spewison*

DATE 10/9/2013

Conditions of Approval (if any):