# **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Bi	UREAU OF LAND MANAC	JEMENT OCT 6	0 2012	5. Lease Serial No.	
SUNDRY NOTICES AND REPORTS ON WELLS OCT 2 3 2013  Do not use this form for proposals to drill or to rejenter an				NMLC029395A	
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals CD ARTESIA				5. If Indian, Allottee	or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agre	ement, Name and/or No.
Type of Well     Gas Well □ Oth	ner	The second secon		8. Well Name and No TURNER A 024	
2. Name of Operator LINN ENERGY		TERRY B CALLAHAN		9. API Well No. 30-015-05275	7111
3a. Address		3b. Phone No. (include area coo	de)	10. Field and Pool, or	Exploratory
600 TRAVIS STREET, SUITE HOUSTON, TX 77002		Ph: 281-840-4272		GRAYBURG J	ACKSON;SRQ-G-SA
4. Location of Well (Footage, Sec., T	R., M., or Survey Description)			11. County or Parish.	and State
Sec 19 T17S R31E Mer NMP 32.824544 N Lat, 103.911516		_		EDDY COUNT	Y, NM
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	F NOTICE, RI	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION		TYPE	OF ACTION		
Notice of Intent	☐ Acidize	Deepen	☐ Product	ion (Start/Resume)	■ Water Shut-Off
_	☐ Alter Casing	☐ Fracture Treat	□ Reclam:	ation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	■ New Construction	□ Recomp	lete	Other
☐ Final Abandonment Notice	Change Plans	🔀 Plug and Abandon	☐ Tempor	arily Abandon	
	☐ Convert to Injection	☐ Plug Back	■ Water D	Disposal	
13. Describe Proposed or Completed Op If the proposal is to deepen directions Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for fi	ally or recomplete horizontally, rk will be performed or provide	give subsurface locations and mea the Bond No. on file with BLM/E	asured and true ve BIA. Required sub	rtical depths of all pertinosequent reports shall be	nent markers and zones.
PROPOSED P&A PROCEDU					S OF APPROVAL
1. MIRU P&A RIG. RIG W/ TI WOC & TAG.				KS CMT @ 1835'.	
2.,SPOT-30-SXS-CMT-@-126	5'. WOC AND TAG. Per	Forate @ 126	S, SQZ	ent to	MATION DEACEDIES
RECLAMATION PROCEDURI  3. PERF 7" CSG @ 569'. CIRC CMT TO SURFACE INSIDE AND OUT W/ APPROX. 150 SXS CMT.  4. CUT OFF WELLHEAD. INSTALL DRYHOLE MARKER. RDMO.  At cut-off Verify cmt to Surf.				ATTACHED	
4. CUT OFF WELLHEAD. IN	ISTALL DRYHOLE MARK	ER. RDMO.	ut-off	verify cm	+ to Surt,
ATTACHED CURRENT AND	PROPOSED WELLBORE	DIAGRAMS.	~/// WIN	T' VELLER	ial cont
Ground Level Dry Hole M	asker Required	May	be reg	zuired.	
14. I hereby certify that the foregoing is	true and corect. Electronic Submission #2	21202 verified by the BLM W	Vell Information	System	
	For LIN	N ENERGY, sent to the Carl processing by JOHNNY DICK	lsbad	•	
Name(Printed/Typed) TERRY B	•	~ 1		E SPECIALIST III	
				Accepted	for weared
Signature (Electronic S	Submission)	Date 09/25	/2013	URDade MM	
	THIS SPACE FO	R FEDERAL OR STAT	E OFFICE U	SE	
Approved By James	P. amos_	Title Sc	EAS		Date 10-20-13
Conditions of approval, if any, are attache certify that the approxant holds legal or equivalent would entitle the applicant to conduct the applicant the applicant to conduct the applicant t	itable title to those rights in the		FO		
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent	U.S.C. Section 1212, make it a catalements or representations as	crime for any person knowingly a to any matter within its jurisdiction	nd willfully to ma	ake to any department or	agency of the United

Well Name:	Turner A #24					
					Well Name:	Turner A #24
	Location:	9	urrent		API No:	10-015-05275
Location	MA OFT N. DOC	Wellp	ore Diagram		Spud Date:	9/17/1952
Section:	T: 175 R: 31E Sect 19	2 2 4	* * *		WBD Update:	9/6/2013 R. Van Hows
Block: Survey:	The state of the s		141		Hote Strec	
Courty:	[ddy	- 113			Suri Carc	12 8-6/6", 184, I-55
Lat/Tong:			[48]		Cament Bland:	50 sa
Flyld:	From Grayburg Lary ann		118		Depth:	219
31:	Clevetions: 1877)'	\$ M	118		100	N/A
07.		3-13	149		Hole Size:	
13-GL Car:			116	85/81, 258	Int Cox:	
ci m/log?	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	4	[2]	un @ 519"		
Localna Regale			18			
E ALLE THE STATE OF THE STATE O	Industry.		li i		Coment Blend:	
l		1.4	Įš.		Returns:	
L			é		roc	
			LS:		<b>I</b>	
10/10/1957	Soud 12" hole 6 dHS to 1924", Set 9-5/8" cag @ 1,850" & cmtd w/ 50 as cmt, Set 7" prod cag @ 1850" cmtd	3	ž			
	in/ 100sss. Set 5-1/2" casing flow from 1060" to TD, net cemented. Perforated through productive zones.	3	13			
ļ	The state of the s		)ž.		Datafit pi Perfornilor	
10/11/1917	1885-1922 shot with 165 gts, Allino-glycerin		3.		10/18/1962	u - 1,885'-1,923' shot with 165 ats otre-glyt
17/1/1961	Web resided and produced only 1.5 BOPD		ξ.		,,	stone water and and ten titt time Bat
7/77/1973	NOI (Fed to TA mov)	3	[g]			
	POH w/ tig, prod squip, capped well with 2000# WOG valve. Well is TA'd [uneconstrated to produce, wait		I₿			
3/6/2973	os waterflood project in 8-10 yrs)	- 31	19			
1/20/19/9	Bradenhead was piped to surface w/ e valve to statled for persoure checks in accordance w/ OCD  NU DDP, RIM w/ Us and scraper to 1845', POH, RIM w/ CIDP and set @ 1825', Circ well w/ 90 bbls corrector	) }	13			
B/22/1985	Inhibited water, Web is TA'd.		13			
The state of the s		65%	13			
		ĵ.	11		And or Learning Line	iment Details
<del></del>		1	13			
		<u> </u>	18		19/11/1952 1,645'-1,913'	Shot w/ 165 gra ettro-glycatin
			13		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	and the distribution
}		اد	13			
			ij			
			1,1			
		**************************************	13			
		- 3	- 1			
		*	Į.i			Tubing Detail
		14	18		loints	Percription
-			19			2 7/6
<del></del>		14	[N		Pkr Dapth	
		13	N		- FRI Copin	<u> </u>
		12.	lĝ.			
		5.4	ai.		Rods	Rod Datail [top to bottom]
		9	];;		1005	Description .
			[±]			
<b></b>		- {}	i i			
		[]	K		L	
		i i i	K			
		1	Į.		Pumping Units	
		i I	E			
		<u> </u>	1.			
			3			
		1	ľ.			
			I.			
			[:	T", 204		_
		3.1	1;	PB20 1880.		·*
				CIEP @ 1835.	(Usia Sha	
			$\sim$	(F 1413)	Hole Stre: Expd.Sed:	7", 20#
					Capadity (bbV/II):	
			1		Coment Blend:	100 ta
			Ì	OH 1863-1914.	Retains: TOC:	H/A
		- [	•		Depth	1976'
-					1	
		l	1	1,8851-1,482	1	
			1	1,043 ·1,065	[	
1		.	1		<u> </u>	**************************************
	the state of the s		-	1,917-1,922		
			1			
		·				
			1,924			
		PAID	Q 1,435'	Open Flore from 1864	1-1954,	
1						

Well Hame	Turner A #24
· · · · · · · · · · · · · · · · · · ·	Location:
Location	990 75: 3630 Five
Section:	7: 175 R: 316 Sec: 19
B≱ock:	
Servey:	
County:	( de/):
Lat/Long:	
Field:	From Grayburg Jackson
	Clevations:
GL:	1673
DF.	
EB-GA Cabe:	
ch m/leg?	

	Lossica Resultements:		
			1
ľ	]		i

Date	
IQ1171952	Spud 11" fore & drid to 1914') Set &5/8" tag Q 1,050' & contd w/ 50 as cont. Set 7" prod cag Q 1,050' ac w/ 100sas, Set 5-1/2" coulty liner from 1860' to T0, not companied. Perforated through productive sonra.
10/11/1957	1RK5-1922 shat with 165 ats. Nero-gyowin
2/3/1943	Well tested and produced only 1.5 80PD
1/27/1573	NOI Med to TA well
	PCHI w/ thg. prod equip, capped was with 1000M WOG valve. We'll is TA'd (uneconomical to produce, wai
1/6/1971	on waterflood project in 8-10 yrs)
1/29/1979	Braderhand was piped to surface w/ a valve in stalled for pressure checks in accordance w/ OCO
184 2 184 18	RU ECP, XIN w/ 6st and straper to 1848. PCH, NIH w/ CISP and set @ 1835", Chr. well w/ 90 bids concessor
1/13/1505	Inhibited water, WeS is TA'd
	Pirst & Abustion Procedures
	Atti m/ rbg, Tag CIBP @ 1435', circ Mif. Joot 30ss cret @ 1815', WOC L jag.
	Spoj 10a cmi @ 1765', WOC & Ing.
	Peri 7" csg @ 569", Circ con jo suriese inside & out se/ approx 150ss cmi.
~~ »···································	Cut off well hand and install dry hole marker.
	The cut was also a different a resident and a second and a
AND DESCRIPTION OF THE PERSON NAMED IN	
	1
-	
· · · · · · · · · · · · · · · · · · ·	

	rop	2569	4
Nei!	bote	Dia	gram



Well Name:	Turner A #24
API Np:	30-015-05275
Spud (Sate:	9/17/1957
WBD tipdate:	9/34/2013, i., Willbanks

Hale Stre: Suff CAS; Cament Blend: Depth: TOC: B-5/8", 784, F55 50 ts \$10' K/A

8-5/0", 188 set Ø 519 Part Ø 509'

Hale She	<i>-</i>	 ·	
lni Sasi			
Coment Blend	i		
Returns			
toc			

Passife of Parfeculions

10/11/1933 2,845'-1,922' shot with 165 are altro-glycom

#### Sele of Fracture Iraniment Orivis

10/11/1952 1,645'-1,922'

Shot w/ 165 ats nitro-glyceria

Spot 10st cmt @ 1265\*

Tubing Dejali				
Johnta	Description			
	2.7/0			
Pir Oepih				

Red Detail (top to bottom)				
Rods	Description			
1	,			

bemeine Units

Spot 30sa cmi

CIEP @ 1835"

J", 200, sai @ 1860

7", 104 100 sa

Q:(1860-1924)

lick She: Prod Cit. Capadry (bbi/fi): Cament Bland: Returns: TUC: Depth 7/A 1925'

1,025, -1,882

1,917-1,923

TD: 1,934' PSTD (P 1,835'

Open Irole from 1860'-1974'

### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

# Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification</u>: Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-393-3612.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. Dry Hole Marker: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds).

- 7. <u>Subsequent Plugging Reporting</u>: Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation procedure.

# Requirements for dry hole markers in Prairie Chicken Habitat <u>Well Identification Markers</u> Conditions of Approval (COA)

The BLM Carlsbad Field Office (CFO) Conditions of Approval (COA) have required that ground level dry hole markers be placed on wells within the Lesser Prairie Chicken habitat area. Onshore Order 2.III.G.10 allows for surface caps to be installed at the base of the cellar of a minimum of 3 feet below the restored ground level. Therefore, these markers shall be set a minimum of 3 feet below the restored ground level. All markers shall be identified by GPS coordinates.

The dry hole markers will be to the following specifications. The operator will construct the markers as follows:

- 1. A steel plate 1/4 inch thick shall be placed on the wellbore, welded in place and with a weep hole.
- 2. Aluminum data plates may be bolted to the steel plate with minimum ¼ inch bolts and locking nuts or self tapping fine threaded screws. A minimum of one in each corner is to be installed on each plate.
- 3. An 8 inch x 8 inch aluminum plate, which is 12 gauge or .080 sign material (1/8 inch aluminum plate may be used in place of the .080 plate) with the required information for that well stamped or engraved in a minimum 3/8 inch tall letter or number.
- 4. The following information will be stamped or engraved on the 8 inch X 8 inch aluminum plate in the following order.
  - a. First row: Operator's name
  - b. Second row: Well name and number
  - c. Third row: Legal location to include ¼ ¼, Section, Township, and range. If the legal location cannot be placed on one row it can be split into two rows with the ¼ ¼ (example: 1980 FNL 1980 FWL) being on the top row.
  - d. Fourth row: Lease Number and API number.
    - i. Example marker plate: (attached)

Notification to NMOCD of this marker type will be done on the subsequent report of abandonment which is submitted to the BLM after the well is plugged. State that a below ground level dry hole marker was installed and GPS coordinates recorded as required in the COAs from the BLM.



## United States Department of the Interior

#### BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

#### Reclamation Objectives and Procedures

Reclamation Objective: Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any and all contaminants, scrap/trash, equipment, pipelines and powerlines. Strip and remove caliche, contour the location to blend with the surrounding landscape, redistribute the native soils, provide erosion control as needed, rip and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation

equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

#### **Inspection & Enforcement**

Jim Amos Supervisory Environmental Protection Specialist 575-234-5909, 575-361-2648 (Cell)

Mike Burton Environmental Protection Specialist 575-234-2226

Jeffery Robertson Natural Resource Specialist 575-234-2230

Jennifer Van Curen Environmental Protection Specialist 575-234-5905

Doug Hoag Civil Engineering Technician 575-234-5979

Linda Denniston
Environmental Protection Specialist
575-234-5974

Solomon Hughes Natural Resource Specialist 575-234-5951

#### Permitting

Cody Layton Natural Resource Specialist 575-234-5959

Trishia Bad Bear Natural Resource Specialist 575-393-3612

Todd Suter Surface Protection Specialist 575-234-5987

Tanner Nygren Natural Resource Specialist 575-234-5975

Amanda Lynch Natural Resource Specialist 575-234-5922

Legion Brumley Environmental Protection Specialist 575-234-5957

#### Realty, Compliance

Randy Pair Environmental Protection Specialist 575-234-6240