Submit I Copy To Appropriate District RECEIVE Take of New Mexico Office District 1 - (575) 393-6161 RECEIVE Take of New Mexico	Form C-103 Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240 MON' 1 0 20130	WELL API NO.
SILS First St. Arresia NM 88210 OIL CONSERVATION DIVISION	30-015-23 W3
District III - (505) 334-6178 1000 Rio Brizzos Rd., Aziec, NM 874 NMOSB ARTESSOUTH St. Francis Dr.	5. Indicate Type of Lease STATE FEE □
District IV – (505) 476-3460 Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No. E-7255
;SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	7. Lease Name or Unit Agreement Name WEST ARTESIA GRAYBURG UNIT
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Injection Well	8. Well Number 020
2. Name of Operator	9. OGRID Number
Alamo Permian Resources. LLC 3. Address of Operator	274841 10. Pool name or Wildcat
415 W. Wall Street, Suite 500, Midland, TX 79701	Artesia; Queen-Grayburg-San Andres
4. Well Location	
Unit Letter J: 1650 feet from the S line and 1980 feet from the E line	
	NMPM County EDDY
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
· · · · · · · · · · · · · · · · · · ·	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING	JOB
DOWNHOLE COMMINGLE	
OTHER: OTHER: RETURN	TO PRODUCTION
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
<u>10/29/13</u>	
MIRU. Unhang well. POOH w/rods & pump. Open casing & flow well into vac truck. Pump 80 bbls H2O dwn tbg. Well died	
(recovered approx 35 BO during killing operations). ND WH, NU BOP. POOH w/tbg. Fou Close BOP. Well venting to flowline overnight. SDFN.	nd hole in btm jt & 4 pitted jts to replace.
Note: RIH to 2551' (367' below btm perf). RIH w/9-5/8" csg scraper in the AM.	
10/30/13	
HSM w/crew re overhead loads & pressured lines.	
No shut-in well pressure. ND BOP. ND WH. PU 9-5/8" csg scraper. NU WH & BOP. R1H w/scraper to 2240'. POOH to csg scraper. ND BOP & WH. Finish POOH. R1H w/tbg to 5000 psi below slips (holding pressure for 10 seconds). Found 6 bad jts & replace 5 tbg	
collars. Tbg set @ 2242'; RD testers. ND BOP. NU WH. Set TAC w/10,000 lbs tension. Shut down due to wind. SDFN. Well venting	
to flow line tbg.	
10/31/13 RIH w/pump & rods. HWO. Pressure pump to 500 psi, ok. Clean location. RDMO.	
KITI Wiputiff & Tous. If wo, I ressure purify to 300 psi, ok. Clean location. KDIMO.	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
SIGNATURE TITLE Regulatory Affairs Coordinator DATE 11/1/2013	
Type or print name CARIESTOKER E-mail address: carie@stokeroilfield.com PHONE: 432.664.7659	
APPROVED BY: 18000 TITLE DIST PROPERTY DAT 11. 15 2013	
Conditions of Approval (if any):	