2 👻				OCD Artesia				
form 3160-5 August 2007)				ELLS		FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010 Lease Serial No. NMLC069705		
SUBMIT IN TRIPLICATE - Other instructions on reve				erse side.	7. If 8	 If Unit or CA/Agreement, Name and/or No. 891000326X 		
1. Type of Well	Gas Well Oth			8. Well Name and No. BIG EDDY UNIT 265H				
2. Name of Operat BOPCO LP		Contact: N E-Mail: wbmckee@	CKEE	9. API Well No. 30-015-41076-00-S1				
3a. Address				 Phone No. (include area code) h: 432-683-2277 		10. Field and Pool, or Exploratory HACKBERRY		
MIDLAND, TX 79702 4. Location of Well (Footage, Sec., T., R., M., or Survey Description						11. County or Parish, and State		
Sec 34 T19S R31E NENW 1120FNL 1980FWL					EDDY COUNTY, NM			
<u> </u>								
1:	2. CHECK APP	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF N	IOTICE, REPOR	T, OR OTHEI	R DATA	
TYPE OF S	UBMISSION	TYPE OF ACTION						
□ Notice of I	ntent	□ Acidize □ Alter Casing	Deepen Fracture Treat		 Production (Start/Resume) Reclamation Recomplete 		☐ Well Integrity ☑ Other	
🛛 Subsequen	t Report	rt 🗖 Casing Repair		v Construction				
Final Aban	ndonment Notice					rarily Abandon Drilling Operatio Disposal		
If the proposal Attach the Bon following comp testing has beer	is to deepen direction d under which the wo pletion of the involved	eration (clearly state all pertinen ally or recomplete horizontally, rk will be performed or provide l operations. If the operation res bandonment Notices shall be file inal inspection.)	give subsurface the Bond No. or sults in a multipl	locations and measure n file with BLM/BIA le completion or reco	red and true vertical (. Required subseque mpletion in a new in	depths of all pertin nt reports shall be terval, a Form 316	ent markers and zones. filed within 30 days 0-4 shall be filed once	
Drill 18-1/8" Class C, folk sks (95 bbls) 04/28/13 tes ? good test. 04/30/13 tes 05/01/13 Tes Drill 14-3/4" Lead 550 sk pits.	owed by Tail 250) cement to half p st choke, TIW, insi et annular to 250 p st casing to 1,500 hole to 2,650'. 05 (183 bbls) Class	26/13 ran 22 jts 16", 84#, sks Class C. Displace wit its. ide gray valve, IBOP and d psi low/1,000 psi high ? go psi ? good test. WOC 76 5/03/13 ran 63 jts of 13-3/8 s C, followed by Tail 300 s blind rams, both 5? pipe r	th 195.5 bbls diverter syste od test. hrs. 3", 68#, HCL- ks Class C.	of produced wat em to 250 psi low -80, UFJ, set at 2 Circ 90 sks cem	er. Circ 284 /1,000 psi high ,606'. ent to half PP stack and	NMO	PECEIVED DEC 04 2013 CD ARTESIA	
14. I hereby certif	fy that the foregoing is	Electronic Submission #2	227388 verifie	d by the BLM Wel	Information Syst	NMOC	D 12/4/13	
		For B nitted to AFMSS for process	SOPCO LP, se	nt to the Carlsba NY DICKERSON o	d on 11/25/2013 (14J			
Name (Printed/	(Typed) CHRIS G	IESE		Title DRILLIN	IG ENGINEER			
	•	Submission)		Date 11/20/2	013		,,,,,	
Signature	(Electronic S							
Signature	(Electronic S	THIS SPACE FC	R FEDERA	AL OR STATE				
Δ		THIS SPACE FC	DR FEDERA	JAMES A TitleSUPERVIS	AMOS		Date 11/26/201	
Approved By A Conditions of appro ertify that the appli which would entitle	val, if any, are attache icant holds legal or eq the applicant to condu	THIS SPACE FC ED ed. Approval of this notice does uitable title to those rights in the uct operations thereon. U.S.C. Section 1212, make it a	not warrant or subject lease	JAMES A A TitleSUPERVIS	AMOS SOR EPS		Date 11/26/201	

** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

•

4

Additional data for EC transaction #227388 that would not fit on the form

32. Additional remarks, continued

Swaco choke to 250 psi low/3,000 psi high. Test annular to 250 psi low/2,500 psi high ? all good tests. Test casing to 1,500 psi. WOC 36.5 hrs. Drill 12-1/4? hole to 4,191?. 05/10/13 ran 103 jts 9-5/8?, 40#, HCP-110 and LTC set at 4,190'.

Drill 12-1/4? hole to 4,191?. 05/10/13 ran 103 jts 9-5/8?, 40#, HCP-110 and LTC set at 4,190'. 1st Stage Lead 1,450 sks Class C. Displace with 310.8 bbls FW with 1,380 psi final circ pressure. Bump plug with 2,008 psi. Circulate 130 bbls of cement to surface, did not pump 2nd stage since circ on 1st stage. Continue to increase pressure to inflate ECP. Pressure began falling at 3,000 psi indicating ECP inflation. Pressure up to 3,000 psi and hold confirming ECP inflation ? floats holding. Drop DV cancelation bomb. Bump cancelation plug at 1,350 psi and pressure up to 2,750 psi.

05/11/13 test choke manifold, blind rams, both 5? pipe rams, 2? and 4? valves on BOP stack and Swaco choke to 250 psi low/3,000 psi high. Test annular to 250 psi low/2,500 psi high ? all good tests. Test casing to 1,500 psi. WOC 31.25 hrs.

05/16/13 open BOP and change out 4? pipe rams. Test choke manifold, blind rams, both 4? and 5? pipe rams, 2? and 4? valves on BOP stack and Swaco choke to 250 psi low/5,000 psi high. Test annular to 250 psi low/2,500 psi high ? all good tests. Drill 8-3/4? hole to a depth of 10,526?. 05/19/13 ran 236 jts 7? 26#, HPC-110 LTC. DV tool at

Drill 8-3/4? hole to a depth of 10,526?. 05/19/13 ran 236 jts 7? 26#, HPC-110 LTC. DV tool at 4,989?. Land casing mandrel in wellhead. Casing shoe at 10,492?. Cement 1st stage of 7" intermediate casing. Pump 100 bbls FW spacer to calibrate density. Lead 700 sks Tuned Light, followed by Tail 100 sks Versacem. Drop plug and displace cement, 30 bbls into displacement started getting red dye back then shortly after got cement back. Diverted flow into half frac. Displaced 185 bbls and slowed pump rate to 4 bbls/min to allow plug to pass thru DV tool. Continue displacing a total of 399 bbls ? plug did not bump. Pump an additional 1.4 bbls ? plug did not bump. Had full returns during cement job. Circulated all 358 bbls cement to surface followed by approx. 12 bbls FW. Possibility of a part in casing near the DV tool or DV tool failed to open. Run CBL, shows bonded casing from 5,660? to 7,200?. Run 40 arm caliper casing inspection log to check for casing integrity, casing looks intact.

approx. 12 bbls FW. Possibility of a part in casing near the DV tool or DV tool failed to open. Run CBL, shows bonded casing from 5,660? to 7,200?. Run 40 arm caliper casing inspection log to check for casing integrity, casing looks intact. 05/23/13 TIH with 4-1/4? inflatable packer, on tubing and 4? DP to test pressure integrity above and below DV tool. Packer leaking ? bad test. Drop DV tool opening bomb. Did not have to pressure up to break circ indicating DV tool already open. Cement 2nd stage Lead - 550 sks of Tuned Light. Displaced with 191 bbls FW and final circ pressure 835 psi. Bump plug and close DV tool with 2,410 psi - DV tool closed. Circulated 71 bbls of cement to surface.

BEU #265H Drilling Operations Sundry continued:

05/27/13 test casing to 2,325 psi prior to drilling out DV tool - good test. Drill out DV tool and float collar. Test casing to 2,325 psi and pressure dropped to 2,140 psi after 30 min. Run CBL from logger TD of 10,491' to surface. CBL shows cement from 5,032' to surface. Gap in cement from 5,032' to 5,680'. CBL shows cement from 5,680' to 8,868'. Gap in cement from 8,868' to 10,252' with cement from 10,252' to 10,491'. Decide to TIH, drill out float shoe, drill 10' of new formation and perform FIT test to 12 ppg MWE with 1,695 psi surface pressure and 8.9 ppg mud in hole - good FIT test. WOC 27.5 hrs.

Drill 6-1/8" hole to a depth of 14,813' (11,048' TVD). 06/07/13 ran 100 jts 4-1/2",11.6#, HCP-110 BTC and a total of (2) 4-1/2", 11.6 ppf, HCP-110, BTC marker jts, one set @ 12,635' in the middle of the lateral and other @ 10,518' at KOP. TIH with 4-1/2" liner on 29 jts of 4" XT-39 HWDP and 296 jts of 4" XT-39 DP. Liner set @ 14,810', top of liner @ 10,255'. Hang liner and confirm by slacking off 90K of 195K stinkg weight. Cement 4-1/2" liner as follows: Pump 35 bbl Tuned Spacer followed by - 270 sks of Solucem H. Bump plug with 3,875 psi - floats held. Slack off 50 Klbs to engage and set liner top packer. Circulate off top of liner with 300 bbls FW and circulated back 50 bbls of tuned spacer and cement to surface while displacing out of hole. NU "D" section tubing head: 7-1/16" 10M WP top flange x 11" 5M WP bottom flange, (2) 2" 10M valves with capping flanges. Test to 1,500 psi for 10 minutes, good test.

Rig released 06/09/2013.

• •