Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

cc 0.2 2013

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

No.

IEIVI	DEC OF 2010	5.	Lease Serial N
ON WELLS		A	NMNM905

SUNDRY Do not use th abandoned we	NOTICES AND REPO is form for proposals to II. Use form 31.60-3 (AP	RTS ON WEILLS drill or to re-enter ap D) for such proposition	D ARTE	NMNM90505 6. If Indian, Allottee of	or Tribe Name	b.		
SUBMIT IN TRIPLICATE - Other instructions on reverse side.			7. If Unit or CA/Agreement, Name and/or No. NMNM94495					
1. Type of Well				8. Well Name and No. ATOM ANT FEDE				
Oil Well Gas Well Oth		LALIDA MATTO			-NAL COM I			
Name of Operator YATES PETROLEUM CORPO	ORATION€-Mail: laura@yat	LAURA WATTS espetroleum.com		9. API Well No. 30-015-27721				
3a. Address 105 SOUTH FOURTH STREET ARTESIA, NM 88210		3b. Phone No. (include area code) Ph: 575-748-4272 Fx: 575-748-4585		10. Field and Pool, or Exploratory WILDOAT, BONE SPRING WC OLS 6-03 52224394				
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)		11. County or Parish,	and State	19112 =		
Sec 10 T22S R24E NWNW 9	90FNL 990FWL	•		EDDY COUNTY	(, NM	(175		
12. CHECK APPI	ROPRIATE BOX(ES) TO) INDICATE NATURE O	F NOTICE, F	REPORT, OR OTHE	R DATA			
TYPE OF SUBMISSION		ТҮРЕ	OF ACTION					
Notice of Intent	☐ Acidize	□ Deepen	☐ Produc	ction (Start/Resume)	■ Water Shu	t-Off		
	☐ Alter Casing	☐ Fracture Treat	Reclar	nation	■ Well Integ	rity		
☐ Subsequent Report	Casing Repair	■ New Construction	🛮 Recon	plete	Other			
☐ Final Abandonment Notice	□ Change Plans	Plug and Abandon	□ Tempo	orarily Abandon				
13. Describe Proposed or Completed Ope	Convert to Injection	☐ Plug Back	☐ Water	•				
If the proposal is to deepen directions Attach the Bond under which the wor following completion of the involved testing has been completed. Final Addermined that the site is ready for final that th	ck will be performed or provide to operations. If the operation rebandonment Notices shall be fil inal inspection.) plans to Plugback and Resequipment necessary. Notice of the provided that is a CIBP at 7,928 ft and spection open Canyon perforation 2500 psi. Perforate the left out evenly throughout the out evenly throughout the	the Bond No. on file with BLM/ sults in a multiple completion or ed only after all requirements, ince ecomplete this well as follow J 3K manual BOP. It a 25 sx class H cement of ions. Bone Spring: 7,132 ft to 7, Inic surfactant package and e acid. Flush to the bottom	BIA. Required s recompletion in a cluding reclamati ws: on plug on top 306 ft (97 friction reduce perforation.	of SEE ATTAC CONDITION er.	filed within 30 day 0-4 shall be filed to and the operator ha DIECTION NMOCD HED FOR	ecord 12/3/2 12/3/2 PROVA		
14. I hereby certify that the foregoing is	true and correct.	222723 verified by the BLM	Well Information	ın System				
	For YATES PETRO	DLEUM CORPORÁTION, ser processing by JOHNNY DIC	nt to the Carlsh	pad				
Name(Printed/Typed) LAURA W	,	~ 1	REPORTING	MICHIEL	<u>LU</u>			
Signature (Electronic S	Submission)	Date 10/1	1/2013	Anov 25	2013			
	THIS SPACE FO	R FEDERAL OR STAT	E OFFICE L	JSE / L. 1	11-911h	20		
Approved By		Title		BUPEAU OF LAND	OFFIC Date			
Conditions of approval, if any, are attached				1				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

which would entitle the applicant to conduct operations thereon.

Office

Additional data for EC transaction #222723 that would not fit on the form

32. Additional remarks, continued

Shut the well in for 8 hours to allow the gel to break and the resin to cure. TIH with tubing and seating nipple to circulate fill out of casing with 2 percent KCL water.
 POOH with frac string. RIH to wash sand down to PBTD. POOH.
 Swab the well until it cleans up then TIH with pumping equipment and turn the well over to the production department.


Treating Schedule attached Schematics attached


Treating Schedule

1bs Proppant

Stage	gal	Prop Conc			•		
Number	_	lb/gal	Stage	Cumulati	ve Pi	coppant	Type
1	34000.	0.00	0.	0.			
2	8000.	1.00	8000.	8000.	20/40	Ottawa	Sand
3	12000.	2.00	24000.	32000.	20/40	Ottawa	Sand
4	15000.	3.00	45000.	77000.	20/40	Ottawa	Sand
5	12000.	4.00	48000.	125000.	20/40	Ottawa	Sand
6	8000.	5.00	40000.	165000.	20/40	Super	LC RCS
7	7500.	6.00	45000.	210000.	20/40	Super	LC RCS
8	+/-3000.	0.00	0.	0.		~~~~	

Estimated Surface Treating Pressure @ 40 BPM = 7,157 psig. Maximum Surface Treating Pressure = 10,000 psig.





Atom Ant Federal Com 1 30-015-27721 Yates Petroleum Corporation November 26, 2013 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by February 26, 2014.

- 1. Operator to set CIBP at 7,928' and place 25 sx Class H Cement on top. Tag required.
- 2. Operator to set a balanced Class C Cement plug from 7,500'-7,326' to seal the top of the Wolfcamp formation.
- 3. Must conduct a casing integrity test before perforating and fracturing. Submit results to BLM. The CIT is to be performed on the production casing to max treating pressure. Notify BLM if test fails.
- 4. If CIT passes, operator is approved to recomplete to the Bone Spring as written.
- 5. Before casing or a liner is added or replaced, prior BLM approval of the design is required. Use notice of intent Form 3160-5.
- 6. Surface disturbance beyond the originally approved pad must have prior approval.
- 7. Closed loop system required.
- 8. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 9. Operator to have H2S monitoring equipment on location.

- 10. A minimum of a 2000 (2M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (2M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above pre-charge. The pre-charge test shall follow requirements in Onshore Order #2.
- 11. Subsequent sundry required detailing work done, a C-102 form, and completion report for the new formations. Operator to include well bore schematic of current well condition when work is complete.
- 12. Submit sundry to remove "COM" from the name.
- 13. See attached for general requirements.

JAM 112613

BUREAU OF LAND MANAGEMENT Carlsbad Field Office

620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

General Requirements for Plug Backs

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the 90th day provide this office, prior to the 90th day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat** Class "C", for up to 7,500 feet of depth or **Neat** Class "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.