Form 2160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

	Expires, July
Lease Seri	al No.
DIMARIMO	107607


SUBMIT IN TRIPLICATE - Other instructions on reverse side.	7 ISII-in - CA/A NO. N. N. N. N.		
	7. If Unit or CA/Agreement, Name and/or No.		
1. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Other	8. Well Name and No. RADAR 24 FEDERAL 1		
2. Name of Operator Contact: JUDITH A. BARNETT DEVON ENERGY PRODUCTION CO.EMail: Judith.Barnett@dvn.com	9. API Well No. 30-015-31357		
3a. Address 333 W. SHERIDAN OKLAHOMA CITY, OK 73102  3b. Phone No. (include area con Ph: 405-228-8699)	de) 10. Field and Pool, or Exploratory LUSK;BONE SPRING		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	11. County or Parish, and State		
Sec 24 T19S R31E 660FNL 1980FWL	EDDY COUNTY, NM		
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF	FNOTICE, REPORT, OR OTHER DATA		
TYPE OF SUBMISSION TYPE	TYPE OF ACTION		
Notice of Intent	☐ Production (Start/Resume) ☐ Water Shut-Off		
☐ Alter Casing ☐ Fracture Treat	☐ Reclamation ☐ Well Integrity		
☐ Subsequent Report ☐ Casing Repair ☐ New Construction	Recomplete		
☐ Final Abandonment Notice ☐ Change Plans ☐ Plug and Abandon	□ Temporarily Abandon		
☐ Convert to Injection ☐ Plug Back	■ Water Disposal		
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/E following completion of the involved operations. If the operation results in a multiple completion or retesting has been completed. Final Abandonment Notices shall be filed only after all requirements, includetermined that the site is ready for final inspection.)  Devon Energy Production Company L. P. respectfully requests to abandon existing Delaware perfs. Recomplete to Cherry Canyon as follows:  1. MIRU PU. POOH w/pump & rods. 2. ND WH. NU BOP & test. Rise pkr. POOH w/BHA. 3. RIH w/ CIBP on tbg. Set CIBP @ ~9600'. PUH & spot 300'(35sx CI H) cmt plu above DV Tool). 4. PUH & reverse circ tbg clean. RIH. Tag TOC. 5. RIH w/ CIBP on tbg & set @ ~7230'. PUH & spot 50'(~6sx CI C) on CIBP. 6. PUH & reverse circ tbg clean. RIH tag TOC. 7. RIH w/ CIBP on tbg & set CIBP 5250'. PUH & spot 50'(~6sx CI C) on CIBP. 8. PUH & reverse circ tbg clean. RIH. Tag TOC. PT to 1000psi.	Bone Spring &    FECEIVED		
14. I hereby certify that the foregoing is true and correct.	Accepted for record		
Electronic Submission #228487 verified by the BLM W For DEVON ENERGY PRODUCTION CO.LP, ser Committed to AFMSS for processing by KURT SIMM	nt to the Carlsbad		
Name(Printed/Typed) JUDITH A. BARNETT Title SR. F	EGULATORY SPECIALIST		
Signature (Electronic Submission) Date 12/03	/2013		
THIS SPACE FOR FEDERAL OR STATI	OFFICE USE APPRUVEU		
Approved By  Conditions of approval, if any, are attached. Approval of this notice does not warrant or	DEC 1 1 2013 <sup>16</sup>		
certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.  Office  Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly a States any false, figuitings or fraudulent statements or representations as to any matter within its invisibility.	Is/ Chris Walls		

#### Additional data for EC transaction #228487 that would not fit on the form

#### 32. Additional remarks, continued

9. RU WL. Pèrf Cherry Canyon 4910-20' @ 2 spf: Total 20 holes. 
RD WL. RIH w/ pkr & test tbg to 8400psi.
10. RU & acidize. Set pkr @ 4700' & test. Unset pkr & spot 100g acid across perfs. Set pkr & test to 500psi.
11. Hold 500psi on backside. Spearhead w/6K g, 15% HCL.
12. RU & RIH w/ swab & swab. RU frac crew & frac w/70K#'s 20/40. FWB. RIH w/ rods & pump. LT pump. RDMO PU. TOP.


Attachment



DEVON, ENERGY PRODUCTION COMPANY LP		
Well Name: RADAR 24 FEDERAL 1	Field: LUSK WEST	
Location: 660' FNL & 1980' FWL; SEC 24-T195-R31E	County: EDDY State: NM	
Elevation: 3558' KB; 3540' GL; 18' KB to GL	Spud Date: 10/4/00   Compl Date: 1/25/01	
AP#: 30-015-31357   Prepared by: Ronnie Slack	Date: 10/22/13 Rev:	
CURRENT SCHEMAT  17-1/2" hole 13-3/8", 48#, H40, STC, @ 832' Cmt'd w/778 sx, cmt to surface		
12-1/4" hole  8-5/8, 24#, K55, STC, 0 - 2,200'  8-5/8, 32#, K55, STC, 2,200 - 4,505' (csg pkr @ 2,584, DV @ 2,533) Cmt'd w/1925 sx, cmt to surf	Trendent	
Delaware & Bone Spring Commingled 2/18/05  DELAWARE  5,300' - 5,304' (8/15/04)  5,311' - 5,316' (8/15/04)		
By 110 Spring BONE SPRING 7,288'-7,272' (2/3/03) 7,280'-7,283' (2/3/03)		
BONE SPRING 8,535' - 8,545' (2/3/03)	2-7/8", 6.5#, L80, production tubing	
BONE SPRING 8,801' - 8,814' (4/16/04)	1-1/4", rod pump @ 9,487'	
	[ ]	
DV @ 9,504'	On/Off Tool	
BONE SPRING 9,657' - 9,670' (12/01-sundry date) 9,682' - 9,696' (12/01-sundry date)	Arrowset Packer @ 9,530 <sup></sup> (8/17/13)	
BONE SPRING 9,874' - 9,880' (7/30/01)	9,815' PBD CIBP @ 9,850', w/35' cmt (12/01-sundry date)	
1	11,340 PBD CIBP @ 11,375', w/35' cmt (7/30/01)	
MORIOW 11, 957  MORROW 12,440'-12,454' (1/25/01)	12,365' PBD CIBP @ 12,400', w/35' cmt (5/1/01)	
	(2) (2) (2) (MD	




The Radar 24 Fed 1 prospective Cherry Canyon pay section looks like this (note the caliper and resistivity profile, both indicative of perm):



The existing Cherry Canyon producing zone look like this:



RADAR 24 FEDERAL t 30915313570000 TD 12750 074 C NE NW 02-12-2001 3540 CR



# Radar 24 Fed 1 30-015-31357 Devon Energy Production Co. December 11, 2013 Conditions of Approval

- 1. Drill out CIBP at 9850' and spot a 205' plug must be set across the top of the Wolfcamp from 10,530'-10,325'.
- 2. Set CIBP at 9600' and pump 35 sx of class H cement as proposed. Tag at 9400' or higher.
- 3. Set CIBP at 7215' and spot 225' of class C cement to 6990'. (Bone Spring Top 7040').
- 4. Set CIBP at 5250' and pump a minimum of 25 sx or bail 35' class C cement on top.
- 5. Surface disturbance beyond the originally approved pad must have prior approval.
- 6. Closed loop system required.
- 7. Operator to have H2S monitoring equipment on location as H2S has been reported from wells in the area.
- 8. Subsequent sundry, completion report and wellbore schematic required.
- 9. See attached general plugback requirements.

CRW 121113

### BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Production Zone Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from this approval.

If you are unable to plug back the well by the  $90^{th}$  day provide this office, prior to the  $90^{th}$  day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged back. Failure to do so will result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plug back operations. For wells in Eddy County, call 575-361-2822.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. Before pumping cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either **Neat Class** "C", for up to 7,500 feet of depth or **Neat Class** "H", for deeper than 7,500 feet plugs.

- 6. <u>Subsequent Plug back Reporting:</u> Within 30 days after plug back work is completed, file one original and three copies of the Subsequent Report, Form 3160-5 to BLM. The report should give in detail the manner in which the plug back work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. <u>Show date work was completed.</u>
- 7. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.