

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

RJM 1335338341 OPERATOR Initial Report Final Report

Name of Company Judah Oil / <i>Greenimo SWD LLC</i>	Contact James Campanella
Address P.O. Box 568 611 W Mahone, Ste. D Artesia, NM	Telephone No. 575-746-1280
Facility Name Green "A" Federal #10 SWD <i>(263684)</i>	Facility Type SWD

Surface Owner BLM	Mineral Owner Federal	API No. 30-015-21748
-------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter K	Section 29	Township 17S	Range 29E	Feet from the 1980	North/South Line	Feet from the 1980	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	------------------	-----------------------	----------------	----------------

Latitude 32.803694974 Longitude -104.099097557

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 150bbbls	Volume Recovered 100
Source of Release Well Head	Date and Hour of Occurrence 12/12/13	Date and Hour of Discovery 12/12/13
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher of NMOCD	
By Whom? James B. Campanella	Date and Hour 12/12/13	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

RECEIVED
DEC 17 2013
NMOCD ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The release stemmed from a failure of components on the well head. The faulty components were replaced and the well was put back into service. Talon/LPE mobilized personnel to conduct an initial site assessment and soil sampling on the location.

Describe Area Affected and Cleanup Action Taken.*
The release originated at the well head and flowed southeast across the location. All of the fluid was contained to the location. Initial spill response activities included utilizing a vacuum truck to recover as much standing fluid as possible and scraping the surface of the impacted area to prevent any further expanse of fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: James B. Campanella	Approved by Environmental Specialist: Signed By <i>[Signature]</i>	
Title: Manager	Approval Date: <u>DEC 19 2013</u>	Expiration Date:
E-mail Address: jbc@judahoil.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date:	Phone: 575-746-1280	

PROPOSAL NO LATER THAN:
January 19, 2013 ZRP-2121

* Attach Additional Sheets If Necessary