
Submit 1 Copy To Appropriate District	State of New Me	xico	Form C-103
Office District I – (575) 393-6161	Energy, Minerals and Rad	The sources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240		AN 1 6 2014	WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION	DIVISION	30-015-00290
District III - (505) 334-6178	1220 South St. Erar		5. Indicate Type of Lease STATE STATE SEE
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, Martin	7505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			
87505 SUNDRY NC	TICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		ATOKA SAN ANDRES UNIT	
DIFFERENT RESERVOIR. USE "APP PROPOSALS.)	LICATION FOR PERMIT" (FORM C-101) FO	DR SUCH	8. Well Number #151
1. Type of Well: Oil Well	Gas Well 🗌 Other Injection		
2. Name of Operator	· · · · · · · · · · · · · · · · · · ·		9. OGRID Number 277558
LIME ROCK RESOURCES I	1-A, L.P.	· · · · · · · · · · · · · · · · · · ·	
3. Address of Operator c/o Mike Pippin LLC, 3104 N. S	ullivan Farmington NM 97401		10. Pool name or Wildcat Atoka San Andres (3610)
Co Mike Fippin LLC, 5104 N. S	univan, Faimington, NW 87401		Atoka Sali Alidies (5010)
4. Well Location			· · · · · · · · · · · · · · · · · · ·
Únit Letter <u>M</u>	: <u>990</u> feet from the <u>South</u>	line and <u>33</u>	0 feet from the <u>West</u> line
Section 13		Range 26-E	NMPM Eddy County
	11. Elevation (Show whether DR,	, RKB, RT, GR, etc.)	
	3314' GL	· · · · · · · · · · · · · · · · · · ·	
10 01 1			
12. Check	Appropriate Box to Indicate N	ature of Notice, I	Report or Other Data
NOTICE OF	INTENTION TO:	SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK [REMEDIAL WORK	
TEMPORARILY ABANDON [CHANGE PLANS	COMMENCE DRIL	LING OPNS. D PAND A
-	MULTIPLE COMPL	CASING/CEMENT	JOB 🗌
_			
-		OTHER:	
OTHER: P&A			give pertinent dates, including estimated date
	work). SEE RULE 19.15.7.14 NMAC		
proposed completion or a		r	······
	this well as follows: MIDLICLL If.	TOUL	
			all production equipment. TIH w/tbg &
			(1244'-1144'), 8-5/8" csg shoe @
1194'. Place a balanced 25 sx	plug (~215') @ 1244'. WOC. Tag	g cmt. Plug #3 (60	'-Surface). W/tbg @ 60', circ cmt down
tbg & up 5-1/2" csg to surface.	(~7 sx). Cut off csg below surface	csg flange. Install	P&A marker with cmt to comply with
government specs. RD move	off location, cut off anchors and res	store location. See	attached wellbore diagrams.
• • • • • • • • • • • •			
Spud Date: 1/16/57	Drilling Rig	Release Date:	2/4/57
I hereby certify that the information	on above is true and complete to the be	est of my knowledge	and belief.
SIGNATURE Mile		In the state of the second second	
SIGNATURE	IIILE Petro	leum Engineer - Age	entDATE1/15/14
Type or print name Mike Pi	ppin E-mail address	: mike@pippin	llc.com PHONE: 505-327-4573
For State Use Only			
)ad $($	-PICT H	nust built sou
APPROVED BY	TITLE Urst	All aller	<u> 1010/01 DATE 000 16,0019</u>
Conditions of Approval (if any):	-	/	Nr Allachad
CONDITIONS OF APPROVAL ATTAC	Libbert an Ise 1983	ging of well bore only.	- * See Attached
	of C 103 (Subsam	nd is retained pending rec tent Report of Well Pluggi	
Approval Granted providing wor		nd at OCD Web Page und	
Completed by	E		
	rorais, www.cmnrs	d.state.nm.us/ocd.	·
gun 10,00	115	d.state.nm.us/ocd.	<u></u>

ATOKA SAN ANDRES UNIT #151

Proposed P&A -1/15/14 - Mike Pippin

Atoka San Andres (3610)

(M) Section 13, T-18-S, R-26-E, Eddy County, NM




ATOKA SAN ANDRES UNIT #151

Current -1/15/14 - Mike Pippin

Atoka San Andres (3610)

(M) Section 13, T-18-S, R-26-E, Eddy County, NM



NEW MEXICO OIL CONSERVATION DIVISION DISTRICT 2 OFFICE 811 S. FIRST STREET ARTESIA, NM 88210 (575)748-1283

CONDITIONS OF APPROVAL FOR PLUGGING & ABANDONMENT

Operato	pr: Lime Rock Resources II, A. L.P	
Well Na	me & Number: Atoka San Andres Unit #151	
A DI #.	30-015-00290	

- 1. Produced water <u>will not</u> be used during any part of the plugging & abandonment operation.
- 2. Notify NMOCD Dist. 2 office at least 24 hrs before beginning work.
- 3. Closed Loop System is to be used for entire plugging operation. Upon completion, contents of steel pit are to be hauled to a permitted disposal location.
- 4. Trucking companies being used to haul oilfield waste fluids to a disposal commercial or private shall have an approved NMOCD C-133 permit. A copy of this permit shall be available in each truck used to haul waste products. It is the responsibility of the operator, as well as the contractor, to verify that this permit is place prior to performing work. Drivers shall produce a copy upon request of NMOCD Field Inspectors.
- 5. A subsequent C-103 will serve as notification that the well bore has been plugged ONLY. A C-103 FINAL shall be filed before any bonding can be released on the well. Upon receipt of the Final, an inspection will be performed to verify that the location has been satisfactorily cleaned to NMOCD standards.
- 6. If work has not begun within 90 days of the approval of this procedure, an extension request must be filed, stating reason that well has not been plugged.
- 7. Every attempt must be made to clean the well bore out to below the perfs, before any plugs can be set, by whatever means possible.
- 8. Cement Retainers may not be used.

9. Squeeze pressures are not to exceed 500 PSI, unless approval is given by NMOCD.
10. Plugs may be combined after consulting with and getting approval from NMOCD.
11. Minimum WOC time for tag plugs will be 4 Hrs.

DATE: Jan 16, 2014

APPROVED BY:

GUIDELINES FOR PLUGGING AND ABANDONMENT

DISTRICT II / ARTESIA

- All cement plugs will be a minimum of 100' in length or a minimum of 25 sacks of cement, whichever is greater.
- Mud laden fluids must be placed between all cement plugs.
- Mud laden fluids must be mixed at 25 sacks of gel per 100 bbls of water.
- A cement plug is required to be set 50' below and 50' above all casing shoes and casing stub plugs. These plugs must be tagged.
- A CIBP with 35' of cement on top may be set in lieu of 100' cement plug.
- A plug as indicated above must be placed within 100' of top perforation. This plug must be tagged.
- Plugs set below and above salt zones must be tagged.
- No more than 2000' is to be allowed between cement plugs in open hole and no more than 3000' in cased hole.
- DV tools are required to have a 100' cement plug set 50' above and below the tool and must be tagged.
- Formations to be isolated with plugs placed at the top of each formation are:
 - o Fusselman
 - o Devonian
 - o Morrow
 - o Wolfcamp
 - o Bone Spring
 - o Delaware
 - Any Salt Section (Plug at top and bottom)
 - o Abo
 - o Glorieta
 - Yates (this plus is usually at base of salt section)
- If cement does not exist behind casing strings at recommended formation depths, the casing must be cut and pulled with plugs set at these depths or casing must be perforated and cement squeezed behind casing at the formation depths.
- In the R-111-P area (Potash Mine area) a solid cement plug must be set across the salt section.
 Fluid used to mix the cement shall be saturated with the salts common to the section penetrated and in suitable proportions, but not more than a 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible (50' below and 50' above).